



DV55NAO

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT CONNECT T200 L SWB P/V
Colour	White
Year of manufacture	2005
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-17
Pictures	15
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-04-14
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	88
Total items failed	8

MOT #22 2024-04-15 13:53

MOT test number 941743478250

Result ✓ Passed

Next expiry date 2025-04-14

**Advice** Nearside Front Inner Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21 2023-04-14 18:00

MOT test number 400878678626

Result ✓ Passed

**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** General corrosion to underside of vehicle

MOT #20 2022-04-13 07:04

MOT test number 199063602727

Result ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2022-04-12 08:14

**MOT test number**

483902053251

**Result****✗ Failed****DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))**MAJOR** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Offside Front Drag link end ball joint has excessive play (2.1.3 (b) (i))**MAJOR** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))**MAJOR** Nearside Front Drag link end ball joint has excessive play (2.1.3 (b) (i))**MAJOR** Nearside Front Brake pipe excessively corroded (1.1.11 (c))**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



MOT #18

2021-10-13 10:31

MOT test number

858164691963

Result

✖ Failed

- MAJOR

Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Minor

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Nearside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
- Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Offside Drag link end ball joint has slight play (2.1.3 (b) (i))
- MAJOR

Offside Rear Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))
- Advice

Tyre worn close to legal limit/worn on edge all (5.2.3 (e))
- MAJOR

Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
- Advice

Nearside Drag link end ball joint has slight play (2.1.3 (b) (i))



MOT #17	2021-09-03 09:28
MOT test number	740505792333
Result	✗ Failed

**MAJOR** Offside Rear Seat belt not functioning as intended (7.1.2 (c))

**MAJOR** Nearside Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))

**MAJOR** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

**MAJOR** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MAJOR** Nearside Front Brake pipe excessively corroded to rear (1.1.11 (c))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Offside Rear Bumper damaged and likely to cause injury when grazed or contacted end cap (6.1.4 (a) (i))

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MAJOR** All direction indicators incorrect colour (4.4.3 (a))

**MAJOR** Nearside Drag link end ball joint has excessive play (2.1.3 (b) (i))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MAJOR** Nearside Rear Seat belt not functioning as intended (7.1.2 (c))

**MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MAJOR** Rear Seat belt buckle missing (7.1.2 (d))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Offside Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))

**MAJOR** Offside Front Brake pipe excessively corroded to rear (1.1.11 (c))

**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MAJOR** Rear Other passenger door does not latch securely closed (6.2.3 (a))

**Minor** Offside Rear Other passenger door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))

**MAJOR** Offside Drag link end ball joint has excessive play (2.1.3 (b) (i))

**Advice** Rear seat insecure

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #16**

2020-12-15 13:24

**MOT test number**

356493432197

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive spring mount (5.3.6 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))



**MOT #15**

2020-12-14 10:01

**MOT test number**

805055043013

**Result****✗ Failed****MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive spring mount (5.3.6 (a) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))**MAJOR** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Front Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))**MAJOR** Nearside Rear Inner Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))**MOT #14**

2019-06-12 08:08

**MOT test number**

120870261706

**Result****✓ Passed****Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2019-06-07 08:00

**MOT test number**

398986413434

**Result**

✗ Failed

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MAJOR** Nearside Front Steering rack insecure (2.1.3 (a) (i))

**Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))

**MAJOR** Front Brakes imbalanced across an axle 37% (1.2.1 (b) (i))

**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MAJOR** Nearside Rear Suspension spring mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

**MAJOR** Steering rack modification unsafe not centralising/stiff (2.1.3 (f) (i))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MAJOR** Rear Brakes imbalanced across an axle 38% (1.2.1 (b) (i))

**MOT #12**

2018-06-13 08:25

**MOT test number**

190058441617

**Result**

✓ Passed

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2017-06-19 15:55

**MOT test number**

311791341958

**Result**

✓ Passed

**MOT #10**

2016-03-22 14:23

**MOT test number**

717906665492

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2016-03-21 14:14**MOT test number** 643962649353**Result** ✗ Failed

- Fail** Centre Stop lamp not working (1.2.1b)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Front registration plate character(s) likely to be misread (6.3.4b)
- Fail** Registration plate lamp not working (1.1.C.1d)
- Fail** Exhaust system not adequately supported (7.1.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #8** 2014-11-03 10:01**MOT test number** 177407804314**Result** ✓ Passed**MOT #7** 2013-10-04 09:47**MOT test number** 489607373254**Result** ✓ Passed**MOT #6** 2012-10-08 14:45**MOT test number** 117932282205**Result** ✓ Passed**MOT #5** 2011-08-17 14:42**MOT test number** 925919021271**Result** ✓ Passed



MOT #4	2010-11-30 10:47
MOT test number	923304430305
Result	✓ Passed
MOT #3	2009-11-03 15:00
MOT test number	391327909319
Result	✓ Passed
MOT #2	2008-11-05 14:45
MOT test number	873380418347
Result	✓ Passed
MOT #1	2008-11-05 14:45
MOT test number	572560518353
Result	✗ Failed
<div>Pass with rectification</div> Centre Stop lamp not working (1.2.1b)	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
14 April 2025

<b>Tax status</b>	Valid until 1 August
-------------------	----------------------

<b>Days left</b>	93
------------------	----

<b>MOT expiry date</b>	14 April 2025
------------------------	---------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-11-29
Last registration	2024-04-15
Complete history	<a href="#">See info</a>



Registration #1	2005-11-29	11 mi
Registration #2	2008-11-05	43.884 mi
Registration #3	2009-11-03	57.211 mi
Registration #4	2010-11-30	71.037 mi
Registration #5	2011-08-17	77.416 mi
Registration #6	2012-10-08	85.799 mi
Registration #7	2013-10-04	90.578 mi
Registration #8	2014-11-03	96.497 mi
Registration #9	2016-03-21	112.769 mi
Registration #10	2016-03-22	112.773 mi
Registration #11	2017-06-19	124.087 mi
Registration #12	2018-06-13	135.968 mi
Registration #13	2019-06-13	147.849 mi
Registration #14	2020-06-13	159.730 mi
Registration #15	2021-06-13	171.611 mi
Registration #16	2022-06-13	183.492 mi
Registration #17	2023-06-13	195.373 mi
Registration #18	2024-06-13	207.254 mi
Registration #19	2025-06-13	219.135 mi
Registration #20	2026-06-13	231.016 mi
Registration #21	2027-06-13	242.897 mi
Registration #22	2028-06-13	254.778 mi
Registration #23	2029-06-13	266.659 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	598 mm
Length	4278 mm
Kerb weight	1410 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	5M64902