





report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA VVTI
Colour	Blue
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	170 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg



CarCheck.co.uk page 1/19



Internet history

Entry 1

Date	2021-12-12	
Pictures	1	
Listing price	View report	



source: autotrader.co.uk

CarCheck.co.uk page 2/19



MOT history

CarCheck.co.uk page 3/19



MOT #27 2021-12-11 11:41

MOT test number 758752979225

Result X Failed

CarCheck.co.uk page 4/19

Fail Brake fluid contaminated (1.8 (a)) Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) Nearside Front Brake pad(s) wearing thin 2mm (1.1.13 (a) (ii)) **Advice** Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii)) Advice Exhaust mounting defective Center box (6.1.2 (a)) Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Offside Front Vehicle structure is fractured but structural rigidity is not significantly reduced inside Advice door (6.1.1 (a) (i)) Minor Offside Front Headlamp lens slightly defective (4.1.1 (b) (i)) Fail Front Brakes imbalanced across an axle (1.2.1 (b) (i)) Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice **Advice** Boot lid component damaged but not likely to cause injury Struts (6.2.1 (a) (i)) Offside Parking brake inoperative on one side (1.4.1 (a)) Fail Advice Offside Front Coil spring corroded (5.3.1 (b) (i)) Advice Offside Front Brake pad(s) wearing thin 2.5mm (1.1.13 (a) (ii)) Advice Brake fluid close to minimum mark (1.1.10 (d) (ii)) Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b)) Fail Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a)) Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i)) **Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Minor Battery insecure but not likely to fall from carrier Positive terminal loose (4.13 (a) (i)) Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

Advice

Nearside Front Coil spring corroded (5.3.1 (b) (i))



MOT test number

Result

Advice Nearside front tyre cracking

Advice Front and rear suspension

Advice Underbody corrosion floor and general

Advice Offside front tyre cracking

MOT #25 2020-11-26 09:32 **MOT** test number 552148741416 × Failed Result **Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i)) Advice Nearside front tyre cracking Advice Front and rear suspension Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) **Advice** Underbody corrosion floor and general **Advice** Offside front tyre cracking Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))

MOT #24	2019-11-06 08:05
MOT test number	753048256077
Result	✓ Passed
Advice All under body has corrosion	

CarCheck.co.uk page 5/19



MOT #23 2019-10-31 08:30 **MOT** test number 322580359560 Result × Failed Fail Offside Front Brake pipe excessively corroded (1.1.11 (c)) Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c)) Fail **Advice** All under body has corrosion Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a)) Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT test number

452879272866

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge On legal limit (5.2.3 (e))

Advice Unable to fully inspect underside of vehicle due to coating applied

CarCheck.co.uk page 6/19



MOT #21 2018-11-07 11:38

MOT test number 176320041752

Result X Failed

Fail Offside Front Headlamp aim projected beam image is obviously incorrect Misting over (4.1.2 (c))

Fail Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Unable to fully inspect underside of vehicle due to coating applied

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect Misting over (4.1.2 (c))

Fail Exhaust has a major leak of exhaust gases (6.1.2 (a))

Fail Front Brakes imbalanced across an axle (1.2.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge On legal limit (5.2.3 (e))

Fail Driver's view of the road through the swept area of the windscreen materially affected by an obstruction Phone mount (3.1 (a) (ii))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail Offside Front Position lamp not working (4.2.1 (a))

MOT #20 2017-09-25 10:35

MOT test number 593124123853

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Underside of vehicle corroded

Advice Both front head lights misted over

CarCheck.co.uk page 7/19



MOT #19 2017-09-25 10:35

MOT test number 966364661937

Result X Failed

Pass with rectification Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Underside of vehicle corroded

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Both front head lights misted over

MOT #18 2016-11-04 12:52

MOT test number 226592188825

Result \(\sqrt{Passed} \)

Advice Exhaust system corroded

Advice Nearside Front Headlight starting to discolour

Advice Slight play in inner steering rack joint

Advice Offside Front Headlight starting to discolour

MOT #17 2015-09-30 14:00

MOT test number 169178368496

Result ✓ Passed

Advice Corrosion & surface rust on underbody of vehicle

Advice Undertrays & covers fittedunable to examine some testable components .

Advice Both front shock absorber seals split

CarCheck.co.uk page 8/19



MOT #16 2015-09-30 11:15

MOT test number 349362037582

Result X Failed

Advice Undertrays & covers fittedunable to examine some testable components .

Advice Both front shock absorber seals split

Fail Offside Front Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)

Fail Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Corrosion & surface rust on underbody of vehicle

Fail Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)

Fail Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #15 2014-09-25 10:23

MOT test number 225188764209

Result \(\sqrt{Passed} \)

Notice Slight fluctuation on rear brakes

Notice Both front shocker seals split

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 9/19



MOT #14 2014-09-24 16:37 **MOT** test number 179627464280 Result × Failed **Notice** Slight fluctuation on rear brakes Notice Both front shocker seals split Fail Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b) Notice Under-trays fitted obscuring some underside components Fail Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b) Front registration plate faded (6.3.1d) Fail

MOT test number
946425873220

Result
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Notice Both front to rear brake pipes corroded at rear next to flexy

Advice Nearside Rear rear parking (secondary) brake grabbing slightly (3.7.B.6b)

MOT test number

Result

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Pass with rectification Offside Front Side repeater not working (1.4.A.2c)

Advice Nearside Rear rear parking (secondary) brake grabbing slightly (3.7.B.6b)

Notice Both front to rear brake pipes corroded at rear next to flexy

CarCheck.co.uk page 10/19



MOT test number

Result

Notice Plastic skirts fittedunable to examine outer sills ?

Notice Both front shocker seals split .

Notice Under-trays fitted obscuring some underside components

Notice Surface rust on underbody??

MOT #10

MOT test number

Result

Notice All alloy wheels deteriorating

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #9		2010-12-06 12:37
MOT test	number	770790640369
Result		✓ Passed
Advice	Offside Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Brake pipe slightly corroded (3.6.B.2c)	
Notice	All four alloy wheels deteriorating	

CarCheck.co.uk page 11/19



MOT test number

Result

Notice Rear wiper split

Notice Plastic skirts fitted unable to examine outer sills

Notice Alloy wheels deterioated

MOT #7 2009-12-30 16:18 **MOT** test number 280374769330 Result × Failed **Notice** Plastic skirts fitted unable to examine outer sills Fail Offside Front brake disc excessively scored (3.5.1h) Fail Brakes imbalanced across an axle (3.7.B.5b) Notice Alloy wheels deterioated Fail Nearside Front brake disc excessively scored (3.5.1h) Fail Offside front brake recording little or no effort (3.7.B.5a) **Notice** Rear wiper split

MOT #6

MOT test number

232866468313

Result

Notice Offside rear brake bindind slightly

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #5
 2008-01-03 14:53

 MOT test number
 724863908065

 Result
 ✓ Passed

CarCheck.co.uk page 12/19



MOT #4 2007-01-05 14:55

MOT test number 852065107071

Result ✓ Passed

MOT #3 2007-01-02 11:22

MOT test number 263982607074

Result X Failed

Fail Parking brake lever ratchet mechanism is excessively worn (3.1.5)

MOT #2 2005-12-06 11:39

MOT test number 171020545395

Result ✓ Passed

MOT #1 2005-12-05 15:38

MOT test number 524629535357

Result X Failed

Advice Nearside Front brake disc slightly pitted (3.5.1h)

Advice Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Fail Offside Rear brake disc excessively pitted (3.5.1h)

Advice Offside Front brake disc slightly pitted (3.5.1h)

Fail Nearside Rear brake disc excessively pitted (3.5.1h)


CarCheck.co.uk page 13/19



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 14/19



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 15/19



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
manus .	

manus .	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NK
Fiate since	m.n.n
	More info >

CarCheck.co.uk page 16/19



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 17/19



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2001-09-14
Last registration	2021-12-11
Complete history	See info



Registration #1	2001-09-14	29 mi
Registration #2	2005-12-05	42.607 mi
Registration #3	2005-12-06	42.607 mi
Registration #4	2007-01-02	49.730 mi
Registration #5	2007-01-05	49.792 mi
Registration #6	2008-01-03	54.900 mi
Registration #7	2008-12-31	59.050 mi
Registration #8	2009-12-30	63.357 mi
Registration #9	2009-12-31	63.357 mi
Registration #10	2010-12-06	67.518 mi
Registration #11	2011-12-05	71.373 mi
Registration #12	2012-12-05	75.191 mi
Registration #13	2013-10-02	78.306 mi
Registration #14	2014-09-24	82.872 mi
Registration #15		11.177 mi
Registration #16		11.117 es
Registration #17		11.177 mi
Registration #18		11.177 es
Registration #19		11.777 mi
Registration #20		11.777 es
Registration #21		11.777 66
Registration #22		11.117 es
Registration #23		11.777 es
Registration #24		11.117 es
Registration #25		11.777 es
Registration #26		0.00 44
CarCheck.co.uk		page 18/19

Registration #27

Registration #28

More info >

mn.n.n



Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	1ZZ0771609

CarCheck.co.uk page 19/19