





report date: 2024-03-28

General information

Make	TOYOTA
Model	PREVIA D-4D T SPIRIT 7STR
Colour	Silver
Year of manufacture	2005
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 1.800 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.2 mpg
CO2 emission	191 g/km
CO2 label	J



CarCheck.co.uk page 1/18



Internet history

Entry 1

Date 2022-05-22

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/18



	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2025-04-10
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	94
Total items failed	7

MOT #24		2024-04-11 13:11
MOT test	number	335047801063
Result		✓ Passed
Next expi	ry date	2025-04-10
Advice (c))	Brake pipe corroded, covered in grease or other material Both front to rear	metal pipes (1.1.11
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Lower radiator mounts corroded	

CarCheck.co.uk page 3/18



report date: 2024-03-28

MOT #23 2024-04-01 15:08

MOT test number 949025450785

Result X Failed

MAJOR Nearside Other passenger door cannot be opened from outside the vehicle side loading (6.2.3 (a))

Advice Brake pipe corroded, covered in grease or other material both front to rear metal brake pipes

(1.1.11 (c))

Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice Coil spring corroded both rear springs (5.3.1 (b) (i))

Advice Lower radiator x mounts excessively corroded

MAJOR Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill (7.1.1 (a) (i))

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MAJOR Offside Other passenger door cannot be opened from outside the vehicle side loading (6.2.3 (a))

Advice Axle swivel pins and bushes swivel pin and/or bush slightly worn rear axle bushes (5.1.2 (b) (i))

Advice Engine mil on(pre 2008)

MAJOR Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill area (5.3.6 (a) (i))

Minor Headlamp lens slightly defective both headlamp lenses cloudy, beam images faint (4.1.1 (b) (i))

MAJOR Steering locking device missing split pins missing from both track rod ends (2.1.3 (d))

MOT #22 2023-02-24 14:57

MOT test number 561712416591

Result \rightarrow Passed

Advice Lower crossmember panel under radiator rusting through

Advice Front and rear subframes and components rusting

Advice Tyre worn close to legal limit/worn on edge off side front tyre inner edge bald and close to limits

(5.2.3 (e))

CarCheck.co.uk page 4/18



report date: 2024-03-28

MOT #21 2023-02-15 14:48

MOT test number 973050616890

Result X Failed

Advice

Lower crossmember panel under radiator rusting through

MAJOR Suspension component mounting prescribed area excessively corroded significantly reducing structural strength rear of off side sill area (5.3.6 (a) (i))

MAJOR Suspension component mounting prescribed area excessively corroded significantly reducing structural strength rear of near side inner sill area (5.3.6 (a) (i))

Advice

Tyre worn close to legal limit/worn on edge off side front tyre inner edge bald and close to limits

(5.2.3 (e))

MAJOR Nearside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))

MAJOR Brake pipe excessively corroded rear of near side front to rear pipe (1.1.11 (c))

Advice Front and rear subframes and components rusting

MAJOR Suspension component mounting prescribed area excessively corroded significantly reducing structural strength rear of off side inner sill area (5.3.6 (a) (i))

MAJOR Suspension component mounting prescribed area excessively corroded significantly reducing structural strength rear of near side sill area (5.3.6 (a) (i))

MAJOR Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))

MAJOR Brakes imbalanced across an axle off side front slow to react (1.2.1 (b) (i))

CarCheck.co.uk page 5/18



report date: 2024-03-28

MOT #20 2022-12-20 16:18

MOT test number 770550123990

Result X Failed

MAJOR Nearside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting inner door sill (6.2.2 (d) (i))

MAJOR Offside Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting outer door sill (6.2.2 (d) (i))

DANGEROUS Offside Rear Brake hose ferrule excessively corroded and likely to fail (1.1.12 (f) (ii))

MAJOR Offside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

MAJOR Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Corrsion to underside

MAJOR Offside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting inner door sill (6.2.2 (d) (i))

DANGEROUS Nearside Rear Brake hose ferrule excessively corroded and likely to fail (1.1.12 (f) (ii))

MAJOR Nearside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

Advice Stop lamp(s) non-obligatory stop lamp not working high level (4.3.1 (a) (ii))

MAJOR Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

MOT #19 2021-12-09 11:21

MOT test number 420231413459

Result \(\sqrt{Passed} \)

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 6/18



report date: 2024-03-28

MOT #18 2020-12-15 12:04

MOT test number 195256431459

Result ✓ Passed

Advice Brake pipe corroded, covered in grease or other material both rear and front to rear (1.1.11 (c))

Advice Front Suspension component mounting prescribed area is corroded but not considered excessive cross member (5.3.6 (a) (i))

Advice Coil spring corroded both rear and offside front (5.3.1 (b) (i))

Advice Sub-frame corroded but not seriously weakened front and front mounting points (5.3.3 (b) (i))

Advice Rear exhaust deteriorated

MOT #17 2020-12-14 12:20

MOT test number 902408147195

Result X Failed

MAJOR Suspension component mounting prescribed area excessively corroded significantly reducing structural strength both outer sills at rear (5.3.6 (a) (i))

Advice Front Suspension component mounting prescribed area is corroded but not considered excessive cross member (5.3.6 (a) (i))

Advice Coil spring corroded both rear and offside front (5.3.1 (b) (i))

Advice Rear exhaust deteriorated

Advice Sub-frame corroded but not seriously weakened front and front mounting points (5.3.3 (b) (i))

MAJOR Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill (5.3.6 (a) (i))

Advice Brake pipe corroded, covered in grease or other material both rear and front to rear (1.1.11 (c))

MOT #16 2019-06-14 11:27

MOT test number 809439829608

CarCheck.co.uk page 7/18



Result

MT05YLK

report date: 2024-03-28

✓ Passed

MOT #15 2019-06-14 11:27

MOT test number 148087241355

Result X Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #14 2018-06-14 09:00

MOT test number 975096059204

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Vehicle structure is corroded but structural rigidity is not significantly reduced front and rear (6.1.1 (c) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both sides inner sills (6.1.1 (c) (i))

Advice Central Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #13 2017-06-19 13:08

MOT test number 426133712065

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered

excessive sills (2.4.A.3)

CarCheck.co.uk page 8/18



report date: 2024-03-28

MOT #12 2017-06-16 11:10

MOT test number 539918348154

Result X Failed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear coil spring corroded (2.4.C.1b)

Fail Nearside Rear Trailing arm synthetic bush deteriorated resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive sills (2.4.A.3)

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Fail Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #11 2016-06-01 10:59

MOT test number 659333229112

Result

Passed

Advice Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #10 2015-06-15 09:14

MOT test number 775546165121

Result

Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2014-06-12 12:01

MOT test number 658453064155

CarCheck.co.uk page 9/18



report date: 2024-03-28

MOT #8		2013-06-27 09:47
MOT test	number	706838173106
Result		✓ Passed
Notice	Steering rack bushes worn	
Notice	Rear axle bushes splitting	
Notice	Ctr stop lamp	

MOT #7	2012-06-26 09:29
MOT test number	295778172101
Result	✓ Passed
Notice Drivers wiper blade split	

MOT #6	2012-06-22 10:35
MOT test number	116154872140
Result	X Failed
Notice Spare tyre defective	
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Notice Drivers wiper blade split	
Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #5	2011-06-22 11:17
MOT test number	887963471195
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2010-06-24 14:04
MOT test number	452425570149
Result	✓ Passed

CarCheck.co.uk page 10/18




report date: 2024-03-28

MOT #3 2009-06-26 10:31 **MOT test number** 201287579157 Result ✓ Passed MOT #2 2008-06-27 17:01 **MOT** test number 342989478118 Result ✓ Passed MOT #1 2008-06-27 15:13 264789478458 **MOT test number** Result × Failed Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Offside Front Tyre worn close to the legal limit (4.1.E.1) **Advice**

CarCheck.co.uk page 11/18



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	10 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 12/18




report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 13/18



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 14/18



Owner history	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	UK SIPE
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 15/18



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 16/18



Mileage check

Odometer	In kilometers
Mileage registrations	26
First mileage registration	2005-06-28
Last registration	2024-04-11
Complete history	See info



Registration #1	2005-06-28	16 mi
Registration #2	2008-06-27	41.020 mi
Registration #3	2008-06-27	41.020 mi
Registration #4	2009-06-26	49.996 mi
Registration #5	2010-06-24	59.298 mi
Registration #6	2011-06-22	67.722 mi
Registration #7	2012-06-22	74.281 mi
Registration #8	2012-06-26	74.368 mi
Registration #9	2013-06-27	78.283 mi
Registration #10	2014-06-12	83.579 mi
Registration #11	2015-06-15	87.930 mi
Registration #12	2016-06-01	92.361 mi
Registration #13	2017-06-16	97.785 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		11.777 au

CarCheck.co.uk page 17/18



Car features

S0225	Air conditioning

The TOYOTA factory car options list is only available in the premium report.

S0295

50482

\$0501 \$0566

\$0567 \$0569

View the complete TOYOTA factory list for this vehicle here.

More info >

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1810 mm
Length	4750 mm
Wheel base	2900 mm
Kerb weight	1740 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	87 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 18/1

Number of axles 2

Engine number 1CD0508265