



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Silver
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	129 Nm at 4.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg






Internet history

Entry 1

Date	2021-09-02
Pictures	31
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #24** 2021-08-13 10:45**MOT test number** 190283703098**Result** ✓ Passed**Next expiry date** 2022-08-12**Advice** Offside Rear Brake pipe corroded, covered in grease or other material feeding flexi (1.1.11 (c))**Advice** Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))**Advice** Long travel on foot brake**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material feeding flexi (1.1.11 (c))**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #23** 2021-07-29 08:15**MOT test number** 225158109102**Result** ✗ Failed**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Minor** Windscreen wiper blade defective both front wiper blades split (3.4 (b) (i))**MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**MAJOR** Nearside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen jet blocked (3.5 (a))**MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**MAJOR** Nearside Rear Parking (secondary brake) on a single line braking system grabbing severely (1.3.1 (c))



MOT #22

2020-08-05 15:04

MOT test number

783137193327

Result

✓ Passed

- Advice** Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))
- Advice** Brake hose has slight corrosion to ferrule rusting on all hoses (1.1.12 (f) (i))
- Advice** Oil leak, but not excessive slight leak from chain tensioner cover ? (8.4.1 (a) (i))
- Minor** Headlamp lens slightly defective both outer lenses 'fogged' (4.1.1 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material heavy rusting on exposed sections of both rear brake pipes (1.1.11 (c))
- Advice** Tyre slightly damaged/cracking or perishing both front tyres perished (5.2.3 (d) (ii))
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive rusting on inner sills and rear chassis (5.3.6 (a) (i))

MOT #21

2020-07-24 08:22

MOT test number

546243857554

Result

✗ Failed

- Advice** Brake pipe corroded, covered in grease or other material heavy rusting on exposed sections of both rear brake pipes (1.1.11 (c))
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive rusting on inner sills and rear chassis (5.3.6 (a) (i))
- Advice** Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))
- Advice** Tyre slightly damaged/cracking or perishing both front tyres perished (5.2.3 (d) (ii))
- Minor** Headlamp lens slightly defective both outer lenses 'fogged' (4.1.1 (b) (i))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Brake hose has slight corrosion to ferrule rusting on all hoses (1.1.12 (f) (i))
- MAJOR** Supplementary restraint system warning lamp indicates a fault air bag lamp on and offside front curtain air bag loose on pillar (7.1.6 (a))
- Advice** Oil leak, but not excessive slight leak from chain tensioner cover ? (8.4.1 (a) (i))
- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect bulb not fitted correctly (4.1.2 (c))
- Advice** Nearside screen wash jet partially blocked

**MOT #20**

2019-07-22 13:29

MOT test number

936541820413

Result

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive rusting on sills and rear chassis - heavy in places (5.3.6 (a) (i))
- Advice** Front Tyre slightly damaged/cracking or perishing both front tyres starting to perish (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19

2019-07-22 09:00

MOT test number

277087686012

Result

✗ Failed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive rusting on sills and rear chassis - heavy in places (5.3.6 (a) (i))
- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Rear screen wash not working - pump?
- Advice** Nearside Rear Parking (secondary brake) grabbing slightly also - low performance from offside rear - imbalance 34% (1.3.1 (c))
- Advice** Front Tyre slightly damaged/cracking or perishing both front tyres starting to perish (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18

2018-07-26 14:52

MOT test number

160764430162

Result

✓ Passed

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Underside of vehicle corroded
- Advice** Nearside front tyre perished on side wall

**MOT #17**

2018-07-26 08:40

MOT test number

342215892653

Result**✗ Failed****Advice**

Underside of vehicle corroded

Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Nearside front tyre perished on side wall

MAJOR

Offside Front Suspension arm corroded and seriously weakened (5.3.3 (b) (i))

MOT #16

2017-07-19 15:30

MOT test number

675182842034

Result**✓ Passed****Advice**

Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #15

2017-07-19 08:23

MOT test number

393335881108

Result**✗ Failed****Fail**

Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail

Nearside Front position lamp(s) not working (1.1.A.3b)

Fail

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice

Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #14

2016-08-09 13:00

MOT test number

515882468456

Result**✓ Passed****Advice**

Rear screen wash pump not working

**MOT #13**

2016-08-09 08:33

MOT test number

164565559686

Result**✗ Failed****Advice** Rear screen wash pump not working**Advice** Offside Rear rear parking (secondary) brake grabbing slightly suspect brake linings contaminated/split (3.7.B.6b)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #12**

2015-08-13 08:55

MOT test number

898116968437

Result**✓ Passed****Advice** Brake pad(s) wearing thin (3.5.1g)**Advice** Child seat fitted not allowing inspection of adult seat belt**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside rear tyre stepped on inner edge**MOT #11**

2015-08-13 08:55

MOT test number

934735929852

Result**✗ Failed****Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Child seat fitted not allowing inspection of adult seat belt**Advice** Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside rear tyre stepped on inner edge**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #10**

2014-08-29 13:37

MOT test number

375181144251

Result

✓ Passed

Advice Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Rear screen wash not working**MOT #9**

2014-08-29 09:56

MOT test number

617011944241

Result

✗ Failed

Fail Nearside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Rear screen wash not working**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #8**

2013-06-05 15:00

MOT test number

936216853102

Result

✓ Passed

Notice Rear screen wash not working (pump?)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7**

2013-06-05 10:59

MOT test number

339476253158

Result**✗ Failed****Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Rear screen wash not working (pump?)**Notice** Offside wiper blade in poor condition**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6**

2012-05-25 14:54

MOT test number

496086942192

Result**✓ Passed****MOT #5**

2012-05-22 14:37

MOT test number

206683242188

Result**✗ Failed****Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)



MOT #4	2011-05-24 17:46
MOT test number	595164241171
Result	✓ Passed
MOT #3	2010-05-14 11:29
MOT test number	380414330165
Result	✓ Passed
MOT #2	2009-05-21 11:54
MOT test number	593041149174
Result	✓ Passed
MOT #1	2009-05-21 11:54
MOT test number	574181749141
Result	✗ Failed
Pass with rectification	Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Pass with rectification	Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Pass with rectification	Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Pass with rectification	Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YP06GDK
Plate since	2019-03-28
Current registration	YP06GDK
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2006-05-20
Last registration	2021-08-13
Complete history	See info



Registration #1	2006-05-20	20 mi
Registration #2	2009-05-21	25.469 mi
Registration #3	2010-05-14	34.997 mi
Registration #4	2011-05-24	43.667 mi
Registration #5	2012-05-22	46.389 mi
Registration #6	2012-05-25	46.389 mi
Registration #7	2013-06-05	52.088 mi
Registration #8	2013-06-05	52.088 mi
Registration #9	2014-08-29	58.345 mi
Registration #10	2014-08-29	58.345 mi
Registration #11	2015-08-13	62.113 mi
Registration #12	2015-08-13	62.113 mi
Registration #13	2016-08-09	65.050 mi
Registration #14	2016-08-09	65.050 mi
Registration #15	2016-08-09	65.050 mi
Registration #16	2016-08-09	65.050 mi
Registration #17	2016-08-09	65.050 mi
Registration #18	2016-08-09	65.050 mi
Registration #19	2016-08-09	65.050 mi
Registration #20	2016-08-09	65.050 mi
Registration #21	2016-08-09	65.050 mi
Registration #22	2016-08-09	65.050 mi
Registration #23	2016-08-09	65.050 mi
Registration #24	2016-08-09	65.050 mi
Registration #25	2016-08-09	65.050 mi



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4ZZU798028