






report date: 2022-08-10

General information

Make	LOTUS
Model	ELAN ELAN SE
Colour	Red
Year of manufacture	1992
Top speed	137 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	198 Nm at 4.200 rpm
Engine capacity	1.588 cc
Cylinders	4
Fuel type	Petrol
Consumption city	19.3 mpg
Consumption extra urban	37.2 mpg
Consumption combined	37.2 mpg



CarCheck.co.uk page 1/16



Internet history

Entry 1

Date 2021-07-03

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



report date: 2022-08-10

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-05-03
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	76
Total items failed	17

MOT #21	2024-04-23 09:13
MOT test number	119983253131
Result	✓ Passed
Next expiry date	2025-05-03
Advice Coolant leak	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #20	2023-04-21 08:14
MOT test number	793457654570
Result	✓ Passed
MOT #19	2022-05-03 12:48
MOT test number	800197695526
Result	✓ Passed

MOT #18		2021-05-04 08:07
MOT test	number	259674338722
Result		✓ Passed
Advice	Brake hose slightly deteriorated both fronts (1.1.12 (b) (ii))	
Advice	Wheel bearing has slight play both rears (5.1.3 (a) (i))	
Advice	Both front tyres over 10 years old	

CarCheck.co.uk page 3/16



report date: 2022-08-10

2021-04-28 09:49 **MOT #17** 712614491142 **MOT** test number Result **★** Failed **Advice** Brake hose slightly deteriorated both fronts (1.1.12 (b) (ii)) Fail Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a)) Fail Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b)) **Advice** Both front tyres over 10 years old **Advice** Wheel bearing has slight play both rears (5.1.3 (a) (i)) Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) Brake fluid contaminated (1.8 (a)) Fail

MOT #16		2015-10-08 15:51
MOT test	number	630484157440
Result		✓ Passed
Advice	Nearside Rear wheel bearing has slight play (2.6.2)	
Advice	Offside Rear wheel bearing has slight play (2.6.2)	

CarCheck.co.uk page 4/16



Advice

K675LAP

report date: 2022-08-10

MOT #15 2015-10-05 11:46 **MOT** test number 313365436697 Result × Failed Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3) **Advice** Nearside parking brake performance lower than offside,, recommend check Fail Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b) Advice Nearside Rear wheel bearing has slight play (2.6.2) Fail Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4) Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3) Parking brake: efficiency below requirements (3.7.B.7) Fail **Advice** Offside rear brake binding slightly Fail Front Exhaust has a major leak of exhaust gases (7.1.2)

MOT #14		2014-10-10 12:35
MOT test	number	518363184207
Result		✓ Passed
Notice	Minor oil leak	
Notice	Both rear footbrake performances slightly low	
Advice	Suspension arm corroded but not seriously weakened (2.4.G.1)	

Offside Rear wheel bearing has slight play (2.6.2)

CarCheck.co.uk page 5/16



MOT #13

MOT test number

988137773263

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Both rear footbrake performances slightly low

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Recommend check steering track

MOT #12 2013-10-04 12:17

MOT test number 317357073286

Result X Failed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Both rear footbrake performances slightly low

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Recommend check steering track

Pass with rectification Offside Headlamp not working on dipped beam (1.7.5a)

MOT #11 2012-10-04 12:40

MOT test number 458278872236

Result

Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Recommend check tyre pressures and steering track

Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Both rear footbrake performances slightly low

CarCheck.co.uk page 6/16



MOT #10 2011-09-29 12:35

MOT test number 268972571281

Result Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Engine sump, slight damage

Advice Service brake: service brake efficiency only just met. It would appear that the braking system

requires adjustment or repair. (3.7.B.7)

Notice Oil leak

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Recommend check steering track

MOT #9 2011-09-29 12:35

MOT test number 947702471278

Result X Failed

Advice Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice Oil leak

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Recommend check steering track

Pass with rectification Exhaust emissions carbon monoxide content excessive (7.3.B.1a)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Engine sump, slight damage

CarCheck.co.uk page 7/16



MOT #8 2010-09-28 12:49

MOT test number 124051970272

Result \sqrt{Passed}

Notice Advise check steering track and tyre pressures

Advice Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Suspension arm corroded but not seriously weakened (2.4.G.1)

Notice Engine sump slight damage

Advice Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

Notice Rear footbrake performances low

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires

adjustment or repair. (3.7.B.5b)

Advice Offside Rear Suspension arm corroded but not seriously weakened (2.4.G.1)

MOT #7 2009-09-21 10:22

MOT test number 111384969275

Advice Nearside Headlamp not in a clean condition but not affecting beam image (1.2.4a)

Advice Offside Headlamp not in a clean condition but not affecting beam image (1.2.4a)

MOT #6 2009-09-18 14:22

MOT test number 764861269256

Result ★ Failed

Advice Nearside Headlamp not in a clean condition but not affecting beam image (1.2.4a)

Fail Nearside Headlamp aim too low and too far to the left. (1.8)

Advice Offside Headlamp not in a clean condition but not affecting beam image (1.2.4a)

CarCheck.co.uk page 8/16



Result

K675LAP report date: 2022-08-10

✓ Passed

 MOT #5
 2008-09-22 10:40

 MOT test number
 804146568284

MOT #4 2007-10-11 15:02

MOT test number 363054587447

Advice Nearside Front Headlamp damaged but light output not reduced (1.7.5a)

Advice Centre Vehicle structure has slight corrosion (6.1.A.1)

Advice Offside Front Suspension arm corroded but not seriously weakened (2.4.G.1)

Advice Offside Rear Suspension arm corroded but not seriously weakened (2.4.G.1)

Advice Offside Front Headlamp damaged but light output not reduced (1.7.5a)

Advice Nearside Front Suspension arm corroded but not seriously weakened (2.4.G.1)

Notice Sump badly damaged may cause mayjor oil leak soon

Advice Nearside Rear Suspension arm corroded but not seriously weakened (2.4.G.1)

CarCheck.co.uk page 9/16



report date: 2022-08-10

MOT #3 2007-10-02 12:38 **MOT** test number 432975077200 Result **X** Failed **Advice** Offside Rear Suspension arm corroded but not seriously weakened (2.4.G.1) Advice Offside Front Suspension arm corroded but not seriously weakened (2.4.G.1) Fail Rear Exhaust has a major leak of exhaust gases (7.1.2) Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3) Fail Advice Offside Front Headlamp damaged but light output not reduced (1.7.5a) Advice Nearside Rear Suspension arm corroded but not seriously weakened (2.4.G.1) Nearside Front Suspension arm corroded but not seriously weakened (2.4.G.1) Advice Notice Sump badly damaged may cause mayjor oil leak soon Fail Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4) **Advice** Nearside Front Headlamp damaged but light output not reduced (1.7.5a) **Advice** Centre Vehicle structure has slight corrosion (6.1.A.1)

MOT #2		2006-10-02 14:38
MOT test	number	894795776282
Result		✓ Passed
Notice	N/S/F indicator lense cracked	
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)	

MOT #1	2005-09-29 15:06
MOT test number	720792975222
Result	✓ Passed


CarCheck.co.uk page 10/16



3 May 2025

Tax & MOT check

MOT expiry date



Full MOT history See MOT history

CarCheck.co.uk page 11/16



report date: 2022-08-10

Damage history

Check the damage history for this LOTUS. See if, where and when this LOTUS had damage and the car repair costs. We also check if this LOTUS was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra LOTUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/16



Owner history	
For how long did the current and previous owner(s) have this LOTUS? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

HARMAN CO.	

	More info >
Plate changes	
See in this check if this LOTUS had different number plates.	
Number of plates	
Current registration	NK SING SING SING SING SING SING SING SING
Plate since	
Current registration	NK NE
Plate since	
	Moro info

CarCheck.co.uk page 13/16



Finance check

Check if this LOTUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LOTUS has been settled.

If not, and you buy this LOTUS then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LOTUS is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 14/16



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	1992-09-08
Last registration	2024-04-23
Complete history	See info



Registration #1	1992-09-08	28 mi
Registration #2	2005-09-29	31.095 mi
Registration #3	2006-10-02	32.190 mi
Registration #4	2007-10-02	33.578 mi
Registration #5	2007-10-11	33.578 mi
Registration #6	2008-09-22	34.122 mi
Registration #7	2009-09-18	34.852 mi
Registration #8	2009-09-21	34.852 mi
Registration #9	2010-09-28	35.857 mi
Registration #10	2011-09-29	37.093 mi
Registration #11	2012-10-04	38.192 mi
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		91,700 esi
Registration #20		11.777 es
Registration #21		11.777 es

More info >

CarCheck.co.uk page 15/16



- ·		_	
Luman	CIONC	A. W	MAIAH
Dimen:	כווטוכ	CX V	velull

Width	1885 mm
Height	1230 mm
Length	3803 mm
Wheel base	2575 mm

Additional information

Number of doors	2
Engine number	234362

CarCheck.co.uk page 16/16