



W679TRX

report date: 2024-03-28

General information

Make	MAZDA
Model	BONGO
Colour	White
Year of manufacture	2000
Gearbox	-

Engine & fuel consumption

Engine capacity	2.499 cc
Fuel type	Diesel



LABEL UNKNOWN



## MOT history

MOT expiry date	2023-03-01
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	96
Total items failed	49

MOT #25 2022-03-02 17:14

MOT test number 728986071303

Result ✓ Passed

Next expiry date 2023-03-01

**Advice** Nearside Inner Vehicle structure is repaired but structural rigidity is not significantly reduced sill's (6.1.1 (d) (i))

**Advice** Offside Inner Vehicle structure is repaired but structural rigidity is not significantly reduced sill (6.1.1 (d) (i))

**Advice** Suspension component mounting repair covered in underseal (5.3.6 (a) (i))

MOT #24 2022-02-22 13:35

MOT test number 952216591369

Result ✗ Failed

**Fail** Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced chassis cross member (6.1.1 (c) (i))

**Advice** Nearside Inner Vehicle structure is repaired but structural rigidity is not significantly reduced sill's (6.1.1 (d) (i))

**Fail** Front Service brake excessively binding (1.2.1 (f))

**Fail** Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced inner wheel arch (6.1.1 (c) (i))

**Fail** Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced inner wheel arch (6.1.1 (c) (i))

**Advice** Offside Inner Vehicle structure is repaired but structural rigidity is not significantly reduced sill (6.1.1 (d) (i))

**Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

**Fail** Nearside Front Inner Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced chassis [marked in yellow] (6.1.1 (c) (i))

**MOT #23** 2021-02-19 16:21**MOT test number** 759431465789**Result** ✓ Passed

- Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Suspension component mounting repair covered in underseal inner sill (5.3.6 (a) (i))
- Advice** Offside Suspension component mounting repair covered in underseal inner sill (5.3.6 (a) (i))

**MOT #22** 2021-02-17 12:43**MOT test number** 882559476725**Result** ✗ Failed

- Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength shocker area[chassis] (5.3.6 (a) (i))
- Fail** Offside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced inner sill (6.1.1 (c) (i))
- Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced chassis (6.1.1 (c) (i))
- Fail** Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced inner wheel arch (6.1.1 (c) (i))

**MOT #21** 2019-07-15 12:11**MOT test number** 189077628341**Result** ✓ Passed

- Advice** Nearside & Offside sills corroded
- Advice** Chassis corroded
- Minor** Front Outer Drive shaft joint constant velocity boot severely deteriorated Nearside & Offside (6.1.7 (g) (i))

**MOT #20**

2019-07-12 11:13

**MOT test number**

648782478710

**Result****✗ Failed****Advice** Nearside & Offside sills corroded**Fail** Nearside Front Inner Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting sill (6.2.2 (d) (i))**Minor** Front Outer Drive shaft joint constant velocity boot severely deteriorated Nearside & Offside (6.1.7 (g) (i))**Advice** Chassis corroded**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**MOT #19**

2018-07-13 08:46

**MOT test number**

924374365052

**Result****✓ Passed****Advice** Sills corroded**Advice** Chassis corroded**MOT #18**

2018-07-10 15:39

**MOT test number**

594101110930

**Result****✗ Failed****Advice** Chassis corroded**Fail** Offside Front Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting sill (6.2.2 (d) (i))**Advice** Sills corroded**MOT #17**

2017-07-12 13:37

**MOT test number**

949904340710

**Result****✓ Passed**



MOT #16	2016-12-02 13:04
MOT test number	673117459119
Result	✗ Failed

- Fail** Nearside Rear Vehicle structure has an inadequate repair, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Advice** Exhaust system corroded
- Fail** Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)
- Fail** Offside Front Vehicle structure has an inadequate repair, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Advice** Rear outriggers offside and nearside corroded
- Fail** Nearside Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Advice** Unable to check offside and nearside rear wheel bearings as unable to spins wheels due to four wheel drive system
- Fail** Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Advice** Offside sills heavily repaired and filler
- Fail** Rear Rear fog lamp not working (1.3.2b)
- Fail** Nearside Front Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Advice** Offside and nearside floor to sills corroded
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Offside Rear Vehicle structure has an inadequate repair, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Advice** Unable to view rear brake pads
- Fail** Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)
- Advice** Front brake discs corroded
- Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Rear Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Front subframe corroded
- Fail** Offside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Advice** Nearside sills heavily repaired and filler
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #15** 2015-09-30 15:00**MOT test number** 700498252010**Result** ✓ Passed

**Advice** Offside Front Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt aging (2.4.G.2)

**Advice** Nearside Front Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt aging (2.4.G.2)

**Advice** Driveshaft gaiters aging

**MOT #14** 2014-10-02 17:05**MOT test number** 918675474267**Result** ✓ Passed

**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #13** 2014-10-02 10:48**MOT test number** 127145374204**Result** ✗ Failed

**Notice** Both rear tyres on legal limits

**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Notice** Coolant leak

**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)





MOT #12

2013-07-16 11:22

MOT test number

205807493136

Result

✓ Passed

- Notice

Coolant hose has been repaired
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice

Discs rusty
- Notice

Arches repaired by filler
- Notice

Fuel tank dented
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice

Filler repair to offside outer sill



MOT #11	2013-06-19 11:32
MOT test number	265220773178
Result	✗ Failed

- Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Offside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Nearside Rear Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Offside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Arches repaired by filler
- Fail** Nearside Rear Vehicle structure excessively corroded within 30cm of towbar mounting (6.6.6)
- Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Notice** Fuel tank dented
- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Nearside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Notice** Filler repair to offside outer sill
- Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Advice** Offside Rear Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Coolant hose has been repaired
- Fail** Nearside Seat belt anchorage prescribed area is excessively corroded (5.2.6)
- Fail** Nearside Rear Vehicle structure excessively corroded within 30cm of towbar mounting (6.6.6)
- Notice** Discs rusty

**MOT #10** 2012-07-12 12:50**MOT test number** 149914192127**Result** ✓ Passed**MOT #9** 2012-03-19 14:50**MOT test number** 865149672044**Result** ✓ Passed**Advice** Offside Outer Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Body has slight corrosion (6.1.B.2)**MOT #8** 2011-01-28 16:52**MOT test number** 439288321055**Result** ✓ Passed**Advice** Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Outer Front Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Notice** N/s/f & o/s/f tyres wearing off on inner edges**Advice** Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Notice** O/s & n/s inner & outer sills slightly corroded



MOT #7

2010-02-01 13:06

MOT test number

302892730048

Result

✓ Passed

- Advice

Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)
- Advice

Nearside Front Upper Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice

Exhaust has part of the system slightly deteriorated (7.1.1a)
- Advice

Front brake disc slightly pitted (3.5.1h)
- Advice

Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice

Offside Front constant velocity joint gaiter deteriorated (2.5.C.1a)
- Advice

Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice

Body has slight corrosion (6.1.B.2)
- Advice

Nearside Front Brake pipe slightly corroded (3.6.B.2c)



MOT #6 2010-02-01 13:06

MOT test number 123112930437

Result ✗ Failed

- Advice** Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)
- Advice** Nearside Front Upper Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)
- Advice** Front brake disc slightly pitted (3.5.1h)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front constant velocity joint gaiter deteriorated (2.5.C.1a)
- Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Pass with rectification** Centre Exhaust system not adequately supported (7.1.1)
- Advice** Body has slight corrosion (6.1.B.2)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #5 2009-02-04 16:58

MOT test number 754425139057

Result ✓ Passed

- Advice** Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Inner Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Offside inner and outer cills has slight corrosion

**MOT #4** 2009-01-16 13:08**MOT test number** 812426419069**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Rear fog lamp not working (1.3.2b)**Advice** Offside Body has slight corrosion (6.1.B.2)**Fail** Brake performance not tested (3.7.A.1)**Advice** Offside Front Body has slight corrosion (6.1.B.2)**Fail** Service brake: efficiency below requirements (3.7.C.1a)**Advice** Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Rear Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Fail** Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)**MOT #3** 2008-01-21 10:13**MOT test number** 193141228432**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)



MOT #2	2007-01-22 12:48
MOT test number	362432027029
Result	✓ Passed

MOT #1	2006-01-25 10:22
MOT test number	720405726038
Result	✓ Passed
Advice	Brake pad(s) wearing thin (3.5.1g)
Notice	O/s/f tyre wearing on the inner edge





Tax & MOT check

✕  
Untaxed

Tax expired:  
1 November 2022

✕  
MOT

Expired:  
1 March 2023

Tax status		Expired at 1 November 2022
Days left		546 days too late
MOT expiry date		1 March 2023
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>W679TRX</b>
Plate since	2019-09-28
Current registration	<b>W679TRX</b>
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-09-02
Last registration	2022-03-02
Complete history	<a href="#">See info</a>



Registration #1	2003-09-02	6 mi
Registration #2	2006-01-25	70.421 mi
Registration #3	2007-01-22	104.120 mi
Registration #4	2008-01-21	75.659 mi
Registration #5	2009-01-16	139.386 mi
Registration #6	2009-02-04	139.800 mi
Registration #7	2010-02-01	154.661 mi
Registration #8	2011-01-28	165.479 mi
Registration #9	2012-03-19	168.825 mi
Registration #10	2012-07-12	16.920 mi
Registration #11	2013-06-19	107.347 mi
Registration #12	2013-07-16	107.347 mi
Registration #13	2014-10-02	109.526 mi
Registration #14	2015-01-20	109.526 mi
Registration #15	2015-01-20	109.526 mi
Registration #16	2015-01-20	109.526 mi
Registration #17	2015-01-20	109.526 mi
Registration #18	2015-01-20	109.526 mi
Registration #19	2015-01-20	109.526 mi
Registration #20	2015-01-20	109.526 mi
Registration #21	2015-01-20	109.526 mi
Registration #22	2015-01-20	109.526 mi
Registration #23	2015-01-20	109.526 mi
Registration #24	2015-01-20	109.526 mi
Registration #25	2015-01-20	109.526 mi



Additional information

Number of seats	8
Engine number	0483