



report date: 2024-03-28

General information

Make	MAZDA
Model	5 TS2
Colour	Grey
Year of manufacture	-
Top speed	113 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	165 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg





Internet history

Entry 1

Date	2022-01-08
Pictures	0
Listing price	View report

source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #19	2021-01-21 10:21
MOT test number	580982340241
Result	✓ Passed
Next expiry date	2022-02-13
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front engine oil leak
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced all under body corrosion (6.1.1 (c) (i))

MOT #18	2020-02-04 13:17
MOT test number	360495241369
Result	✓ Passed
Advice	Underbody slight corrosion



MOT #17 2020-01-28 15:04

MOT test number 404883711866

Result ✖ Failed

MAJOR Offside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Exhaust slightly deteriorated

MAJOR Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Nearside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))

MAJOR Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Underbody slight corrosion

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))



MOT #16 2020-01-25 14:59

MOT test number 419770678021

Result ✗ Failed

- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- MAJOR** Nearside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))
- Advice** Nearside Vehicle structure is corroded but structural rigidity is not significantly reduced inner sill (6.1.1 (c) (i))
- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 27% (1.2.1 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- MAJOR** Offside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))
- Advice** Offside Vehicle structure is corroded but structural rigidity is not significantly reduced inner sill (6.1.1 (c) (i))

MOT #15 2019-02-14 12:43

MOT test number 427748706407

Result ✓ Passed

- Advice** Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Under body corroded
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))



MOT #14 2019-02-14 10:57

MOT test number 588222307496

Result ✗ Failed

Advice Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Under body corroded

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Front Inner Drive shaft joint constant velocity boot missing (6.1.7 (g) (ii))

MOT #13 2018-08-10 10:22

MOT test number 916255536673

Result ✔ Passed

Advice Fluid leak, but not excessive Suspected Coolant leak from radiator area. Unable to see fully without undertray removal. (8.4.1 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge Down to 2.5mm but bald on inner edge. 205/55 R 16 (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front wishbone, front bush. (5.3.4 (a) (i))



MOT #12 2018-08-08 08:45

MOT test number 488929984236

Result ✗ Failed

- Advice** Fluid leak, but not excessive Suspected Coolant leak from radiator area. Unable to see fully without undertray removal. (8.4.1 (a) (i))
- DANGEROUS** Exhaust shield missing where fitted as original equipment creating a risk of fire Fuel tank heat shield missing. (6.1.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front wishbone, front bush. (5.3.4 (a) (i))
- DANGEROUS** Brake master cylinder leaking (1.1.10 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Down to 2.5mm but bald on inner edge. 205/55 R 16 (5.2.3 (e))
- MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively Wiper blade judders across screen. (3.4 (b) (ii))

MOT #11 2017-08-17 09:40

MOT test number 689413523764

Result ✓ Passed

- Advice** Both front and o/s/r tyres worn on edge

MOT #10 2017-08-16 13:57

MOT test number 202516814531

Result ✗ Failed

- Advice** Both front and o/s/r tyres worn on edge
- Fail** Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)
- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #9 2016-08-12 10:54

MOT test number 719935268659

Result ✓ Passed



MOT #8 2015-07-28 13:49

MOT test number 987349705204

Result ✔ Passed

- Notice** Front discs deteriorated on inner facia [s]
- Notice** Offside rear trailing arm bush split
- Notice** Nearside front CV gaiter has a pin hole in it
- Notice** Offside front suspension arm rear bush split
- Notice** Nearside rear trailing arm bush split
- Notice** Exhaust heatshield loose
- Notice** Nearside front suspension arm rear bush split

MOT #7 2015-07-27 15:33

MOT test number 428288905242

Result ✘ Failed

- Notice** Offside rear trailing arm bush split
- Notice** Rear discs deteriorated on edges
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Notice** Nearside front CV gaiter has a pin hole in it
- Notice** Offside front suspension arm rear bush split
- Notice** Nearside rear trailing arm bush split
- Notice** Exhaust heatshield loose
- Fail** Rear brake application uneven (3.7.B.2)
- Notice** Nearside front suspension arm rear bush split
- Notice** Front discs deteriorated on inner fascia(s)



MOT #6 2014-08-11 16:27

MOT test number 296533724281

Result ✓ Passed

- Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Notice** Split on off side front tyre
- Advice** Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2013-08-15 14:22

MOT test number 317527423488

Result ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** O/s/f tyre has a cut on outer sidewall

MOT #4 2012-08-22 14:26

MOT test number 569995632246

Result ✓ Passed

MOT #3 2012-08-16 18:42

MOT test number 105109722212

Result ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Shock absorber has a serious fluid leak (2.7.3)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)

MOT #2 2011-01-21 16:16

MOT test number 427631121007

Result ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #1 2011-01-21 11:09

MOT test number 306711521060

Result ✗ Failed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)

Advice Front Brake pad(s) wearing thin (3.5.1g)




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	YA07FRZ
Plate since	2024-03-28
Current registration	YA07FRZ
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-06-29
Last registration	2021-01-21
Complete history	See info



Registration #1	2007-06-29	26 mi
Registration #2	2011-01-21	29.044 mi
Registration #3	2011-01-21	29.045 mi
Registration #4	2012-08-16	43.369 mi
Registration #5	2012-08-22	43.379 mi
Registration #6	2013-08-15	51.073 mi
Registration #7	2014-08-11	55.660 mi
Registration #8	2015-07-27	62.076 mi
Registration #9	2015-07-28	62.076 mi
Registration #10	2016-08-12	67.304 mi
Registration #11	2017-08-16	78.073 mi
Registration #12	2018-01-21	81.277 mi
Registration #13	2018-01-21	81.277 mi
Registration #14	2018-01-21	81.277 mi
Registration #15	2018-01-21	81.277 mi
Registration #16	2018-01-21	81.277 mi
Registration #17	2018-01-21	81.277 mi
Registration #18	2018-01-21	81.277 mi
Registration #19	2018-01-21	81.277 mi
Registration #20	2018-01-21	81.277 mi
Registration #21	2021-01-21	81.277 mi

[More info >](#)



Safety ratings

NCAP rating ★★★★★
Video [see crash video](#)



Dimensions & weight

Width	1755 mm
Height	1655 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1512 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	L8 20217257