





General information

| Make NISS/ | AN |
|--------------------------|------------|
| Model PIXO | N-TEC |
| Colour Grey | |
| Year of manufacture 2012 | |
| Top speed96 m | ph |
| 0 - 60 mph 14.0 | seconds |
| Gearbox 5 spe | eed Manual |

Engine & fuel consumption

| Power | 67 BHP |
|-------------------------|--------------------|
| Max. torque | 90 Nm at 3.400 rpm |
| Engine capacity | 996 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 103 g/km |
| CO2 label | В |







Internet history

Entry 1

Date Pictures 2022-01-23

10

Listing price

View report



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-05-09 |
|--------------------|------------|
| MOT pass rate | 69 % |
| MOT passed | 9 |
| Failed MOT tests | 4 |
| Total advice items | 34 |
| Total items failed | 9 |

| MOT #13 | | 2023-05-10 12:10 |
|----------------|---|----------------------|
| MOT test | number | 387629342781 |
| Result | | 🗸 Passed |
| Next expi | ry date | 2024-05-09 |
| Advice | Central Front Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice | Central Front Registration plate deteriorated but not likely to be misread (0.1 (| o)) |
| Advice (b)) | Front Headlamp has a product on the lens but not seriously reducing light outp | ut Both sides (4.1.4 |
| Advice | Coil spring corroded All x 4 (5.3.1 (b) (i)) | |





| MOT #12 | 2023-05-09 13:40 |
|---|---------------------|
| MOT test number | 720105288188 |
| Result | 🗙 Failed |
| Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (| b) (ii)) |
| Advice Central Front Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Fail Offside Front Suspension arm pin or bush likely to become detached wishbone rear (5.3.4 (a) (ii)) | arm bush marked |
| Fail Nearside Front Anti-roll bar linkage damaged and seriously weakened bent (5.3.3 (b | o) (i)) |
| Advice Front Headlamp has a product on the lens but not seriously reducing light output (b)) | t Both sides (4.1.4 |
| Fail Nearside Front Suspension arm pin or bush likely to become detached wishbone reamarked (5.3.4 (a) (ii)) | ar arm bush |
| Advice Coil spring corroded All x 4 (5.3.1 (b) (i)) | |
| Advice Central Front Registration plate deteriorated but not likely to be misread (0.1 (b) |)) |
| NOT #11 | 2022 01 24 10 41 |

| MOT #11 | 2022-01-24 18:41 |
|-----------------|------------------|
| MOT test number | 692629052740 |
| Result | ✓ Passed |
| | |

| MOT #10 | | 2021-11-03 16:37 |
|----------------------|--|------------------|
| MOT test | number | 405233962051 |
| Result | | ✓ Passed |
| Advice | Nearside Front Brake pipe corroded, covered in grease or other materia | al (1.1.11 (c)) |
| Advice bushes (5. | Advice Suspension arm pin or bush worn but not resulting in excessive movement both front arms- rear bushes (5.3.4 (a) (i)) | |
| Advice | Offside Front Brake pipe corroded, covered in grease or other material | (1.1.11 (c)) |



| FV12HZU |
|-------------------------|
| report date: 2024-03-29 |

| MOT #9 | 2021-10-27 11:20 |
|---|--------------------|
| MOT test number | 636350547137 |
| Result | 🗙 Failed |
| Fail Nearside Brake pipe excessively corroded front to rear (1.1.11 (c)) | |
| Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 | (c)) |
| Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.1 | 1 (c)) |
| Advice Suspension arm pin or bush worn but not resulting in excessive movement both bushes (5.3.4 (a) (i)) | h front arms- rear |

| MOT #8 | 2020- | 11-11 11:14 |
|----------------|---|-------------|
| MOT test | number 960 |)183612491 |
| Result | | ✓ Passed |
| Advice | Front Brake pipe corroded, covered in grease or other material Both (1.1.11 (c)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge 2.5-3mm (5.2.3 (e)) | |
| Advice | Nearside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 | (c)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge 1.6-2mm (5.2.3 (e)) | |
| Advice (i)) | Front Suspension arm pin or bush worn but not resulting in excessive movement Both (| 5.3.4 (a) |

| MOT #7 | 2019-11-08 11:52 |
|----------------|---|
| MOT test | number 969560431322 |
| Result | ✓ Passed |
| Advice | Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c)) |
| Advice (i)) | Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) |





| MOT #6 | 2019-11-08 11:52 |
|--------------------------------|--|
| MOT test number | 884083248342 |
| Result | × Failed |
| Pass with rectification | Offside Rear fog lamp not working (4.5.1 (a) (ii)) |
| Advice Nearside Brake | pipe corroded, covered in grease or other material front to rear (1.1.11 (c)) |
| Pass with rectification | Rear fog lamp tell-tale not working (4.9.1 (a) (ii)) |
| Advice Front Suspensio (i)) | n arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) |

| MOT #5 | 2018-10-15 13:23 |
|----------------|--|
| MOT test | number 248143639107 |
| Result | ✓ Passed |
| Advice | Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) |
| Advice (i)) | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) |

| MOT #4 | 2018-10-06 08:50 |
|---|--------------------------|
| MOT test number | 70000826564 |
| Result | × Failed |
| Fail Offside Brake pipe excessively corroded front to rear (1.1.11 (c)) | |
| Advice Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) | |
| Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) | |
| Advice Offside Front Suspension arm pin or bush worn but not resulting in excess (i)) | sive movement (5.3.4 (a) |





| МОТ #3 | 2017-10-11 09:36 |
|--|-----------------------|
| MOT test number | 934157103038 |
| Result | ✓ Passed |
| Advice Offside Front Suspension arm rubber bush deteriorated but not resulting rear bush (2.4.G.2) | in excessive movement |
| Advice Offside Brake pipe slightly corroded front to rear (3.6.B.2c) | |
| Advice Offside Rear Tyre worn close to the legal limit 2-2.5mm (4.1.E.1) | |

| MOT #2 | 2016-10-20 10 |):24 |
|-------------------------|--|------|
| MOT test | number 833237904 | 355 |
| Result | ✓ Pas | sed |
| Advice | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | |
| Advice | Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1) | |
| Advice | Both rear tyres slightly perished on outer edges | |
| Advice (2.4.G.2) | Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movemen | t |

| MOT #1 | 2015-11-09 15:06 |
|-----------------|------------------|
| MOT test number | 931328716149 |
| Result | ✓ Passed |



Tax & MOT check

| Tax due: 1 August 2024 | ✓ Taxed | Expires: 9 May 2024 | ✓ МОТ |
|----------------------------------|------------|-------------------------------|----------------------|
| Tax status | | | Valid until 1 August |
| Days left | | | 93 |
| MOT expiry date | | | 9 May 2024 |
| Full MOT history | | | See MOT history |
| Tax calculation | | | |
| Vahiela class | | 10 | |

| Vehicle class | 48 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|---------|-------|
| Date | | |
| Category | | Lamp |
| Туре | | |
| Damage 2 | | AMPL |
| Date | | · · · |
| Category | 1000000 | AMPL |
| Туре | | |

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|---|-------------|
| *********** | |
| ******** | |
| ******* | |
| ************ | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this NISSAN had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2012-03-27 |
| Last registration | 2023-05-10 |
| Complete history | See info |



| Registration #1 | 2012-03-27 | 14 mi |
|------------------|------------|------------|
| Registration #2 | 2015-11-09 | 23.540 mi |
| Registration #3 | 2016-10-20 | 37.065 mi |
| Registration #4 | 2017-10-11 | 43.268 mi |
| Registration #5 | 2018-10-06 | 48.173 mi |
| Registration #6 | 2018-10-15 | 48.343 mi |
| Registration #7 | 2019-11-08 | 55.894 mi |
| Registration #8 | 2019-11-08 | 55.894 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 esi |
| Registration #15 | | 10.200 mil |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| \$0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Dimensions & weight

| Width | 1630 mm |
|---------------------|---------|
| Height | 1470 mm |
| Length | 3565 mm |
| Wheel base | 2360 mm |
| Kerb weight | 855 kg |
| Max. allowed weight | 1250 kg |

Additional information

| Fuel delivery | Multi-Point Injection |
|-----------------|-----------------------|
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 145729 |