





report date: 2024-03-29

### General information

Make	MAZDA
Model	3 SPORT
Colour	White
Year of manufacture	-
Top speed	128 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	151 BHP
Max. torque	191 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	52.3 mpg
Consumption combined	41.5 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-29

## MOT history

MOT #18	2020-08-12 12:47
MOT test number	210995942320
Result	<b>✓</b> Passed
Next expiry date	2021-08-11
MOT #17	2020-08-11 12:39
MOT test number	667898750116
Result	<b>×</b> Failed

**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #16		2020-03-09 14:21
MOT test	number	732253610179
Result		<b>✓</b> Passed
Advice	Nearside Rear Lower Suspension arm corroded but not seriously weakened (	(5.3.3 (b) (i))
Advice	Entire underside of vehicle is corroded and has a covering of underseal.	
Advice floor chass	Offside Front Seat belt anchorage prescribed area is corroded but not consider sis rail holed $(7.1.1 (a) (i))$	dered excessive under
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Lower Suspension arm corroded but not seriously weakened (5.	.3.3 (b) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	

CarCheck.co.uk page 2/13



Advice

**Advice** 

SE08OBV

report date: 2024-03-29

**MOT #15** 2020-03-09 10:02 **MOT** test number 720923831926 Result × Failed **MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) Advice Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)) Offside Front Position lamp not working (4.2.1 (a) (ii)) **MAJOR** Entire underside of vehicle is corroded and has a covering of underseal. Advice Advice Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive under floor chassis rail holed (7.1.1 (a) (i))

MOT #14

MOT test number

644735625037

Result

Advice Car is undersealed all over underside

Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #13** 2018-07-06 14:11 **MOT** test number 584729228122 Result Passed **Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i)) Advice Rear subframe corroded Advice Front subframe corroded Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #12** 2018-07-06 08:35

**MOT test number** 442891409654

**Result** X Failed

**DANGEROUS** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Heat shield above catalyst insecure casing risk of fire

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**Advice** Rear subframe corroded

**DANGEROUS** Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front subframe corroded

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**MOT #11** 2017-07-27 10:09

MOT test number 787911764950

Result 

Passed

**Advice** Exhaust heat shield loose

**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #10** 2017-07-27 08:16

**MOT test number** 766156453166

**Result** X Failed

**Advice** Exhaust heat shield loose

**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Fail** Offside Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 4/13



report date: 2024-03-29

**MOT #9** 2016-07-26 10:45

**MOT test number** 217081461178

**Result** ✓ Passed

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #8 2016-07-26 07:46

MOT test number 705118421865

**Result** X Failed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Offside Front position lamp(s) not working (1.1.A.3b)

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

(2.4.G.2)

**Fail** Nearside Registration plate lamp not working (1.1.C.1d)

MOT #7 2015-07-02 11:26

**MOT test number** 328773585109

Result \( \sqrt{Passed} \)

**Advice** Offside rear brake fluctuating, but not excessively (3.7.B.3)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 5/13



report date: 2024-03-29


MOT #6	2015-07-02 09:20
MOT test number	295783685498
Result	<b>X</b> Failed
Advice Offside front brake fluctuating, but not excessively (3.7.B.3)	
Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in (2.4.G.2)	excessive movement
Fail Offside Headlamp aim too low (1.8)	
Fail Nearside Rear coil spring broken (2.4.C.1a)	
Advice Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice Offside rear brake fluctuating, but not excessively (3.7.B.3)	
Fail Nearside Headlamp aim too low (1.8)	
Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in execution (2.4.G.2)	xcessive movement
Fail Rear Upper Stop lamp not working (1.2.1b)	
Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3)	

MOT #5	2014-07-04 10:25
MOT test number	475685484111
Result	✓ Passed
MOT #4	2013-07-27 11:26
MOT test number	528928903293
Result	<b>✓</b> Passed
MOT #3	2012-07-23 09:07
MOT test number	228075902274
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29





CarCheck.co.uk page 7/13



report date: 2024-03-29

### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



SE080BV

report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	biotom
UMMINAI	nisiaiv
OVVIICI	IIIJCOI Y

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full re		Α
***************************************		
***************************************		
************		
	More info	>
Plate changes		
See in this check if this MAZDA had different number plates.		
Number of plates		
Current registration	NK SIE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-07-23
Last registration	2020-08-12
Complete history	See info



Registration #1	2008-07-23	7 mi
Registration #2	2011-07-16	20.229 mi
Registration #3	2011-07-16	20.229 mi
Registration #4	2012-07-23	29.647 mi
Registration #5	2013-07-27	37.167 mi
Registration #6	2014-07-04	43.882 mi
Registration #7	2015-07-02	51.238 mi
Registration #8	2015-07-02	51.238 mi
Registration #9	2016-07-26	58.705 mi
Registration #10	2016-07-26	58.705 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.177 ms

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Safety ratings

NCAP rating	
-------------	--

**Video** <u>see crash video</u>



# Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4490 mm
Wheel base	2640 mm
Kerb weight	1335 kg
Max. allowed weight	1790 kg

## Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 10401773

CarCheck.co.uk page 13/13