



M359BDM

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 100LWB KOMBI
Colour	White
Year of manufacture	1995
Gearbox	-MANUAL

Engine & fuel consumption

Engine capacity	2.496 cc
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-12-03
MOT pass rate	58 %
MOT passed	14
Failed MOT tests	10
Total advice items	35
Total items failed	55

MOT #24	2023-12-04 09:15
MOT test number	718926242447
Result	✓ Passed
Next expiry date	2024-12-03
Advice	Oil leak, but not excessive (8.4.1 (a) (i))



MOT #23	2021-03-23 11:33
MOT test number	699344750139
Result	✗ Failed

**Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Offside Rear Outer Body component corroded and likely to cause injury Wheel Arch Corroded And Sharp (6.2.1 (a) (i))

**Fail** Nearside Front Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Wheel Arch (5.3.6 (a) (i))

**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Brakes Spongy

**Fail** Nearside Front Inner Seat belt anchorage prescribed area strength or continuity significantly reduced Sill To Step (7.1.1 (a) (i))

**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Nearside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Cross Member Near Spring Mount (5.3.6 (a) (i))

**Fail** Offside Front Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected Inner Wheel Arch (5.3.6 (a) (ii))

**Fail** Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sill (5.3.6 (a) (i))

**Fail** Brake load sensing valve seized and ABS not fitted or inoperative (1.1.17 (c) (ii))

**Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

**Fail** Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced Outer sill (7.1.1 (a) (i))

**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Cross Member Near Spring Mount (5.3.6 (a) (i))

**Fail** Offside Front Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected Chassis (5.3.6 (a) (ii))

**Fail** Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sill (5.3.6 (a) (i))

**MOT #22** 2019-06-14 15:21**MOT test number** 313298838320**Result** ✓ Passed**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #21** 2018-06-08 08:39**MOT test number** 393804878233**Result** ✓ Passed**MOT #20** 2017-06-22 15:52**MOT test number** 162545196281**Result** ✓ Passed**Advice** Nearside Rear starting to crack and perish**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #19**

2017-06-15 08:52

**MOT test number**

607616202592

**Result****✗ Failed**

- Fail** Nearside Rear Lower Suspension component mounting prescribed area is excessively corroded outer sill (2.4.A.3)
- Fail** Nearside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Offside Front Upper Suspension component mounting prescribed area is excessively corroded innerwing (2.4.A.3)
- Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)
- Fail** Nearside Front Upper Suspension component mounting prescribed area is excessively corroded innerwing (2.4.A.3)
- Fail** Nearside Front Inner Suspension component mounting prescribed area is excessively corroded step area (2.4.A.3)
- Fail** Offside Rear Lower Suspension component mounting prescribed area is excessively corroded inner sill (2.4.A.3)
- Fail** Offside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Offside Front Lower Suspension component mounting prescribed area is excessively corroded innerwing (2.4.A.3)
- Fail** Nearside Front Lower Suspension component mounting prescribed area is excessively corroded innerwing (2.4.A.3)

**MOT #18**

2016-06-16 13:24

**MOT test number**

640525328274

**Result****✓ Passed**

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Advice** Towbar component slightly corroded (6.6.1)

**MOT #17**

2014-07-29 15:34

**MOT test number**

106000214279

**Result****✓ Passed**

**MOT #16**

2014-07-11 09:48

**MOT test number**

546382294157

**Result****✗ Failed**

- Fail** Nearside Battery insecure (1.9.1)
- Fail** Nearside Rear Body has a sharp edge caused by corrosion (6.1.C.1)
- Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
- Fail** Offside Headlamp insecure (1.7.3)
- Fail** Offside Battery insecure (1.9.1)
- Fail** Offside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Exhaust emits an excessive level of metered smoke for a non-turbo charged engine (7.4.B.3b)
- Fail** Offside Headlamp aim too high (1.8)

**MOT #15**

2013-05-28 17:06

**MOT test number**

935028843154

**Result****✓ Passed**

- Notice** Advise front number plate cracked slightly but still securley mounted

**MOT #14**

2013-05-20 10:24

**MOT test number**

619980043103

**Result****✗ Failed**

- Fail** Offside Rear Suspension spring mounting prescribed area is inadequately repaired (2.4.A.3)
- Notice** Advise front number plate cracked slightly but still securely mounted
- Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Nearside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Nearside Rear Body has a sharp edge caused by corrosion (6.1.C.1)
- Fail** Offside Front Battery insecure (1.9.1)
- Fail** Offside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Offside Rear Body has a sharp edge caused by corrosion (6.1.C.1)

**MOT #13**

2012-04-26 13:25

**MOT test number**

367847512108

**Result****✓ Passed**

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)



**MOT #12** 2012-04-26 09:20**MOT test number** 227507812149**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #11** 2011-04-19 15:13**MOT test number** 967249801178**Result** ✓ Passed**Notice** Offside front tyre wearing on inner and outer edge**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #10** 2010-05-18 16:31**MOT test number** 171268730159**Result** ✓ Passed**MOT #9** 2010-05-17 13:04**MOT test number** 233957930427**Result** ✗ Failed**Notice** Battery insecure**Fail** Nearside Front Subframe mounting prescribed area is excessively corroded (2.4.A.3)**Notice** O/s/f and o/s/r tyres wearing low**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)

**MOT #8**

2010-04-06 11:02

**MOT test number**

732896090035

**Result**

✗ Failed

- Fail** Offside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)
- Fail** Exhaust emits an excessive level of metered smoke for a non-turbo charged engine (7.4.B.3b)
- Fail** Offside Front Lower Seat belt anchorage prescribed area is excessively corroded (5.2.6)
- Fail** Offside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)

**MOT #7**

2009-03-05 14:40

**MOT test number**

892074669067

**Result**

✓ Passed

- Advice** Offside Rear Vehicle structure has slight corrosion (6.1.A.1)

**MOT #6**

2009-03-03 10:18

**MOT test number**

332622269061

**Result**

✗ Failed

- Fail** Offside Front Subframe mounting prescribed area is excessively corroded (2.4.A.3)
- Advice** Offside Rear Vehicle structure has slight corrosion (6.1.A.1)
- Fail** Nearside Side repeater not working (1.4.A.2c)
- Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)

**MOT #5**

2008-02-05 12:52

**MOT test number**

104966238407

**Result**

✓ Passed

**MOT #4** 2007-05-23 12:03**MOT test number** 202553347407**Result** Passed**MOT #3** 2007-04-28 11:26**MOT test number** 633828417109**Result** Failed**Fail** Nearside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)**Fail** Offside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)**MOT #2** 2006-03-06 13:52**MOT test number** 261205566085**Result** Passed**MOT #1** 2006-03-02 15:08**MOT test number** 121021466443**Result** Failed**Fail** Offside Front Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)**Fail** Front brake disc excessively pitted (3.5.1h)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 December 2024

✓  
**MOT**

**Expires:**  
3 December 2024

Tax status		Valid until 1 December
Days left		215
MOT expiry date		3 December 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	1995-06-19
Last registration	2023-12-04
Complete history	<a href="#">See info</a>



Registration #1	1995-06-19	28 mi
Registration #2	2006-03-02	55.002 mi
Registration #3	2006-03-06	55.027 mi
Registration #4	2007-04-28	61.376 mi
Registration #5	2007-05-23	61.645 mi
Registration #6	2008-02-05	62.969 mi
Registration #7	2009-03-03	67.926 mi
Registration #8	2009-03-05	67.926 mi
Registration #9	2010-04-06	70.976 mi
Registration #10	2010-05-17	70.981 mi
Registration #11	2010-05-18	70.981 mi
Registration #12	2011-04-19	73.754 mi
Registration #13	2012-04-26	75.863 mi
Registration #14	2013-05-01	76.377 mi
Registration #15	2014-05-01	76.377 mi
Registration #16	2015-05-01	76.377 mi
Registration #17	2016-05-01	76.377 mi
Registration #18	2017-05-01	76.377 mi
Registration #19	2018-05-01	76.377 mi
Registration #20	2019-05-01	76.377 mi
Registration #21	2020-05-01	76.377 mi
Registration #22	2021-05-01	76.377 mi
Registration #23	2022-05-01	76.377 mi
Registration #24	2023-05-01	76.377 mi
Registration #25	2023-12-04	76.377 mi





Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Number of axles	2
Engine number	RJ44633