





General information

| Make | VOLKSWAGEN |
|---------------------|----------------|
| Model | LUPO E |
| Colour | Green |
| Year of manufacture | 2001 |
| Top speed | 106 mph |
| 0 - 60 mph | 12.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 75 BHP |
|-------------------------|---------------------|
| Max. torque | 124 Nm at 3.800 rpm |
| Engine capacity | 1.390 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 32.5 mpg |
| Consumption extra urban | 57.6 mpg |
| Consumption combined | 44.8 mpg |
| CO2 emission | 149 g/km |
| CO2 label | F |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-07-06 |
| Pictures | 1 |
| Listing price | View report |
| | |



source: autotrader.co.uk





MOT history

| MOT expiry date | 2023-03-11 |
|--------------------|------------|
| MOT pass rate | 71 % |
| MOT passed | 15 |
| Failed MOT tests | 6 |
| Total advice items | 69 |
| Total items failed | 20 |

| MOT #21 | 2023-02-08 09:58 |
|---|------------------|
| MOT test number | 298458334147 |
| Result | 🗙 Failed |
| Advice Rear axle corroded | |
| Advice Front Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Fail Emissions unable to be completed due to condition of exhaust system (8.2.1.2 (d)) | |
| Advice Rear service brake low readings on offside and nearside | |
| Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) | |
| Fail Exhaust has a major leak of exhaust gases (6.1.2 (a)) | |

| MOT #20 | | 2022-02-28 10:49 |
|----------|--|------------------|
| MOT test | number | 322834717933 |
| Result | | ✓ Passed |
| Advice | Central Exhaust has a minor leak of exhaust gases (6.1.2 (a)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |





| MOT #19 | | 2021-03-01 10:48 |
|--------------------------|---|--------------------|
| MOT test | number | 544267296755 |
| Result | | ✓ Passed |
| Minor | Nearside Front Obligatory mirror slightly loose (3.3 (b) (i)) | |
| Advice | Nearside Front Coil spring corroded (5.3.1 (b) (i)) | |
| Advice | Offside Front Non obligatory mirror damaged | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice (5.3.4 (a) | Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excess (i)) | sive movement |
| Advice | Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) | |
| Advice | Rear Coil spring corroded both rear (5.3.1 (b) (i)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice (a) (i)) | Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessiv | ve movement (5.3.4 |





| MOT #18 2021-02-23 10:04 |
|--|
| MOT test number 685803804334 |
| Result X Failed |
| Advice Nearside Front Coil spring corroded (5.3.1 (b) (i)) |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) |
| Advice (a) (i)) Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 |
| Fail Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a)) |
| Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) |
| Minor Nearside Front Obligatory mirror slightly loose (3.3 (b) (i)) |
| Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) |
| Advice Offside Front Non obligatory mirror damaged |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice Rear Coil spring corroded both rear (5.3.1 (b) (i)) |
| Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) |
| Fail Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b)) |
| Advice Exhaust has a minor leak of exhaust gases also corroded (6.1.2 (a)) |



Advice

Rear axle corroded



MOT #17 2020-03-12 15:40 MOT test number 230502037424 Result ✓ Passed Advice Coil spring corroded x4 springs (5.3.1 (b) (i))

| Advice | Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i)) |
|----------------------------|--|
| | |
| MOT #16 | 2019-03-07 14:42 |
| MOT test | number 402674670790 |
| Result | ✓ Passed |
| Advice | Sub frame corroded |
| Advice (i)) | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) |
| Advice | Rear wiper broken |
| Advice (5.3.4 (a) (| Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement i)) |
| Advice | Rear axle corroded |
| Advice (a) (i)) | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |
| Advice | Offside wing mirror surround missing |
| Advice (a) (i)) | Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 |





| MOT #15 | | 2017-12-08 12:05 |
|--------------------|--|------------------------|
| MOT test | number | 679907423362 |
| Result | | ✓ Passed |
| Advice | Offside door mirror cover missing | |
| Advice | Front registration plate deteriorated but not likely to be misread (6.3.1d) | |
| Advice movement | Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not it (2.4.G.2) | resulting in excessive |
| Advice | Engine light on | |
| Advice | Nearside door mirror has temporary repair | |
| Advice movemen | Nearside Front Lower Suspension arm rubber bush deteriorated but not re t (2.4.G.2) | sulting in excessive |
| Advice movemen | Offside Front Anti-roll bar linkage rubber bush deteriorated but not resultir t (2.4.G.2) | ng in excessive |
| | | |

| MOT #14 | 2016-11-08 17:09 |
|--|--|
| MOT test number | 127404262738 |
| Result | ✓ Passed |
| Advice Nearside front wing mirror damaged - se | ecured using tape |
| Advice Offside front wing mirror casing damage | ed/missing |
| Advice Nearside Front Lower Suspension arm removement (2.4.G.2) | ubber bush deteriorated but not resulting in excessive |





| MOT #13 2016-03-29 10:0 |
|---|
| MOT test number 39177841733 |
| Result × Failer |
| Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2) |
| Advice Engine management lamp on indicating a fault |
| Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |
| Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3) |
| Advice Rear and centre exhaust sections corroded |
| Fail Offside Front Direction indicators incorrect colour (1.4.A.2f) |
| Advice Offside wing mirror casing damaged/missing |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice Front Exhaust has a minor leak of exhaust gases flexi (7.1.2) |
| Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3) |
| Advice Front and rear exhaust hangers corroded and broken |
| Fail Nearside Front Direction indicators incorrect colour (1.4.A.2f) |
| Advice Nearside wing mirror damaged - secured using tape |
| Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| Advice Nearside Rear tyre worn - tread depth 3mm |
| |

| MOT #12 | | 2015-02-25 16:23 |
|----------|--|------------------|
| MOT test | number | 789556055095 |
| Result | | ✓ Passed |
| Notice | O/s/f door mirror cover is missing | |
| Advice | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | |





| MOT #11 | 2015-02-25 16:23 |
|---|------------------|
| MOT test number | 159526755447 |
| Result | 🗙 Failed |
| Pass with rectification Front Headlamp aim too high (1.8) | |
| Notice O/s/f door mirror cover is missing | |
| Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | |
| | |
| MOT #10 | 2013-07-17 14:37 |

| MOT test number | 207728693103 |
|-----------------|--------------|
| Result | ✓ Passed |

| MOT #9 | | 2013-07-17 10:01 |
|---|---|------------------|
| MOT test number | | 398988493119 |
| Result | | 🗙 Failed |
| Pass with rectification | Offside Front Windscreen wiper blade insecure (8.2.2) | |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | | |
| Pass with rectification | Nearside Front Headlamp aim too high (1.8) | |

| MOT #8 | | 2012-07-03 09:18 |
|----------|--|------------------|
| MOT test | number | 289365582497 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Notice | Rear exhaust deteriorated | |





| MOT #7 | 2012-07-03 09:18 | |
|---|---|--|
| MOT test number | 278435782149 | |
| Result | × Failed | |
| Pass with rectification | Offside Windscreen washer provides insufficient washer liquid (8.2.3) | |
| Notice Rear exhaust deteriorated | | |
| Pass with rectification | Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) | |
| Pass with rectification | Nearside Windscreen washer provides insufficient washer liquid (8.2.3) | |
| Pass with rectification | Nearside Headlamp aim too low (1.8) | |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | | |

| МОТ #6 | 2011-07-11 13:49 |
|-----------------|------------------|
| MOT test number | 636442991107 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2010-07-12 11:10 |
| MOT test number | 280583290438 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2009-07-09 11:20 |
| MOT test number | 662530799111 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2008-06-28 09:48 |
| MOT test number | 602350888163 |
| Result | ✓ Passed |





| MOT #2 | 2007-06-25 15:38 |
|---|------------------|
| MOT test number | 900966677110 |
| Result | ✓ Passed |
| Advice Front brake disc slightly pitted (3.5.1h) | |
| MOT #1 | 2006-06-28 16:22 |
| MOT test number | 421319476184 |
| Result | ✓ Passed |
| Notice All 4tyres slight cracking onside walls | |



Tax & MOT check

| X Untaxed Tax expired: 15 February 2023 | X MOT Expired: 11 March 2023 |
|--|---|
| Tax status | Expired at 15 February 2023 |
| Days left | 440 days too late |
| MOT expiry date | 11 March 2023 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 48 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E CAT ON |
| Date | * |
| Category | AMP |
| Туре | |

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10 700 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And and a second s | |
|--|-------------|
| ********** | |
| ********* | |
| | |
| | |
| ********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| | |
| Plate since | |





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 21 |
| First mileage registration | 2001-06-29 |
| Last registration | 2023-02-08 |
| Complete history | <u>See info</u> |



| Registration #1 | 2001-06-29 | 14 mi |
|------------------|------------|------------|
| Registration #2 | 2006-06-28 | 4.096 mi |
| Registration #3 | 2007-06-25 | 4.523 mi |
| Registration #4 | 2008-06-28 | 6.917 mi |
| Registration #5 | 2009-07-09 | 15.023 mi |
| Registration #6 | 2010-07-12 | 21.848 mi |
| Registration #7 | 2011-07-11 | 26.747 mi |
| Registration #8 | 2012-07-03 | 29.152 mi |
| Registration #9 | 2013-07-17 | 32.586 mi |
| Registration #10 | 2013-07-17 | 32.591 mi |
| Registration #11 | 2015-02-25 | 54.523 mi |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.777 esi |
| Registration #14 | | 11.777 est |
| Registration #15 | | 11.777 esi |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.777 esi |
| Registration #18 | | 11.777 est |
| Registration #19 | | 11.777 esi |
| Registration #20 | | 11.777 est |
| Registration #21 | | 11.227 esi |

More info >





Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 60567 | |
| 50569 | |

Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|------------------------|-----------------------|
| Width | 1860 mm |
| Height | 1459 mm |
| Length | 3527 mm |
| Wheel base | 2321 mm |
| Additional information | |
| Fuel tank capacity | 34 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |

2

AUA010470

Number of axles

Engine number

CarCheck.co.uk