





### General information

Make	VOLKSWAGEN
Model	SHARAN CARAT TDI (130BHP)
Colour	Silver
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	130 BHP
Max. torque	310 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg





# Internet history

Entry	1
Date	

Pictures

2021-07-16

25

Listing price

View report



source: cargurus.co.uk





MOT history





MOT #23	2022-08-22 09:21
MOT test number	716575609994
Result	🗙 Failed

<b>Fail</b> Central Exhaust has a major leak of exhaust gases (6.1.2 (a))
FailOffside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
<b>Fail</b> Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Advice Oil leak, but not excessive (8.4.1 (a) (i))
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Fail</b> Offside Front Inner Steering linkage ball joint ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Fail</b> Nearside Front Brake disc significantly and obviously worn inner surface (1.1.14 (a) (i))
<b>Fail</b> Nearside Front Inner Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
<b>Fail</b> Nearside Front Inner Steering linkage ball joint ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
<b>Fail</b> Nearside Front Inner Steering linkage ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))
<b>Fail</b> Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))



MOT #22		2021-07-19 14:10
MOT test	number	716435947404
Result		✓ Passed
MOT #21		2020-10-15 11:59
MOT test	number	648231129109
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (	c))
Advice	Rear Shock absorbers has a slightly worn bush Both (5.3.2 (c))	
Minor	Offside Front Brake hose slightly damaged (1.1.12 (b) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2 mm. (5.2.3 (e))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11	L (c))
Advice	Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))	
Minor	Nearside Front Brake hose slightly damaged (1.1.12 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2 mm. (5.2.3 (e))	
Advice	Offside Front McPherson strut has slight movement at the upper attachment.	



HD53EYW report date: 2024-03-29

MOT #20 2020-10-15 1	10:04
<b>MOT test number</b> 69382495	8338
Result X F	ailed
Advice Rear Shock absorbers has a slightly worn bush Both (5.3.2 (c))	
Advice Offside Front Tyre worn close to legal limit/worn on edge 2 mm. (5.2.3 (e))	
Fail (ii))Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4	(b)
Advice Offside Front McPherson strut has slight movement at the upper attachment.	
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Minor Offside Front Brake hose slightly damaged (1.1.12 (b) (i))	
Advice Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge 2 mm. (5.2.3 (e))	
Fail (b) (ii))Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.	.4
FailOffside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Minor Nearside Front Brake hose slightly damaged (1.1.12 (b) (i))	
Advice Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	





MOT #19		2019-11-12 17:56
MOT test	number	509311422339
Result		✓ Passed
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c	))
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4	4 (b) (i))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #18		2018-11-20 12:22
MOT test	number	823750230200
Result		✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (	1.1.14 (a) (ii))
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effec	ct (5.3.2 (b))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11)	(c))





MOT #17	2018-11-19 16:17	
MOT test number	542722096236	
Result	🗙 Failed	
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1	.1.11 (c))	
Fail Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt		
(5.3.4 (b) (ii))		
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weak	ened (1.1.14 (a) (ii))	
Advice Offside Front Brake pipe corroded, covered in grease or other material (2	1.1.11 (c))	
<b>Fail</b> Offside Rear Parking brake inoperative on one side (1.4.1 (a))		
Advice Nearside Rear Shock absorbers light misting of oil or has limited dampin	g effect (5.3.2 (b))	
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))	

MOT #16		2017-11-01 15:28
MOT test	number	945968566976
Result		✓ Passed
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Brake pipe slightly corroded Both front at calipers (3.6.B.2c)	

MOT #15	2017-10-31 08:59
MOT test number	212354232891
Result	🗙 Failed
<b>Fail</b> Nearside rear parking brake recording little or no effort (3.7.B.6a)	
Advice Brake pipe slightly corroded Both front at calipers (3.6.B.2c)	
Fail Nearside Rear wheel bearing rough when rotated (2.6.1)	
Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Fail Parking brake: efficiency below requirements (3.7.B.7)	





MOT #14	2016-10-14 10:03
MOT test number	806156587741
Result	✓ Passed
MOT #13	2015-10-01 12:49
MOT test number	440803545432
Result	✓ Passed
MOT #12	2014-10-10 13:35
MOT test number	786783484205
Result	✓ Passed
MOT #11	2013-11-01 11:48
MOT test number	908535203366
Result	✓ Passed
Advice Windscreen has damage to an area less that	n a 10mm circle within zone 'A' (8.3.1a)
Advice Front brake disc worn, pitted or scored, but	not seriously weakened (3.5.1i)
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Offside Rear Shock absorber has a light mist	ting of oil (2.7.3)
Advice Rear brake disc worn, pitted or scored, but r	not seriously weakened (3.5.1i)

MOT #10	2012-12-14 07:55
MOT test number	967769042338
Result	✓ Passed





MOT #9	2012-12-06 11:48
MOT test number	647751542335
Result	🗙 Failed
<b>Fail</b> Nearside Inner Front constant velocity joint gaiter deteriorated to the extent that i prevents the ingress of dirt etc (2.5.C.1a)	t no longer
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
<b>Fail</b> Offside Inner Front constant velocity joint gaiter deteriorated to the extent that it is the ingress of dirt etc (2.5.C.1a)	no longer prevents
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #8	2011-12-17 08:07

MOT test	number 725571851300
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Both inner cv gaitors split
Advice	Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)



MOT #7	2011-12-14 08:58
MOT test number	725518541376
Result	🗙 Failed
Fail Offside Rear Passenger's seat insecure (6.2.A.1)	
<b>Fail</b> Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3	3.1d)
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Both inner cv gaitors split	
Fail Nearside Headlamp aim too high (1.8)	
Fail Offside Rear An item not tested (Manual)	
Advice Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a	)

MOT #6		2010-12-17 12:53
MOT test	number	324871350364
Result		Passed
Notice	N/s and o/s driveshaft inner joint gaiters split	
Notice	Slight damage to front number plate	

MOT #5		2010-12-17 12:53
MOT test number		733161750328
Result		× Failed
Pass with rectification	Offside Headlamp aim too high (1.8)	
Notice N/s and o/s driveshaft inner joint gaiters split		
Notice Slight damage t	o front number plate	

**HD53EYW** 

report date: 2024-03-29





MOT #4	2009-12-15	14:01
MOT test	<b>number</b> 47469994	49458
Result	✓ P	assed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	
Advice	Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)	

MOT #3		2008-12-10 10:41
MOT test r	number	472435248405
Result		✓ Passed
Notice	O/s sill damaged	
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)	

MOT #2	2007-12-08 10:14
MOT test number	380162047357
Result	✓ Passed
<b>Notice</b> Child seat fitted not allowing full inspection of adult belt	

MOT #1	2006-12-15 11:47
MOT test number	940199946371
Result	✓ Passed





#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damaye 2	E CAT D
Date	*
Category	AMPL
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

***********	
********	
and the second sec	
***********	
*********	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-12-19
Last registration	2022-08-22
Complete history	See info



Registration #1	2003-12-19	7 mi
Registration #2	2006-12-15	29.313 mi
Registration #3	2007-12-08	42.888 mi
Registration #4	2008-12-10	54.234 mi
Registration #5	2009-12-15	67.692 mi
Registration #6	2010-12-17	80.792 mi
Registration #7	2011-12-14	91.560 mi
Registration #8	2011-12-17	91.600 mi
Registration #9	2012-12-06	103.943 mi
Registration #10	2012-12-14	104.125 mi
Registration #11	2013-11-01	114.117 mi
Registration #12	2014-10-10	129.706 mi
Registration #13		11.777 esi
Registration #14		10.207 mil
Registration #15		11.227 esi
Registration #15 Registration #16		00.000 em
		00.000 est 0.000 est 00.000 est
Registration #16		00.000 est 0.000 est 00.000 est 00.000 est
Registration #16 Registration #17		00.000 ees 0.000 ees 00.000 ees 00.000 ees 00.000 ees
Registration #16 Registration #17 Registration #18		00.000 est 0.000 est 00.000 est 00.000 est 00.000 est 00.000 est
Registration #16 Registration #17 Registration #18 Registration #19		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		10.000 esi 0.000 esi 0.000 esi 0.000 esi 0.000 esi 0.000 esi 0.000 esi 0.000 esi
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		10.000 est 10.000







### Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

Number of doors

Number of axles

CarCheck.co.uk

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1810 mm
Height	1730 mm
Length	4634 mm
Wheel base	2841 mm
Kerb weight	1928 kg
Additional information	
Fuel tank capacity	70 I
Fuel delivery	Direct Injection

5 2

ASZ313222