





report date: 2024-03-28

General information

Make	FORD
Model	MONDEO ST TDCI
Colour	Black
Year of manufacture	2006
Top speed	137 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	46.3 mpg
CO2 emission	161 g/km
CO2 label	G



CarCheck.co.uk page 1/13



AK56ZKW report date: 2024-03-28

MOT history	M	OT	history
-------------	---	----	---------

MOT expiry date	2021-05-26
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	55
Total items failed	8

MOT #15		2020-05-27 09:37
MOT test	number	269446082007
Result		✓ Passed
Next expi	ry date	2021-05-26
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Fuel Pipe/s corroded	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Minor	Brake pipe inadequately clipped or supported (1.1.11 (d) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 2/13



Advice

Advice

AK56ZKW

report date: 2024-03-28

MOT #14 2020-05-20 12:47

MOT test number 671587924997

Result **X** Failed **Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i)) Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Front Lower Anti-roll bar ball joint excessively worn (5.3.4 (a) (i)) Fail Minor Brake pipe inadequately clipped or supported (1.1.11 (d) (i)) Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Fuel Pipe/s corroded Advice Offside Front Coil spring corroded (5.3.1 (b) (i)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13 2019-02-09 10:57

MOT test number 290409813622

Result ✓ Passed **Advice** Fuel Pipe/s corroded Exhaust has a minor leak of exhaust gases (6.1.2 (a)) Advice Advice Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii)) Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i)) Advice Nearside Front Coil spring corroded (5.3.1 (b) (i)) Advice Driver's view Items removed from driver's view prior to test (3.1 (a) (ii)) Minor Offside Rear Brake pipe inadequately clipped or supported (1.1.11 (d) (i)) **Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii)) Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) Advice Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i)) Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #12 2019-02-09 10:27

MOT test number 243549575893

Result X Failed

Fail Offside Front Position lamp not working (4.2.1 (a))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Minor Offside Rear Brake pipe inadequately clipped or supported (1.1.11 (d) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Tyre slightly damaged (5.2.3 (d) (ii))

Advice Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Fuel Pipe/s corroded

Fail Nearside Front Position lamp not working (4.2.1 (a))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Nearside Rear Position lamp not working (4.2.1 (a))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

CarCheck.co.uk page 5/13



Result

MOT test number

AK56ZKW

report date: 2024-03-28

Passed

928206862207

MOT #11	2018-02-19 16:02

MOT test number 713858038225

MOT #10 2017-03-30 14:25

MOT test number 794691114752

Result ✓ Passed

Advice Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

 MOT #9
 2016-04-06 12:33

 MOT test number
 302462718209

 MOT #8
 2015-04-14 16:45

 MOT test number
 977454305143

 MOT #7
 2014-09-27 09:46

 MOT test number
 789080974208

Result

Passed

MOT #6 2013-09-28 08:34 MOT test number 356011673264

Result

Passed

MOT #5 2012-09-22 07:50

CarCheck.co.uk page 6/13



MOT #2

MOT test number

AK56ZKW

report date: 2024-03-28

2010-09-18 08:50

181661360222

MOT #4	2011-10-12 10:24
MOT test number	698555981259
Result	✓ Passed
MOT #3	2011-10-08 08:57
MOT test number	438881881243
Result	× Failed
Fail Offside Front coil spring incomplete (2.4.C.1a)	

Result	✓ Passed
MOT #1	2009-10-03 09:41
MOT test number	162086779200
Result	✓ Passed

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	OK OK
Plate since	
Current registration	SK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-10-16
Last registration	2020-05-27
Complete history	See info



Registration #1	2006-10-16	12 mi
Registration #2	2009-10-03	21.269 mi
Registration #3	2010-09-18	28.507 mi
Registration #4	2011-10-08	36.379 mi
Registration #5	2011-10-12	36.463 mi
Registration #6	2012-09-22	43.759 mi
Registration #7	2013-09-28	52.215 mi
Registration #8	2014-09-27	57.491 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		0.00 44
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 12/13



AK56ZKW report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1958 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Kerb weight	1484 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	58 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	e 13/13

Number of axles2Engine number6U31174