




General information

Make	MASERATI
Model	COUPE V8 GRANSPORT
Colour	Blue
Year of manufacture	2005
Top speed	180 mph
0 - 60 mph	4.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	395 BHP
Max. torque	452 Nm at 4.500 rpm
Engine capacity	4.244 cc
Cylinders	8
Fuel type	Petrol
Consumption city	10.8 mpg
Consumption extra urban	22.6 mpg
Consumption combined	16.1 mpg
CO2 emission	400 g/km
CO2 label	M







Internet history

Entry 2

Date	2021-07-19
Pictures	31
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-05-26
Pictures	1
Listing price	View report



source: autoonline.co.uk

**MOT history**

MOT expiry date	2022-11-17
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	19
Total items failed	8

MOT #16 2021-11-18 12:21**MOT test number** 154536151715**Result** ✓ Passed**Next expiry date** 2022-11-17

Minor Offside Front Windscreen damaged but not adversely affecting driver's view Stone chip to driver side of windscreen (3.2 (a) (i))

MOT #15 2019-12-17 12:12**MOT test number** 629445547589**Result** ✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14** 2019-12-17 10:09**MOT test number** 266318404381**Result** ✗ Failed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2018-12-06 10:03**MOT test number** 342511993182**Result** ✓ Passed**MOT #12** 2017-06-17 13:34**MOT test number** 269681551870**Result** ✓ Passed**Advice** Front coil spring corroded both (2.4.C.1b)**MOT #11** 2016-06-12 12:30**MOT test number** 221870686389**Result** ✓ Passed**MOT #10** 2015-06-20 11:55**MOT test number** 249521675458**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #9** 2014-06-14 14:30**MOT test number** 587385964179**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #8** 2013-06-06 08:58**MOT test number** 178837953135**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2013-06-03 16:11**MOT test number** 407344253143**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Steering rack gaiter split (2.2.D.2d)**MOT #6** 2012-06-23 09:47**MOT test number** 238615472112**Result** ✓ Passed

**MOT #5** 2012-06-22 14:38**MOT test number** 136064572154**Result** ✓ Passed**Notice** Slight vertical movement in steering column**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2010-10-28 15:30**MOT test number** 680381400343**Result** ✓ Passed**MOT #3** 2009-10-19 18:20**MOT test number** 104722999230**Result** ✓ Passed**MOT #2** 2008-10-21 14:37**MOT test number** 493225598207**Result** ✓ Passed**MOT #1** 2008-10-20 15:10**MOT test number** 560984698205**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)



Damage history


Check the damage history for this MASERATI. See if, where and when this MASERATI had damage and the car repair costs. We also check if this MASERATI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MASERATI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

[More info](#) >



Owner history

For how long did the current and previous owner(s) have this MASERATI? How many owners did this MASERATI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this MASERATI had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-06-29
Current registration	 XXXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this MASERATI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MASERATI has been settled.

If not, and you buy this MASERATI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MASERATI is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-09-05
Last registration	2021-11-18
Complete history	See info



Registration #1	2005-09-05	28 mi
Registration #2	2008-10-20	19.743 mi
Registration #3	2008-10-21	19.750 mi
Registration #4	2009-10-19	23.486 mi
Registration #5	2010-10-28	24.550 mi
Registration #6	2012-06-22	25.486 mi
Registration #7	2012-06-23	25.570 mi
Registration #8	2013-06-03	29.511 mi
Registration #9	2013-06-06	29.511 mi
Registration #10	2014-06-14	31.645 mi
Registration #11	2015-06-22	35.277 mi
Registration #12	2016-06-22	35.277 mi
Registration #13	2017-06-22	35.277 mi
Registration #14	2018-06-22	35.277 mi
Registration #15	2019-06-22	35.277 mi
Registration #16	2020-06-22	35.277 mi
Registration #17	2021-06-22	35.277 mi
Registration #18	2021-11-18	35.277 mi
Registration #19	2021-11-18	35.277 mi

[More info >](#)

**Dimensions & weight**

Width	1822 mm
Height	1295 mm
Length	4523 mm
Wheel base	2660 mm
Kerb weight	1680 kg

Additional information

Fuel tank capacity	88 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Engine number	97975