





General information

| Make | CITROEN |
|---------------------|----------------|
| Model | C2 HDI VTR |
| Colour | Silver |
| Year of manufacture | 2009 |
| Top speed | 103 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 67 BHP |
|-------------------------|---------------------|
| Max. torque | 160 Nm at 2.000 rpm |
| Engine capacity | 1.398 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 76.4 mpg |
| Consumption combined | 65.7 mpg |
| CO2 emission | 113 g/km |
| CO2 label | С |





Internet history


| Ent | try | 1 |
|-----|-----|---|
| | | |

Date Pictures 2022-01-25

10

Listing price

View report



source: autotrader.co.uk



MOT history

| MOT expiry date | 2025-02-12 |
|--------------------|------------|
| MOT pass rate | 60 % |
| MOT passed | 12 |
| Failed MOT tests | 8 |
| Total advice items | 48 |
| Total items failed | 8 |

| MOT #20 | | 2024-02-13 12:18 |
|------------------------|---|------------------|
| MOT test | number | 915888528303 |
| Result | | ✓ Passed |
| Next expi | iry date | 2025-02-12 |
| Advice | Rear Direction indicator slightly discoloured $x2$ (4.4.3 (a)) | |
| Advice | X2 rear bump stops missing | |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice (a) (i)) | Nearside Front Macpherson strut pin or bush worn but not resulting in excessive | movement (5.3.4 |
| Advice | Nearside Rear Service brake binding but not excessively (1.2.1 (f)) | |





| MOT #19 | 2024-02-12 11:58 |
|------------------------|--|
| MOT test | number 718568501030 |
| Result | × Failed |
| MAJOR | Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) |
| Advice (a) (i)) | Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 |
| MAJOR ingress of | Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the dirt (6.1.7 (g) (ii)) |
| Advice | Nearside Rear Service brake binding but not excessively (1.2.1 (f)) |
| Advice | X2 rear bump stops missing |
| Advice | Rear Direction indicator slightly discoloured x2 (4.4.3 (a)) |
| MAJOR | Offside Front Macpherson strut pin or bush excessively worn (5.3.4 (a) (i)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |
| MAJOR | Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i)) |

| MOT #18 | | 2023-01-06 14:15 |
|-------------|---|------------------|
| MOT test nu | ımber | 526333287025 |
| Result | | ✓ Passed |
| Advice | Rear Coil spring corroded both sides (5.3.1 (b) (i)) | |
| Advice | Rear Service brake binding but not excessively both sides (1.2.1 (f)) | |
| | | |

| MOT #17 | 2023-01-06 14:15 | |
|--|------------------|--|
| MOT test number | 325490135808 | |
| Result | 🗙 Failed | |
| Advice Rear Coil spring corroded both sides (5.3.1 (b) (i)) | | |
| Advice Rear Service brake binding but not excessively both sides (1.2.1 (f)) | | |
| Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) | | |



| SB59NKT | | |
|-------------------------|--|--|
| report date: 2024-03-28 | | |

| MOT #16 | | 2022-02-12 14:11 |
|----------------------------|---|------------------------|
| MOT test | number | 596135624348 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) | |
| Advice (5.3.4 (a) (| Offside Front Inner Suspension arm pin or bush worn but not resulting in i)) | excessive movement |
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weake | ened (1.1.14 (a) (ii)) |
| Advice | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice (5.3.4 (a) (| Nearside Front Inner Suspension arm pin or bush worn but not resulting i i)) | in excessive movement |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weaken | ed (1.1.14 (a) (ii)) |
| Advice | Surface corrosion on the front subframe. | |

| MOT #15 | 2021-01-09 12:19 |
|-----------------|------------------|
| MOT test number | 819646282866 |
| Result | ✓ Passed |
| | |
| MOT #14 | 2019-07-13 15:08 |
| MOT test number | 915684334643 |
| Result | ✓ Passed |
| | |
| MOT #13 | 2019-07-13 11:10 |

| MOT test number | 763188206537 |
|-----------------|--------------|
| Result | × Failed |

MAJOR Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))





| MOT #12 | | 2018-06-18 16:30 | |
|-----------------------------|---|---------------------------|--|
| MOT test | number | 452511323833 | |
| Result | | ✓ Passed | |
| Advice | Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii)) | | |
| MOT #11 | | 2018-06-18 09:01 | |
| MOT test | number | 378355657520 | |
| Result | | 🗙 Failed | |
| MAJOR play in bal | MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt also play in ball joint (5.3.4 (b) (ii)) | | |
| Advice | Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e)) | | |
| MAJOR (ii)) | Offside Front Suspension arm ball joint dust cover no longer prevents the in | ngress of dirt (5.3.4 (b) | |
| Minor | Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated | (5.3.4 (b) (i)) | |
| Advice | Rear Coil spring corroded both (5.3.1 (b) (i)) | | |
| Advice | Rear All direction indicators slightly discoloured both sides (4.4.3 (a)) | | |
| Advice | Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii)) | | |
| MAJOR ingress of | Offside Front Drive shaft joint constant velocity boot split or insecure, no lo f dirt (6.1.7 (g) (ii)) | onger prevents the | |
| MAJOR | Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i)) | | |
| Minor | Offside Front Brake hose slightly damaged insecure (1.1.12 (b) (i)) | | |

| MOT #10 | 2017-07-18 15:55 |
|-----------------|------------------|
| MOT test number | 904246378058 |
| Result | ✓ Passed |
| | |
| МОТ #9 | 2016-12-01 09:23 |
| MOT test number | 221720618265 |
| Result | ✓ Passed |



SB59NKT report date: 2024-03-28

| MOT #8 | 3 | 2016-11-30 16:20 |
|--------|--|------------------|
| MOT te | st number | 578334395403 |
| Result | | 🗙 Failed |
| Fail | Offside Front Shock absorber has a serious fluid leak (2.7.3) | |
| Fail | Offside Headlamp aim beam image obviously incorrect (1.8.A.1b) | |

| MOT #7 | 2015-11-26 15:33 |
|---|------------------|
| MOT test number | 649305676701 |
| Result | 🗸 Passed |
| Advice Both rear tyres sidewalls perished | |

| МОТ #6 | 2015-11-25 09:13 |
|---|------------------|
| MOT test number | 598335936638 |
| Result | 🗙 Failed |
| FailFront Exhaust has a major leak of exhaust gases (7.1.2)AdviceBoth rear tyres sidewalls perished | |
| Fail Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2) | |

| MOT #5 | | 2014-12-05 12:56 |
|----------|--|------------------|
| MOT test | number | 829119134356 |
| Result | | ✓ Passed |
| Advice | Exhaust has a minor leak of exhaust gases (7.1.2) | |
| Advice | Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2) | |



SB59NKT report date: 2024-03-28

| MOT #4 | 2014-12-05 12:56 | |
|---|--|--|
| MOT test number | 636169134344 | |
| Result | × Failed | |
| Advice Exhaust has a m | inor leak of exhaust gases (7.1.2) | |
| Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively | | |
| (8.2.2) | | |
| Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2) | | |
| Pass with rectification | Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) | |

| МОТ #3 | 2013-12-11 13:46 |
|---|------------------|
| MOT test number | 965175243383 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #2 | | 2013-11-27 15:57 |
|---|--|------------------|
| MOT test I | number | 638201233343 |
| Result | | 🗙 Failed |
| Fail Offside Front Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a) | | |
| Notice | O/s/f inner brake disc excessivly scored and corroded | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| | | |

| MOT #1 | 2012-11-26 12:56 |
|-----------------|------------------|
| MOT test number | 896161532373 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed Tax due: 1 March 2025 | ✓ MOT Expires: 12 February 2025 |
|--|--|
| Tax status | Valid until 1 March |
| Days left | 305 |
| MOT expiry date | 12 February 2025 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| | E Store |
| Date | 1. E |
| Category | amt |
| Туре | |

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| *********** | |
| ******** | |
| ****** | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 21 |
| First mileage registration | 2009-12-21 |
| Last registration | 2024-02-13 |
| Complete history | See info |



| 2009-12-21 | 17 mi |
|------------|--|
| 2012-11-26 | 14.800 mi |
| 2013-11-27 | 21.085 mi |
| 2013-12-11 | 21.085 mi |
| 2014-12-05 | 24.003 mi |
| 2015-11-25 | 27.301 mi |
| 2015-11-26 | 27.301 mi |
| 2016-11-30 | 29.068 mi |
| 2016-12-01 | 29.068 mi |
| 2017-07-18 | 30.191 mi |
| 2018-06-18 | 42.466 mi |
| | 11.777 esi |
| | 11.777 esi |
| | |
| | 11.777 est |
| | 11.777 es |
| | 01,000 est 01,000 est 01,000 est |
| | 11,777 es 11,777 es 11,777 es 11,777 es |
| | 01,777 est 01,777 est 01,777 est 01,777 est 01,777 est |
| | 01,777 46 01,777 46 01,777 46 01,777 46 01,777 46 01,777 46 |
| | 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est |
| | 2012-11-26 2013-11-27 2013-12-11 2014-12-05 2015-11-25 2015-11-26 2016-11-30 2016-12-01 2016-12-01 2017-07-18 2018-06-18 |

More info >





Safety ratings

NCAP rating

Video

see crash video

| Dimensions & weight | |
|--|--------------------------|
| Width | 1659 mm |
| Height | 1477 mm |
| Length | 3666 mm |
| Wheel base | 2315 mm |
| Kerb weight | 1003 kg |
| Max. allowed weight | 1391 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 41 I |
| | 41 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 3 |