



report date: 2024-03-28

General information

Make	SUZUKI
Model	SPLASH DDIS
Colour	Green
Year of manufacture	2009
Top speed	102 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	120 g/km
CO2 label	C





MOT history

MOT expiry date	2025-03-20
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	79
Total items failed	19

MOT #23	2024-03-21 10:59
MOT test number	180574083141
Result	✓ Passed
Next expiry date	2025-03-20
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front top mount slight play
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #22**

2024-03-19 10:00

MOT test number

106580657152

Result**✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Upper both strut top mounts slightly worn**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #21**

2023-01-19 11:55

MOT test number

412155093415

Result**✓ Passed****MOT #20**

2023-01-18 15:34

MOT test number

587941976954

Result**✗ Failed****MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #19**

2022-04-14 07:28

MOT test number

267477048753

Result

✓ Passed

- Advice** Brake pipe corroded, covered in grease or other material Both rear (1.1.11 (c))
- Advice** Rear suspension corroded
- Advice** Fuel Pipe/s corroded
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Macpherson strut pin or bush worn but not resulting in excessive movement Both front (5.3.4 (a) (i))
- Advice** Rear underside of vehicle corroded

MOT #18

2022-04-11 14:38

MOT test number

384362190163

Result

✗ Failed

- Advice** Rear suspension corroded
- Advice** Brake pipe corroded, covered in grease or other material Both rear (1.1.11 (c))
- Advice** Rear underside of vehicle corroded
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Fuel Pipe/s corroded
- Advice** Macpherson strut pin or bush worn but not resulting in excessive movement Both front (5.3.4 (a) (i))
- DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #17

2021-03-29 09:12

MOT test number

130236231948

Result

✓ Passed

**MOT #16**

2020-06-18 12:51

MOT test number

168023037125

Result

✓ Passed

- Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Brake hose has slight corrosion to ferrule both rears (1.1.12 (f) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Fuel Pipe/s corroded

MOT #15

2019-09-04 14:38

MOT test number

987497430450

Result

✓ Passed

MOT #14

2019-02-06 12:39

MOT test number

324505137749

Result

✓ Passed

**MOT #13** 2019-02-04 11:24**MOT test number** 328263862592**Result** ✗ Failed

MAJOR Parking brake lever has excessive movement indicating incorrect adjustment EXCESSIVE TRAVEL (NO RESERVE TRAVEL) (1.1.6 (c))

MAJOR Front Brake disc significantly and obviously worn BOTH SIDES (1.1.14 (a) (i))

MOT #12 2018-04-09 12:02**MOT test number** 509545178624**Result** ✓ Passed

Advice Central Front Inner clutch pedal rubber missing

Advice Offside Front Inner Bumper insecure inner damage to front bumper

Advice Nearside Front Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Offside Rear Upper Brake pipe slightly corroded main pipe to flexi (3.6.B.2c)

Advice Central Front Upper Oil leak major leak from turbo area

Advice Eml warning light on

Advice Nearside Rear Inner Fuel Pipe/s corroded main line pipes

Advice Nearside Rear Upper Brake pipe slightly corroded n/s/r main pipe to flexi (3.6.B.2c)



MOT #11

2018-04-05 12:57

MOT test number

957066334670

Result

✗ Failed

- Fail

Parking brake: efficiency below requirements (3.7.B.7)
- Advice

Nearside Rear Inner Fuel Pipe/s corroded main line pipes
- Fail

Offside Front Lower coil spring broken (2.4.C.1a)
- Fail

Front Windscreen wiper does not clear the windscreen effectively wiper blades torn (8.2.2)
- Advice

Central Front Upper Oil leak major leak from turbo area
- Advice

Offside Rear Upper Brake pipe slightly corroded main pipe to flexi (3.6.B.2c)
- Advice

Eml warning light on
- Fail

Parking brake lever has no reserve travel (3.1.6b)
- Advice

Nearside Front Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Fail

Offside Front Inner Suspension arm rubber mounting bonding deteriorated resulting in excessive movement inner arm bush (2.4.G.2)
- Fail

Offside Rear Direction indicators incorrect colour (1.4.A.2f)
- Advice

Central Front Inner clutch pedal rubber missing
- Advice

Nearside Rear Upper Brake pipe slightly corroded n/s/r main pipe to flexi (3.6.B.2c)
- Advice

Offside Front Inner Bumper insecure inner damage to front bumper



MOT #10	2017-04-04 15:40
MOT test number	289548351359
Result	✓ Passed
Advice	Offside Rear wheel bearing has slight play (2.6.2)
Advice	Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9	2016-04-07 15:13
MOT test number	447692058157
Result	✓ Passed
Advice	Parking brake lever at max adjustment
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Rear Brake hose has slight corrosion to ferrules both (3.6.B.4e)

**MOT #8**

2016-04-06 14:25

MOT test number

903138126650

Result**✗ Failed****Fail** Offside Front Upper Shock absorber has an excessively worn shock absorber pivot (2.7.4)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)**Advice** Rear Brake hose has slight corrosion to ferrules both (3.6.B.4e)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #7**

2015-04-02 15:31

MOT test number

339182195014

Result**✓ Passed****Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Engine oil leak**MOT #6**

2015-04-01 12:50

MOT test number

517071695072

Result**✗ Failed****Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Engine oil leak**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2014-03-28 11:31**MOT test number** 819907684082**Result** ✓ Passed**MOT #4** 2014-03-26 14:33**MOT test number** 678715384049**Result** ✗ Failed

- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Rear brake application uneven (3.7.B.2)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #3 2013-04-03 14:30**MOT test number** 808333793019**Result** ✓ Passed**MOT #2** 2013-03-27 09:40**MOT test number** 907516383099**Result** ✗ Failed

- Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)
- Notice** Handbrake has little reserve travel
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)



MOT #1	2012-03-26 14:05
MOT test number	315686282043
Result	✓ Passed
<div>Notice</div> Parking brake lever needs adjusted	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
20 March 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	SA09XVK
Plate since	2024-03-28
Current registration	SA09XVK
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2009-03-25
Last registration	2024-03-21
Complete history	See info



Registration #1	2009-03-25	29 mi
Registration #2	2012-03-26	12.726 mi
Registration #3	2013-03-27	16.484 mi
Registration #4	2013-04-03	16.535 mi
Registration #5	2014-03-26	23.045 mi
Registration #6	2014-03-28	23.045 mi
Registration #7	2015-04-01	28.954 mi
Registration #8	2015-04-02	28.954 mi
Registration #9	2016-04-06	36.481 mi
Registration #10	2016-04-07	35.481 mi
Registration #11	2017-04-04	44.677 mi
Registration #12	2018-04-05	52.539 mi
Registration #13	2019-04-06	60.490 mi
Registration #14	2020-04-07	68.441 mi
Registration #15	2021-04-08	76.392 mi
Registration #16	2022-04-09	84.343 mi
Registration #17	2023-04-10	92.294 mi
Registration #18	2024-03-21	100.245 mi
Registration #19	2024-03-21	100.245 mi
Registration #20	2024-03-21	100.245 mi
Registration #21	2024-03-21	100.245 mi
Registration #22	2024-03-21	100.245 mi
Registration #23	2024-03-21	100.245 mi
Registration #24	2024-03-21	100.245 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1590 mm
Length	3715 mm
Wheel base	2360 mm
Kerb weight	1160 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	D13A-1140014