

\$ SUZUKI



General information

Z
1
conds
d Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	А








Internet history

Entry 1	
Date	2021-02-04
Pictures	10
Listing price	View report



source: autoonline.co.uk





MOT history

MOT expiry date	2024-04-24
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	19
Total items failed	1

MOT #11	2024-04-25 10:00
MOT test number	617485857412
Result	🗙 Failed
 DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear brake back plate corroded 	

MOT #10	2023-04-25 16:03
MOT test number	336647556191
Result	✓ Passed





MOT #9		2023-04-24 09:03
MOT test	number	177176848481
Result		🗙 Failed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Minor (4.7.1 (b)	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or lig (i))	ht sources
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Front Windscreen wiper does not clear the windscreen effectively Both. (3.4 (b) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 155/65/14 (5.2.3 (e))	

МОТ #8	2022-06-25 09:40
MOT test number	164917624516
Result	✓ Passed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in rear bush cracked (5.3.4 (a) (i))	excessive movement
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamp (4.7.1 (b) (i))	os or light sources
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in e rear bush starting to separate (5.3.4 (a) (i))	xcessive movement
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #7	2021-07-09 17:57
MOT test number	809643468259
Result	🗸 Passed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	





MOT #6	2020-07-11 08:06
MOT test number	468057331030
Result	✓ Passed
Advice Rear bumper cracked	
MOT #5	2019-04-16 10:33
MOT test number	845472839581
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #4	2018-04-12 17:37
MOT test number	418219405484
Result	✓ Passed

MOT #3	2017-04-16 00:31
MOT test number	239490572342
Result	✓ Passed

MOT #2	20	17-04-16 00:31
MOT test number		528856600918
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)	

MOT #1	2017-03-17 14:36
MOT test number	671632708943
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 August 2024	X MOT Expired: 24 April 2024
Tax status	Valid until 1 August
Days left	94
MOT expiry date	24 April 2024
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48
Band	А
Single payment (12 months)	£ 0,00,-

Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

Extra SUZUKI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this SUZUKI had different number plate	25.
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-18
Last registration	2024-04-25
Complete history	See info



Registration #1	2014-03-18	10 mi
Registration #2	2017-03-17	42.632 mi
Registration #3	2017-04-16	42.815 mi
Registration #4	2017-04-16	42.815 mi
Registration #5	2018-04-12	48.993 mi
Registration #6	2019-04-16	56.000 mi
Registration #7	2020-07-11	57.434 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi





Safety ratings

NCAP rating	****
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight	
Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg
Additional information	
Fuel tank capacity	
i dei tuint cupacity	35 I
Fuel delivery	35 I Multi-Point Injection
Fuel delivery	Multi-Point Injection
Fuel delivery Number of doors	Multi-Point Injection 5