



HYUNDAI

YY06ENC

report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Silver
Year of manufacture	-
Top speed	93 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	99 Nm at 3.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg



**MOT history****MOT #20**

2023-10-11 09:10

MOT test number

701426752039

Result**✗ Failed**

- Fail** Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** General underbody surface corrosion
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #19

2022-10-11 08:41

MOT test number

974189685922

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Nail in tyre

**MOT #18**

2022-10-11 08:41

MOT test number

384565236657

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Nail in tyre
- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))

MOT #17

2021-10-13 14:30

MOT test number

281781951637

Result**✓ Passed****MOT #16**

2020-09-01 13:32

MOT test number

379576804544

Result**✓ Passed**

- Advice** Various corrosion on underside of vehicle not holed or to excess at time of test
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #15** 2020-09-01 11:45**MOT test number** 286163915049**Result** ✗ Failed**Advice** Various corrosion on underside of vehicle not holed or to excess at time of test**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #14** 2019-03-27 09:28**MOT test number** 212125105964**Result** ✓ Passed**MOT #13** 2018-04-03 09:00**MOT test number** 430622642670**Result** ✓ Passed**MOT #12** 2017-03-31 14:55**MOT test number** 817508209462**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2016-04-01 10:52**MOT test number** 936988784486**Result** ✓ Passed**MOT #10** 2015-04-02 10:14**MOT test number** 558302595024**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2014-04-02 16:30**MOT test number** 837232094040**Result** ✓ Passed**MOT #8** 2014-03-28 11:21**MOT test number** 306657884047**Result** ✗ Failed**Fail** Offside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #7** 2013-04-02 11:19**MOT test number** 865232093017**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-04-04 16:58**MOT test number** 328375592035**Result** ✓ Passed**MOT #5** 2012-03-29 09:29**MOT test number** 105819582072**Result** ✗ Failed**Fail** Nearside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)**MOT #4** 2011-03-25 14:14**MOT test number** 567244981082**Result** ✓ Passed



MOT #3	2010-03-25 12:39
MOT test number	470064380093
Result	✓ Passed

MOT #2	2010-03-23 13:45
MOT test number	744422280067
Result	✗ Failed
<div><div>Fail</div>Horn not working (1.6.2a)</div>	

MOT #1	2009-03-27 12:20
MOT test number	354056589009
Result	✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	YY06ENC
Plate since	2024-03-29
Current registration	YY06ENC
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-03-30
Last registration	2023-10-11
Complete history	See info



Registration #1	2006-03-30	15 mi
Registration #2	2009-03-27	4.860 mi
Registration #3	2010-03-23	9.300 mi
Registration #4	2010-03-25	9.300 mi
Registration #5	2011-03-25	12.756 mi
Registration #6	2012-03-29	16.146 mi
Registration #7	2012-04-04	16.146 mi
Registration #8	2013-04-02	18.475 mi
Registration #9	2014-03-28	20.844 mi
Registration #10	2014-04-02	20.844 mi
Registration #11	2015-04-02	23.725 mi
Registration #12	2016-04-02	25.377 mi
Registration #13	2017-04-02	25.377 mi
Registration #14	2018-04-02	25.377 mi
Registration #15	2019-04-02	25.377 mi
Registration #16	2020-04-02	25.377 mi
Registration #17	2021-04-02	25.377 mi
Registration #18	2022-04-02	25.377 mi
Registration #19	2023-04-02	25.377 mi
Registration #20	2024-04-02	25.377 mi
Registration #21	2025-04-02	25.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	998 kg
Max. allowed weight	1440 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4HG6096333