




report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER HARD-TOP TD5
Colour	Red
Year of manufacture	2000
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	at 1.950 rpm
Engine capacity	2.495 cc
Cylinders	5
Fuel type	Diesel





## Internet history

### Entry 1

Date	2021-09-19
Pictures	3
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-20
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	141
Total items failed	19

MOT #23 2023-09-28 08:16

MOT test number 279017562854

Result ✔ Passed

Next expiry date 2024-10-20

**Advice** Nearside rear chassis brackets slight corrosion

**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**Advice** Spare wheel loose but fixing nuts seem to be secure

MOT #22 2023-09-27 11:48

MOT test number 714019715258

Result ✘ Failed

**Fail** Offside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))

**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

**Fail** Steering linkage ball joint ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Fail** Nearside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))

**Advice** Nearside rear chassis brackets slight corrosion

**Advice** Spare wheel loose but fixing nuts seem to be secure

**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**Fail** Offside Headlamp aim too high (4.1.2 (a))



<b>MOT #21</b>	2022-09-23 13:57
<b>MOT test number</b>	140437744154
<b>Result</b>	✓ Passed

<b>MOT #20</b>	2021-10-20 09:57
<b>MOT test number</b>	146576689682
<b>Result</b>	✓ Passed
<b>Advice</b>	Coolant leak
<b>Advice</b>	Front steering damper bush worn
<b>Advice</b>	Coil spring corroded All four (5.3.1 (b) (i))
<b>Advice</b>	Nearside Front Nail in tyre
<b>Advice</b>	Spare wheel loose but secure

<b>MOT #19</b>	2020-10-21 14:10
<b>MOT test number</b>	663999069472
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Engine cover fitted.
<b>Advice</b>	Nearside Front Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))



MOT #18 2017-08-25 12:08

MOT test number 822693302896

Result ✔ Passed

- Advice** Oil leak
- Advice** Engine cover fitted.
- Advice** Offside Drag link end ball joint has slight play (2.2.B.1f)
- Advice** Nearside Drag link end ball joint has slight play (2.2.B.1f)
- Advice** Offside Drag link end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Coil spring corroded all four suspension coil springs corroded. (2.4.C.1b)
- Advice** Steering damper bushes worn.
- Advice** Nearside Drag link end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Rear Vehicle structure has slight corrosion cross member ( tow bar not fitted). (6.1.B.2)

MOT #17 2016-08-22 15:10

MOT test number 199527962244

Result ✔ Passed

- Advice** Engine cover fitted.
- Advice** Rear Vehicle structure has slight corrosion chassis cross member has some corrosion, but tow bar not fitted. (6.1.B.2)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Drag link end ball joint has slight play (2.2.B.1f)
- Advice** Nearside Drag link end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Front steering damper bushes worn.
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Drag link end ball joint has slight play (2.2.B.1f)
- Advice** Offside Drag link end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)



MOT #16

2016-08-16 09:11

MOT test number

222449745975

Result

✗ Failed

**Advice** Nearside Rear coil spring corroded (2.4.C.1b)

**Fail** Vehicle structure excessively corroded within 30cm of towbar mounting (6.6.6)

**Advice** Nearside Drag link end ball joint has slight play (2.2.B.1f)

**Advice** Offside Drag link end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Nearside Front Brake pipe excessively corroded brake hose to master cylinder. (3.6.B.2c)

**Advice** Front steering damper bushes worn.

**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

**Advice** Offside Rear coil spring corroded (2.4.C.1b)

**Advice** Offside Drag link end ball joint has slight play (2.2.B.1f)

**Advice** Nearside Drag link end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**Fail** Offside Stop lamp not working (1.2.1b)

**Advice** Engine cover fitted.

**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)



MOT #15

2015-08-19 16:13

MOT test number

725508561742

Result

✓ Passed

- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Advice** Offside Drag link end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Offside Drag link end ball joint has slight play (2.2.B.1f)
- Advice** Front steering damper bushes worn.
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Nearside Drag link end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Nearside Drag link end ball joint has slight play (2.2.B.1f)
- Advice** Engine cover fitted.
- Advice** Vehicle structure slightly corroded within 30cm of towbar mounting (6.6.6)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



**MOT #14**

2014-08-21 18:44

**MOT test number**

939693034242

**Result**

✓ Passed

- Advice** Nearside Drag link end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Notice** Oil leak
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Spare tyre defective
- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Advice** Offside Drag link end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)
- Notice** Coolant level low.
- Advice** Vehicle structure slightly corroded within 30cm of towbar mounting (6.6.6)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Front coil spring corroded (2.4.C.1b)



**MOT #13**

2013-08-27 10:35

**MOT test number**

298669333205

**Result**

✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Drag link end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Oil leak
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Seat belt stitching slightly frayed (5.2.2b)
- Notice** Front steering damper o/s mounting bush worn.
- Advice** Nearside Drag link end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Spare tyre defective
- Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)



MOT #12

2013-08-23 19:49

MOT test number

689045633268

**Result**

✗ Failed

- Advice** Nearside Front Seat belt stitching slightly frayed (5.2.2b)
- Notice** Spare tyre defective
- Advice** Nearside Drag link end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)
- Notice** Oil leak
- Advice** Offside Drag link end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Vehicle structure excessively corroded within 30cm of towbar mounting (6.6.6)
- Notice** Front steering damper o/s mounting bush worn.



MOT #11 2012-09-01 11:24

MOT test number 318215742243

Result ✔ Passed

- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Items removed from driver's view prior to test
- Advice** Nearside Drag link end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Notice** Oil leak
- Notice** Puncture in o/s rear tyre.
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)
- Notice** Both front wiper blades starting to split.
- Advice** Offside Drag link end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)
- Notice** Engine oil level on the min.
- Advice** Vehicle structure slightly corroded within 30cm of towbar mounting (6.6.6)
- Notice** Front steering damper o/s mounting bush worn.
- Advice** Nearside Front Seat belt stitching slightly frayed (5.2.2b)

MOT #10 2011-09-08 18:17

MOT test number 116801451298

Result ✔ Passed

- Advice** Vehicle structure slightly corroded within 30cm of towbar mounting (6.6.6)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Drag link end ball joint has slight play (2.2.B.1f)
- Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)



MOT #9 2010-09-10 18:12

MOT test number 832693250215

Result ✔ Passed

- Advice** Offside Front Ball joint has slight play (2.2.B.1f)
- Notice** O/s drop arm ball joint dust cover split.
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Vehicle structure slightly corroded within 30cm of towbar mounting (6.6.6)

MOT #8 2010-09-10 18:12

MOT test number 691603950207

Result ✘ Failed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Vehicle structure slightly corroded within 30cm of towbar mounting (6.6.6)
- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Advice** Offside Front Ball joint has slight play (2.2.B.1f)
- Notice** O/s drop arm ball joint dust cover split.



**MOT #7** 2009-09-11 15:42

**MOT test number** 821724659286

**Result** ✗ Failed

- Advice** Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Lower Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)
- Pass with rectification** Fuel pipe union leaking (7.2.3)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Lower Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)
- Pass with rectification** Brake pipe inadequately clipped (3.6.B.1)

**MOT #6** 2009-09-11 15:42

**MOT test number** 531584659253

**Result** ✓ Passed

- Advice** Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Lower Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Lower Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)

**MOT #5** 2008-09-05 11:57

**MOT test number** 532689548271

**Result** ✗ Failed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Pass with rectification** Fuel system component leaking (7.2.3)



<b>MOT #4</b>	2008-09-05 11:57
<b>MOT test number</b>	313599248442
<b>Result</b>	✓ Passed
<b>Advice</b>	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

<b>MOT #3</b>	2007-09-12 11:41
<b>MOT test number</b>	592505657273
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Inner Front Brake pipe slightly corroded (3.6.B.2c)
<b>Advice</b>	Nearside Rear Brake pad(s) wearing thin (3.5.1g)
<b>Advice</b>	Offside Inner Front Brake pipe slightly corroded (3.6.B.2c)
<b>Notice</b>	Space wheel missing
<b>Advice</b>	Offside Outer Front Brake pipe slightly corroded (3.6.B.2c)
<b>Advice</b>	Offside Front Brake pad(s) wearing thin (3.5.1g)
<b>Notice</b>	Steering damper bush as slight play
<b>Advice</b>	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #2 2007-09-08 14:05

MOT test number 652851957268

Result ✗ Failed

- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Offside drag link end gaiter split
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Inner Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Brake pipe excessively corroded (3.6.B.2c)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Spare wheel missing
- Advice** Offside Outer Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Steering damper has play in a bush
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Fail** Offside Inner Front Brake pipe excessively corroded (3.6.B.2c)
- Fail** Front registration plate missing (6.3.1a)
- Notice** Battery insecure

MOT #1 2006-05-26 14:12

MOT test number 493746346156

Result ✓ Passed

- Notice** Wind screen has small chip. no bigger than 10mm



Tax & MOT check

✓  
**Taxed**  
Tax due:  
1 November 2024

✓  
**MOT**  
Expires:  
20 October 2024

**Tax status** Valid until 1 November

**Days left** 187

**MOT expiry date** 20 October 2024

**Full MOT history** [See MOT history](#)




Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	<b>V268MEC</b>
Plate since	2024-03-28
Current registration	<b>V268MEC</b>
Plate since	2024-03-28

More info >



**Finance check**

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	22
<b>First mileage registration</b>	2000-01-01
<b>Last registration</b>	2023-09-28
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2000-01-01	25 mi
<b>Registration #2</b>	2006-05-26	91.434 mi
<b>Registration #3</b>	2007-09-08	98.360 mi
<b>Registration #4</b>	2007-09-12	98.360 mi
<b>Registration #5</b>	2008-09-05	101.501 mi
<b>Registration #6</b>	2009-09-11	103.648 mi
<b>Registration #7</b>	2010-09-10	106.332 mi
<b>Registration #8</b>	2011-09-08	108.559 mi
<b>Registration #9</b>	2012-09-01	112.153 mi
<b>Registration #10</b>	2013-08-23	117.248 mi
<b>Registration #11</b>	2013-08-27	117.254 mi
<b>Registration #12</b>	2013-09-01	117.254 mi
<b>Registration #13</b>	2013-09-01	117.254 mi
<b>Registration #14</b>	2013-09-01	117.254 mi
<b>Registration #15</b>	2013-09-01	117.254 mi
<b>Registration #16</b>	2013-09-01	117.254 mi
<b>Registration #17</b>	2013-09-01	117.254 mi
<b>Registration #18</b>	2013-09-01	117.254 mi
<b>Registration #19</b>	2013-09-01	117.254 mi
<b>Registration #20</b>	2013-09-01	117.254 mi
<b>Registration #21</b>	2013-09-01	117.254 mi
<b>Registration #22</b>	2013-09-01	117.254 mi

More info >



**Dimensions & weight**

<b>Width</b>	1790 mm
<b>Height</b>	2076 mm
<b>Length</b>	4599 mm
<b>Kerb weight</b>	1920 kg
<b>Max. allowed weight</b>	3050 kg

**Additional information**

<b>Fuel tank capacity</b>	75 l
<b>Fuel delivery</b>	Direct Injection
<b>Number of axles</b>	2
<b>Engine number</b>	10PA52036