



report date: 2024-03-29

General information

Make	SUZUKI
Model	SX4 GLX
Colour	Silver
Year of manufacture	2008
Top speed	112 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	165 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-16
Pictures	14
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-05-04
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	78
Total items failed	12

MOT #19 2024-04-17 10:19

MOT test number 831086294872

Result ✓ Passed

Next expiry date 2025-05-04

- Advice** Offside Front brake slight lagging in operation
- Advice** Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))

MOT #18 2023-05-05 09:41

MOT test number 897023076288

Result ✓ Passed



MOT #172023-04-28 09:33

MOT test number840875521640

Result		✗ Failed
Fail	Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))	
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail	Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))	
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

**MOT #16**

2022-04-29 13:35

**MOT test number**

823453451452

**Result**

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Fuel tank straps corroded
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 1.7mm , devoid of tread on edges (5.2.3 (e))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Battery suspect
- Advice** Exhaust has a minor leak of exhaust gases corroded (6.1.2 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm, devoid of tread on edges (5.2.3 (e))
- Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #15**

2022-04-29 08:46

**MOT test number**

728858949893

**Result****✗ Failed**

- Advice** Exhaust has a minor leak of exhaust gases corroded (6.1.2 (a))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 1.7mm , devoid of tread on edges (5.2.3 (e))
- Advice** Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Battery suspect
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Pass with rectification** Offside Rear Body component damaged and likely to cause injury (6.2.1 (a) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm, devoid of tread on edges (5.2.3 (e))
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Fuel tank straps corroded
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #14** 2021-04-12 08:51**MOT test number** 772594668110**Result** ✓ Passed**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #13** 2020-03-18 17:03**MOT test number** 870324563118**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #12** 2020-03-18 12:52**MOT test number** 215268856605**Result** ✗ Failed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #11** 2019-04-08 12:10**MOT test number** 283508480071**Result** ✓ Passed

**MOT #10** 2018-04-18 14:58**MOT test number** 646173306086**Result** ✓ Passed

- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Both front tyres cracking between tread
- Advice** Central Exhaust has a minor leak of exhaust gases at rear joint (7.1.2)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #9** 2018-04-16 13:14**MOT test number** 128052564588**Result** ✗ Failed

- Advice** Both front tyres cracking between tread
- Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Central Exhaust has a minor leak of exhaust gases at rear joint (7.1.2)
- Advice** Offside Rear tyre cracking on sidewall and tread
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #8** 2017-03-23 15:39**MOT test number** 993062340440**Result** ✓ Passed

- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #7** 2016-03-17 15:37**MOT test number** 776696690826**Result** ✓ Passed





MOT #6	2015-03-31 11:43
MOT test number	697910795074
Result	✓ Passed

MOT #5	2014-09-27 09:02
MOT test number	477800374257
Result	✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Slight corrosion on all coil springs
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Both rear tyres cracking
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** N/s/f wiper split

**MOT #4** 2014-09-26 17:37**MOT test number** 318129064404**Result** ✗ Failed**Notice** N/s/f wiper split**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Slight corrosion on all coil springs**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear tyres cracking**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-08-21 14:40**MOT test number** 71563333211**Result** ✓ Passed**MOT #2** 2012-08-15 12:37**MOT test number** 247628722239**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** O/s/f tyre cracking between tread**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** N/s/f tyre cracking between tread



MOT #1	2011-06-02 12:29
MOT test number	486573251191
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
4 May 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	4 May 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>NU08HZM</b>
Plate since	2019-03-29
Current registration	<b>NU08HZM</b>
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-14
Last registration	2024-04-17
Complete history	<a href="#">See info</a>



Registration #1	2008-03-14	17 mi
Registration #2	2011-06-02	8.803 mi
Registration #3	2012-08-15	12.746 mi
Registration #4	2013-08-21	16.645 mi
Registration #5	2014-09-26	21.395 mi
Registration #6	2014-09-27	21.395 mi
Registration #7	2015-03-31	23.256 mi
Registration #8	2016-03-17	26.040 mi
Registration #9	2017-03-23	28.420 mi
Registration #10	2018-04-16	31.018 mi
Registration #11	2018-04-18	31.018 mi
Registration #12	2019-05-20	35.277 mi
Registration #13	2020-05-20	35.277 mi
Registration #14	2021-05-20	35.277 mi
Registration #15	2022-05-20	35.277 mi
Registration #16	2023-05-20	35.277 mi
Registration #17	2024-05-20	35.277 mi
Registration #18	2025-05-20	35.277 mi
Registration #19	2026-05-20	35.277 mi
Registration #20	2027-05-20	35.277 mi
Registration #21	2028-05-20	35.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1755 mm
Height	1605 mm
Length	4235 mm
Wheel base	2500 mm
Kerb weight	1205 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-8024559