



report date: 2024-03-28

General information

Make	VOLVO
Model	C70 T5 GT
Colour	Silver
Year of manufacture	2003
Top speed	149 mph
0 - 60 mph	7.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	240 BHP
Max. torque	330 Nm at 5.100 rpm
Engine capacity	2.319 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.6 mpg
Consumption extra urban	36.7 mpg
Consumption combined	28.5 mpg
CO2 emission	261 g/km
CO2 label	M





Internet history

Entry 1

Date	2022-01-06
Pictures	17
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-05
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	39
Total items failed	12

MOT #23	2023-07-06 17:29
MOT test number	327665429064
Result	✓ Passed
Next expiry date	2024-07-05

MOT #22	2022-01-13 13:06
MOT test number	786860618466
Result	✓ Passed

MOT #21	2021-03-29 09:43
MOT test number	418811588097
Result	✓ Passed

- Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front radiator expansion tank leaking

**MOT #20**

2020-03-17 15:30

MOT test number

634916612723

Result

✓ Passed

Minor

Offside Front Suspension arm ball joint dust cover severely deteriorated splitting/perished (5.3.4 (b) (i))

Advice

Nearside Rear Outer sill damage

Minor

Nearside Front Suspension arm ball joint dust cover severely deteriorated splitting/perished (5.3.4 (b) (i))

MOT #19

2019-03-21 09:39

MOT test number

969543368690

Result

✓ Passed

Minor

Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated split (5.3.4 (b) (i))

Minor

Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))

Advice

Nearside Rear Exhaust mounting defective mounting broken on exhaust at rear pipe (6.1.2 (a))

Minor

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated split (5.3.4 (b) (i))

Minor

Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))

**MOT #18**

2019-03-19 11:55

MOT test number

563168900420

Result**✗ Failed**

- Minor** Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Nearside Rear Exhaust mounting defective mounting broken on exhaust at rear pipe (6.1.2 (a))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated split (5.3.4 (b) (i))
- Minor** Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated split (5.3.4 (b) (i))

MOT #17

2018-03-23 14:29

MOT test number

708328286107

Result**✓ Passed**

- Advice** Offside Front Front position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Advice** Nearside Front Front position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

**MOT #16** 2018-03-23 11:45**MOT test number** 887016361835**Result** ✗ Failed**Fail** Offside Front Headlamp aim too low (1.8)**Advice** Nearside Front Front position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Front Headlamp aim too low (1.8)**Fail** Nearside Rear rear parking brake recording little or no effort on test (3.7.B.6a)**Advice** Offside Front Front position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #15** 2017-03-01 14:28**MOT test number** 418800917772**Result** ✓ Passed**Advice** Mil lamp on**MOT #14** 2016-03-18 09:45**MOT test number** 384867088310**Result** ✓ Passed**MOT #13** 2016-03-18 09:45**MOT test number** 980621785354**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)



MOT #12	2015-03-27 09:52
MOT test number	378906985085
Result	✓ Passed
Notice	Rear exhaust support bracket broken on one half
Notice	Mil lamp on

MOT #11	2014-03-28 11:57
MOT test number	208787384085
Result	✓ Passed
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Offside front wiperblade starting to split
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Notice	Slight damage to offside rear side wall
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Front bumper damage

**MOT #10** 2014-03-28 11:57**MOT test number** 405997484051**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Front bumper damage**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Notice** Offside front wiperblade starting to split**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Slight damage to offside rear side wall**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2013-03-28 10:21**MOT test number** 205737383031**Result** ✓ Passed**MOT #8** 2012-03-30 16:38**MOT test number** 326140992088**Result** ✓ Passed**MOT #7** 2011-03-15 12:48**MOT test number** 939994671038**Result** ✓ Passed**MOT #6** 2009-11-12 10:10**MOT test number** 571696619378**Result** ✓ Passed



MOT #5	2008-11-26 10:16
MOT test number	602241438352
Result	✓ Passed
MOT #4	2008-03-26 14:20
MOT test number	364426188044
Result	✓ Passed
MOT #3	2008-03-19 16:23
MOT test number	852969378029
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
MOT #2	2007-03-27 09:04
MOT test number	111526887034
Result	✓ Passed
MOT #1	2006-02-28 12:01
MOT test number	670499156089
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-03-28
Last registration	2023-07-06
Complete history	See info



Registration #1	2003-03-28	20 mi
Registration #2	2006-02-28	7.349 mi
Registration #3	2007-03-27	9.690 mi
Registration #4	2008-03-19	11.670 mi
Registration #5	2008-03-26	116.695 mi
Registration #6	2008-11-26	12.466 mi
Registration #7	2009-11-12	14.885 mi
Registration #8	2011-03-15	15.947 mi
Registration #9	2012-03-30	23.076 mi
Registration #10	2013-03-28	29.755 mi
Registration #11	2014-03-28	34.848 mi
Registration #12	2015-03-27	38.704 mi
Registration #13	2016-03-27	39.377 mi
Registration #14	2016-03-27	39.377 mi
Registration #15	2016-03-27	39.377 mi
Registration #16	2016-03-27	39.377 mi
Registration #17	2016-03-27	39.377 mi
Registration #18	2016-03-27	39.377 mi
Registration #19	2016-03-27	39.377 mi
Registration #20	2016-03-27	39.377 mi
Registration #21	2016-03-27	39.377 mi
Registration #22	2016-03-27	39.377 mi
Registration #23	2016-03-27	39.377 mi
Registration #24	2016-03-27	39.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1820 mm
Height	2660 mm
Length	4720 mm
Wheel base	1420 mm
Kerb weight	1565 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	3115548