





## General information

Make	VOLVO
Model	S80 SE (170BHP)
Colour	Green
Year of manufacture	2004
Top speed	134 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	168 BHP
Max. torque	225 Nm at 4.500 rpm
Engine capacity	2.435 сс
Cylinders	5
Fuel type	Petrol
Consumption city	20.3 mpg
Consumption extra urban	38.2 mpg
Consumption combined	28.8 mpg
CO2 emission	235 g/km
CO2 label	L







# Internet history

Entry 1	
Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk



## MOT history

MOT expiry date	2025-01-22
MOT pass rate	68 %
MOT passed	17
Failed MOT tests	8
Total advice items	97
Total items failed	18

MOT #25		2024-01-23 10:39
MOT test	number	731267800105
Result		✓ Passed
Next expi	ry date	2025-01-22
Advice	Nearside Rear Outer Child Seat fitted not allowing full inspection of adult	belt
Advice	Advice Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Offside and Nearside (1.1.14 (a) (ii))		le and Nearside (1.1.14
Advice	Offside Front Power steering pipe/hose has slight seepage (2.1.5 (a))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Stone chip in windscreen but not adversely affecting driver's view	

MOT #24	2022-12-28 12:31
MOT test number	914830217786
Result	✓ Passed
Advice Central Front Oil leak, but not excessive (8.4.1 (a) (i))	



MOT #23	2022-01-04 20:00
MOT test number	245235907838
Result	✓ Passed
Advice Oil leak, but not excessive Engine (8.4.1 (a) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #22	2021-12-20 15:20
MOT test number	374915378276

MOT test	number	374915378276
Result		🗙 Failed
MAJOR	Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR the ingres	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no lon ss of dirt (6.1.7 (g) (ii))	ger prevents
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Minor	Offside Front Tyre obviously under inflated (5.2.3 (I))	
MAJOR ingress of	Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no long f dirt (6.1.7 (g) (ii))	er prevents the
Advice	Handbrake shoes grinding when handbrake applied	
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))	
MAJOR	Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	4 (a) (ii))
<b>MAJOR</b> the ingres	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no lo ss of dirt (6.1.7 (g) (ii))	nger prevents
<b>MAJOR</b> the ingres	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no long ss of dirt (6.1.7 (g) (ii))	er prevents

MOT #21	2020-12-18 15:05
MOT test number	764312885187
Result	✓ Passed

**OE04PWK** 

report date: 2024-03-29





MOT #20		2019-11-21 10:45
MOT test	number	516625893049
Result		✓ Passed
Advice	Rear Anti-roll bar linkage ball joint has slight play both (5.3.4 (a) (i))	
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

MOT #19	2018-11-16 09:47
MOT test number	955893675933
Result	✓ Passed
Advice Offside Rear Tyre perished	

MOT #18	2017-11-21 16:28
MOT test number	767726135084
Result	✓ Passed
Advice Water ingress into nearside headlamp	

MOT #17	2017-11-21 11:38	
MOT test number	504375191021	
Result	🗙 Failed	
Advice Water ingress into nearside headlamp		
<b>Fail</b> Offside Front Outer Front constant velocity joint gaiter deteriorated to the exten prevents the ingress of dirt etc (2.5.C.1a)	t that it no longer	
<b>Fail</b> Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)		
Fail Nearside Front position lamp(s) not working (1.1.A.3b)		
FailNearside Front Lower Suspension arm rubber bush deteriorated resulting in exce(2.4.G.2)	essive movement	





MOT #16	2016-11-15 11:06
MOT test number	616459355231
Result	✓ Passed
Advice Exhaust centre pipe hangers corroded off but exhaust still adequately sup	pported
<b>Advice</b> Offside Front Lower Suspension arm rubber bush deteriorated but not res movement front bush (2.4.G.2)	sulting in excessive
Advice Central washer jet broken	
Advice Exhaust rear silencer outer casing corroded	
<b>Advice</b> Nearside Front Lower Suspension arm rubber bush deteriorated but not removement front bush (2.4.G.2)	esulting in excessive
MOT #15	2015 10 15 00:00

MOT #15		2015-10-15 09:00
MOT test	number	620080548250
Result		✓ Passed
Advice	Both front tyres worn on the edges	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.	1i)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1	Li)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.	5.1i)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5	5.1i)
Advice	Centre exhaust hanger corroded off but exhaust still adequately supported	





MOT #14	2015-10-14 13:18
MOT test number	356659909473
Result	🗙 Failed
Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.3	1i)
Advice Both front tyres worn on the edges	
Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1	Li)
FailOffside Front Front position lamp(s) not working (1.1.A.3b)	
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5	5.1i)
Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5	5.1i)
Advice Centre exhaust hanger corroded off but exhaust still adequately supported	
FailNearside Front Front position lamp(s) not working (1.1.A.3b)	
<b>Fail</b> Nearside Front Outer Front constant velocity joint gaiter deteriorated to the extent t prevents the ingress of dirt etc (2.5.C.1a)	hat it no longer

MOT #13	2014-10-01 11:45
MOT test number	697824574251
Result	🗸 Passed
Advice Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)	

MOT #12	2014-10-01 09:26
MOT test number	655494074239
Result	× Failed
<b>Fail</b> Fuel cap/sealing device sealing washer deteriorated (7.2.4c)	
Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)	
Notice Nearside rear tyre perished	





MOT #11		2013-10-15 17:19
MOT test	number	229048083297
Result		✓ Passed
Notice	Centre exhaust bracket broken	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Sill covers fitted	
Notice	Nearside rear tyre slightly perished	
Notice	Engine cover fitted	

MOT #10		2012-10-02 12:43
MOT test	number	627546272241
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.3	1d)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

#### MOT #9 2012-09-27 16:07 **MOT test number** 147161172277 Result × Failed Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2) Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) Fail Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)



<b>OE04PWK</b>	
report date: 2024-03-29	

MOT #8		2011-10-04 14:27
MOT test	number	856367571220
Result		✓ Passed
Notice	Top engine stabilizer rubber bush splitting	
Advice movemen	Nearside Front Lower Suspension arm rubber bush deteriorated but not result (2.4.G.2)	ting in excessive
Notice	Both front brake discs slightly worn	
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)	
Notice	Both rear tyres slightly perished	
Advice	Front Windscreen has damage to an area less than a 40mm circle outside zor	ne 'A' (8.3.1d)
Notice	Outer sill mouldings fitted	
Advice movement	Offside Front Lower Suspension arm rubber bush deteriorated but not resultir t (2.4.G.2)	ng in excessive
Notice	Small cuts in the offside rear tyre sidewall	





MOT #7		2011-10-04 14:27
MOT test number		336377471212
Result		🗙 Failed
Pass with rectification	Nearside Front Headlamp aim too low (1.8)	
Advice Nearside Front I movement (2.4.G.2)	ower Suspension arm rubber bush deteriorated but not rest	ulting in excessive
<b>Notice</b> Small cuts in the	e offside rear tyre sidewall	
Advice Exhaust has par	t of the system slightly deteriorated (7.1.1a)	
<b>Notice</b> Outer sill mould	ings fitted	
Pass with rectification	Brake pedal anti-slip provision missing (3.3.A.1b)	
Advice Front Windscree	en has damage to an area less than a 40mm circle outside z	one 'A' (8.3.1d)
<b>Notice</b> Both front brake	discs slightly worn	
Advice Offside Front Lo movement (2.4.G.2)	wer Suspension arm rubber bush deteriorated but not result	ting in excessive
<b>Notice</b> Both rear tyres s	slightly perished	
<b>Notice</b> Top engine stab	ilizer rubber bush splitting	

МОТ #6	2010-09-28 15:00
MOT test number	771251770276
Result	✓ Passed
Advice Front Windscreen has damage to an area less than a 40mm circle out	side zone 'A' (8.3.1d)
Notice Outer sill mouldings fitted	
Notice Nail/screw in the offside rear tyre tread	
<b>Advice</b> Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Notice Both front brake discs slightly worn	
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but no movement (2.4.G.2)	ot resulting in excessive
Advice Exhaust has part of the system slightly deteriorated (7.1.1a)	





MOT #5		2009-09-25 09:59
MOT test	number	574628469205
Result		✓ Passed
Advice	Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Front Windscreen has damage to an area less than a 40mm circle outside z	one 'A' (8.3.1d)
Notice	Outer sill mouldings fitted	
Advice	Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Centre washer jet not working	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

МОТ #4	2009-09-24 16:54
MOT test number	951067369222
Result	🗙 Failed
Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice Outer sill mouldings fitted	
<b>Fail</b> Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Front Windscreen has damage to an area less than a 40mm circle outside zon	ne 'A' (8.3.1d)
Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice Centre washer jet not working	

MOT #3		2008-09-19 12:30
MOT test	number	900803368229
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A'	(8.3.1d)





MOT #2	2007-10-02 09:29	
MOT test number	363605277483	
Result	✓ Passed	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		
MOT #1	2007-10-02 09:29	
MOT test number	783655277291	
Result	× Failed	
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 22 January 2025
Tax status	Valid until 1 January
Days left	247
MOT expiry date	22 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second	
**********	
********	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-05-28
Last registration	2024-01-23
Complete history	See info



Registration #1	2004-05-28	23 mi
Registration #2	2007-10-02	52.563 mi
Registration #3	2008-09-19	58.837 mi
Registration #4	2009-09-24	65.338 mi
Registration #5	2009-09-25	65.338 mi
Registration #6	2010-09-28	73.038 mi
Registration #7	2011-10-04	79.053 mi
Registration #8	2012-09-27	83.534 mi
Registration #9	2012-10-02	83.564 mi
Registration #10	2013-10-15	86.580 mi
Registration #11	2014-10-01	90.340 mi
Registration #12	2014-10-01	90.340 mi
Registration #13	2015-10-14	92.712 mi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #19 Registration #20		10.202 mi 10.202 mi
		10.202 est 10.202 est 10.202 est
Registration #20		10.202 est 10.202 est 10.202 est 10.202 est
Registration #20 Registration #21		10.202 es 0.202 es 0.202 es 0.202 es 0.202 es
Registration #20 Registration #21 Registration #22		0.202 es 0.222 es 0.222 es 0.222 es 0.222 es
Registration #20 Registration #21 Registration #22 Registration #23		01,222 46 01,222 46 01,222 46 01,222 46 01,222 46 01,222 46 01,222 46





## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
\$0566	
S0567	
S0569	

# Safety ratings

Number of seats CarCheck.co.uk

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1830 mm
Height	1430 mm
Length	4820 mm
Wheel base	2790 mm
Kerb weight	1490 kg
Max. allowed weight	2040 kg
Additional information	
Fuel tank capacity	80 I
Fuel delivery	Multi-Point Injection
Number of doors	4

5

page 19/19

Number of axles	2
Engine number	3441122