



R67IUGC

report date: 2024-03-29

General information

Make	MAZDA
Model	323 S
Colour	Blue
Year of manufacture	1998
Top speed	127 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	162 Nm at 4.500 rpm
Engine capacity	1.840 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-21
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-21
MOT pass rate	62 %
MOT passed	18
Failed MOT tests	11
Total advice items	53
Total items failed	24

MOT #29	2023-10-16 15:30
MOT test number	449519805768
Result	✓ Passed
Next expiry date	2024-10-21

MOT #28	2023-10-10 14:56
MOT test number	429549622391
Result	✗ Failed
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #27	2022-09-23 11:52
MOT test number	515294814665
Result	✓ Passed
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))
Advice	Rear Sub-frame is corroded but structural rigidity is not significantly reduced Very rusty (6.1.1 (c) (i))

**MOT #26**

2022-09-23 11:52

MOT test number

233590066381

Result**✗ Failed****Pass with rectification** Nearside Headlamp aim too far to the right (4.1.2 (a))**Pass with rectification** Battery insecure and likely to fall from carrier (4.13 (a) (ii))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced Very rusty (6.1.1 (c) (i))**MOT #25**

2021-10-22 13:15

MOT test number

295824441722

Result**✓ Passed****MOT #24**

2021-10-19 13:57

MOT test number

348863510521

Result**✗ Failed****Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive door sill (5.3.6 (a) (i))**Fail** Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced lower wheel arch/rear of door sill (7.1.1 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Suspension component mounting prescribed area excessively damaged significantly reducing structural strength door sill (5.3.6 (a) (i))

**MOT #23** 2020-10-03 09:12**MOT test number** 770137454936**Result** ✓ Passed**MOT #22** 2020-09-16 15:06**MOT test number** 360644853720**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**MOT #21** 2019-10-01 09:03**MOT test number** 367577428678**Result** ✓ Passed**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Sub-frame corroded but not seriously weakened suspension rods mounting area (5.3.3 (b) (i))**Advice** Brake pipe corroded, covered in grease or other material front to rear pipe (1.1.11 (c))**MOT #20** 2019-09-18 10:53**MOT test number** 568464870206**Result** ✗ Failed**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))**Advice** Brake pipe corroded, covered in grease or other material front to rear pipe (1.1.11 (c))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Sub-frame corroded but not seriously weakened suspension rods mounting area (5.3.3 (b) (i))

**MOT #19**

2018-09-26 11:22

MOT test number

452714618037

Result

✓ Passed

Advice Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

Minor Offside Front Brake hose slightly twisted (1.1.12 (b) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

MOT #18

2017-09-21 12:49

MOT test number

259580472277

Result

✓ Passed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (2.4.A.3)

Advice Rear Sub-frame corroded but not seriously weakened suspension arm mounting area (2.4.G.1)

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (2.4.A.3)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #17

2016-09-06 16:27

MOT test number

500992440946

Result

✓ Passed

Advice Nearside Rear Road wheel slightly damaged (4.2.A.1a)

Advice Centre Stop lamp has light sources not illuminating, but not more than 50% high level (1.2.1b)

MOT #16

2015-09-24 09:40

MOT test number

546656226459

Result

✓ Passed

Advice Nearside Front Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #15**

2015-09-08 14:40

MOT test number

918209379992

Result**✗ Failed****Advice** Engine coolant leak**Fail** Service brake: efficiency below requirements (3.7.B.7)**Fail** Offside Rear Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings o/s/r sill (6.1.B.2)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #14**

2014-09-09 11:55

MOT test number

346732754476

Result**✓ Passed****Notice** Nearside front tyre worn on inner edge**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Bonnet safety catch stiff**MOT #13**

2014-09-09 09:02

MOT test number

839812554232

Result**✗ Failed****Notice** Nearside front tyre worn on inner edge**Fail** Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Notice** Bonnet safety catch stiff**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #12**

2013-08-01 17:06

MOT test number

889923313299

Result

✓ Passed

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Hazard switch sticky**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #11**

2013-08-01 17:06

MOT test number

498053613229

Result

✗ Failed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** Hazard switch sticky**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #10**

2012-08-07 16:03

MOT test number

528110122208

Result

✓ Passed

**MOT #9** 2012-08-06 12:47**MOT test number** 658239912238**Result** ✗ Failed

Fail Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #8 2011-07-28 14:59**MOT test number** 546599301271**Result** ✓ Passed

Notice O/side front tyre worn low inner edge

Notice Child seat fitted not allowing full inspection of adult belt

MOT #7 2011-07-28 09:31**MOT test number** 319559601209**Result** ✗ Failed

Notice Child seat fitted not allowing full inspection of adult belt

Fail Nearside Headlamp not working on dipped beam (1.7.5a)

Notice O/side front tyre worn low inner edge

MOT #6 2010-07-29 16:03**MOT test number** 522660510289**Result** ✓ Passed

Notice Larger dia tyres fitted to rear

**MOT #5** 2010-07-29 12:06**MOT test number** 311130310416**Result** ✗ Failed**Fail** Nearside Front Brake hose twisted (3.6.B.4c)**Notice** Larger dia tyres fitted to rear**Fail** Offside Front Brake hose twisted (3.6.B.4c)**MOT #4** 2009-07-30 14:51**MOT test number** 532351819247**Result** ✓ Passed**MOT #3** 2008-07-30 14:38**MOT test number** 822442218250**Result** ✓ Passed**MOT #2** 2007-06-28 12:37**MOT test number** 743019977162**Result** ✓ Passed**MOT #1** 2006-06-23 14:50**MOT test number** 373454976112**Result** ✓ Passed**Advice** Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Notice** Front no. plate cracked**Advice** Offside Front constant velocity joint gaiter deteriorated (2.5.C.1a)



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	30
First mileage registration	1998-06-29
Last registration	2023-10-16
Complete history	See info



Registration #1	1998-06-29	7 mi
Registration #2	2006-06-23	59.687 mi
Registration #3	2007-06-28	68.938 mi
Registration #4	2008-07-30	73.377 mi
Registration #5	2009-07-30	78.195 mi
Registration #6	2010-07-29	84.467 mi
Registration #7	2010-07-29	84.467 mi
Registration #8	2011-07-28	90.856 mi
Registration #9	2011-07-28	90.856 mi
Registration #10	2012-08-06	97.557 mi
Registration #11	2012-08-07	97.557 mi
Registration #12	2013-08-01	102.132 mi
Registration #13	2014-09-09	106.980 mi
Registration #14	2014-09-09	106.980 mi
Registration #15	2015-09-08	110.750 mi
Registration #16	2016-09-08	115.500 mi
Registration #17	2017-09-08	120.250 mi
Registration #18	2018-09-08	125.000 mi
Registration #19	2019-09-08	129.750 mi
Registration #20	2020-09-08	134.500 mi
Registration #21	2021-09-08	139.250 mi
Registration #22	2022-09-08	144.000 mi
Registration #23	2023-09-08	148.750 mi
Registration #24	2024-09-08	153.500 mi
Registration #25	2025-09-08	158.250 mi
Registration #26	2026-09-08	163.000 mi

Registration #27	2025-25-25	25,252 442
Registration #28	2025-25-25	25,252 442
Registration #29	2025-25-25	25,252 442
Registration #30	2025-25-25	25,252 442

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1225 mm
Length	3975 mm
Kerb weight	1025 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	BP349180