





## General information

| Make                | ΤΟΥΟΤΑ         |
|---------------------|----------------|
| Model               | MR2 GT         |
| Colour              | Red            |
| Year of manufacture | 1990           |
| Top speed           | 137 mph        |
| Gearbox             | 5 speed Manual |

# Engine & fuel consumption

| Power           | 173 BHP             |
|-----------------|---------------------|
| Max. torque     | 186 Nm at 4.800 rpm |
| Engine capacity | 1.998 cc            |
| Cylinders       | 4                   |
| Fuel type       | Petrol              |








# Internet history

| Entry 1       |             |
|---------------|-------------|
| Date          | 2021-10-05  |
| Pictures      | 19          |
| Listing price | View report |









source: autotrader.co.uk



## MOT history

| MOT expiry date    | 2024-05-26 |
|--------------------|------------|
| MOT pass rate      | 67 %       |
| MOT passed         | 14         |
| Failed MOT tests   | 7          |
| Total advice items | 56         |
| Total items failed | 33         |

| MOT #21   |  | 2023-05-24 07:39 |
|-----------|--|------------------|
| MOT test  | number   | 361978831439     |
| Result    |  | Passed           |
| Next expi | ry date  | 2024-05-26       |
| Advice    | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |
| Advice    | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))         |                  |

| MOT #20   | 2023-05-22 09:08 |
|---|------------------|
| MOT test number   | 384742950240     |
| Result  | 🗙 Failed         |
| Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))         |                  |
| Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))          |                  |
| Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |



| <b></b>               | report date: 2024-03-28   |
|-----------------------|---|
|                       |   |
| MOT #19               | 2022-05-11 15:45  |
| MOT test              | <b>number</b> 458044909812  |
| Result                | ✓ Passed  |
| Advice                | Offside Rear Coil spring corroded (5.3.1 (b) (i))   |
| Advice<br>seriously a | Offside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not affecting overall security (6.2.2 (d) (i))                                    |
| Advice                | Both rear wheel arch area's corroded  |
| Advice                | Nearside Rear Coil spring corroded (5.3.1 (b) (i))  |
| Advice                | Offside Front shock absorber corroded   |
| Advice<br>seriously a | Nearside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not affecting overall security rear suspension arm mounting area (6.2.2 (d) (i)) |
| Advice                | Both outer sill area's corroded   |
| Advice                | Nearside Front Coil spring corroded (5.3.1 (b) (i))   |
| Advice                | Nearside Front shock absorber corroded  |

| MOT #18  | 2021-05-27 10:42  |
|--|-------------------|
| MOT test number  | 721120251391      |
| Result   | ✓ Passed          |
| <b>Advice</b> Offside Rear Suspension component mounting prescribed area is corroded but excessive inside arch slightly corroded (5.3.6 (a) (i)) | not considered    |
| Advice O/s/r driveshaft oil seal slightly leaking  |                   |
| Advice Rear Coil spring corroded both spring rear (5.3.1 (b) (i))  |                   |
| <b>Advice</b> Nearside Rear Suspension component mounting prescribed area is corroded b excessive floor slightly corroded (5.3.6 (a) (i))        | ut not considered |
| Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))   |                   |
| Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effective   | ct (5.3.2 (b))    |

**G612SMV** 



| <b>G612SMV</b>          |
|-------------------------|
| report date: 2024-03-28 |

| MOT #17          |   | 2019-07-23 16:17 |
|------------------|---|------------------|
| MOT test         | number  | 213316928836     |
| Result           |   | ✓ Passed         |
| Advice<br>Advice | Exhaust has a minor leak of exhaust gases (6.1.2 (a))<br>Oil leak, but not excessive engine also engine noisy (8.4.1 (a) (i)) |                  |
| MOT #16          |   | 2018-07-10 16:58 |
| MOT test         | number  | 937111541484     |
| Result           |   | ✓ Passed         |

| Advice | Hand brake required a service  |
|--------|--|
| Advice | Oil leak, but not excessive (8.4.1 (a) (i))  |
| Advice | Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))                        |

| MOT #15   | 2017-07-28 15:47            |  |
|---|-----------------------------|--|
| MOT test number   | 831222440659                |  |
| Result  | ✓ Passed                    |  |
| Advice O/s/f ball joint boot deteriated-o/s/f tyre inner edge wearing low-n/s/r wheel bearing has slight play-all welding covered by substance unable to check properly-rear sills slightly distorted-exhaust smoking when cold |                             |  |
| Advice N/s/f anti roll bar link has slight play-o/s/f anti roll bar slightly distorte corroded-exhaust flexi deteriated-x2 front coil springs corroded-oil leak   | ed-x2 inner and outer sills |  |





| <b>MOT #14</b> 2017-06-29 14:26   |
|---|
| MOT test number 570300874031  |
| Result × Failed   |
| <b>Fail</b> Offside Rear Suspension component mounting prescribed area is severely distorted inner sill distorted (2.4.A.3)   |
| <b>Fail</b> Offside Front Tyre(s) incorrect because different size tyres are fitted on the same axle. tyre wrong rotation (4.1.A.1a)  |
| Fail       Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)  |
| <b>Fail</b> Offside Rear Suspension component mounting prescribed area is excessively corroded inner wheel arch holed (2.4.A.3)   |
| <b>Fail</b> Offside Suspension component mounting prescribed area is excessively corroded outer sill holed (2.4.A.3)  |
| Advice O/s/f ball joint boot deteriorated-o/s/f tyre inner edge wearing low-n/s/r wheel bearing has slight play-oil leak  |
| Fail       Parking brake lever has no reserve travel (3.1.6b)   |
| <b>Fail</b> Nearside Rear Suspension component mounting prescribed area is excessively corroded inner sill holed and distorted (2.4.A.3)  |
| <b>Fail</b> Nearside Suspension component mounting prescribed area is excessively corroded complete outer sill holed (2.4.A.3)  |
| Fail       Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)  |
| Fail Battery insecure (1.9.1)   |
| Advice N/s/f anti roll bar link has slight play-o/s/f anti roll bar link slightly distorted-x2 inner and outer sills corroded-exhaust flexi deteriorated-x2 front coil springs corroded |
| <b>Fail</b> Nearside Rear Suspension component mounting prescribed area is excessively corroded inner wheel arch holed (2.4.A.3)  |
| FailOffside Suspension component mounting prescribed area is excessively corroded inner middle sill<br>holed (2.4.A.3)  |





| MOT #13  |  | 2016-07-18 14:12 |
|----------|--|------------------|
| MOT test | number   | 203033508200     |
| Result   |  | ✓ Passed         |
| Advice   | O/s front anti roll bar link bent  |                  |
| Advice   | N/s front and rear brake back plates corroded                                    |                  |
| Advice   | N/s rear outer tyre wall deteriorated  |                  |
| Advice   | Oil leak   |                  |
| Advice   | Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5 | i.1i)            |
| Advice   | O/s front brake back plate corroded  |                  |

| MOT #12   | 2016-07-14 14:44 |
|---|------------------|
| MOT test number   | 675197999921     |
| Result  | 🗙 Failed         |
| Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5 | .1i)             |
| Advice O/s front anti roll bar link bent  |                  |
| FailOffside Front position lamp(s) not working (1.1.A.3b)                               |                  |
| Advice N/s front and rear brake back plates corroded                                    |                  |
| Fail       Offside rear parking brake recording little or no effort (3.7.B.6a)          |                  |
| Advice N/s rear outer tyre wall deteriorated  |                  |
| Fail       Nearside front brake binding (3.7.B.1)                                       |                  |
| FailNearside Front position lamp(s) not working (1.1.A.3b)                              |                  |
| Advice Oil leak   |                  |
| Fail       Nearside Stop lamp not working (1.2.1b)                                      |                  |
| Advice O/s front brake back plate corroded  |                  |
| Fail       Offside rear brake binding (3.7.B.1)   |                  |





| MOT #11  |  | 2015-06-16 12:08 |
|----------|--|------------------|
| MOT test | number   | 408637165130     |
| Result   |  | ✓ Passed         |
| Notice   | N/s front tyre perished  |                  |
| Advice   | Offside Front Anti-roll bar linkage damaged but not seriously weakened (2.4.G.1) |                  |
| Notice   | Handbrake has excess travel  |                  |
| Notice   | Inner edge of o/s front tyre worn + tyre well perished                           |                  |
| Notice   | N/s front brake slightly binding   |                  |
| Notice   | Oil leak   |                  |
|          |  |                  |

| MOT #10  |   | 2014-06-19 15:25 |
|----------|---|------------------|
| MOT test | number                                  | 298130274415     |
| Result   |   | ✓ Passed         |
| Notice   | O/s front anti roll bar link bent       |                  |
| Notice   | Inner edge of o/s front tyre tread worn |                  |





| MOT #9 |   | 2014-04-07 10:53 |
|--------|---|------------------|
| MOT te | st number   | 409187694024     |
| Result |   | 🗙 Failed         |
| Fail   | Offside rear parking brake recording little or no effort (3.7.B.6a)             |                  |
| Fail   | Nearside front brake binding (3.7.B.1)  |                  |
| Fail   | Offside Rear Suspension component mounting prescribed area is excessively corro | oded (2.4.A.3)   |
| Fail   | Nearside rear parking brake recording little or no effort (3.7.B.6a)            |                  |
| Fail   | Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)                  |                  |
| Notic  | e Inner edge of o/s front tyre tread slightly worn                              |                  |
| Fail   | Nearside Front Shock absorber has a serious fluid leak (2.7.3)                  |                  |
| Fail   | Parking brake: efficiency below requirements (3.7.B.7)                          |                  |

| MOT #8   |  | 2012-05-11 14:24 |
|----------|--|------------------|
| MOT test | number   | 248302832169     |
| Result   |  | ✓ Passed         |
| Notice   | Oil leak   |                  |
| Advice   | Offside Front Tyre worn close to the legal limit (4.1.E.1) |                  |
| Notice   | Hand brake only 17%  |                  |

| МОТ #7  | 2012-05-10 12:39 |  |  |
|---|------------------|--|--|
| MOT test number   | 746371132189     |  |  |
| Result  | 🗙 Failed         |  |  |
| Fail       Exhaust emissions carbon monoxide content excessive (7.3.B.1a)   |                  |  |  |
| <b>Advice</b> Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7) |                  |  |  |
| Notice Oil leak   |                  |  |  |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)   |                  |  |  |





| МОТ #6  | 2011-04-19 15:03 |
|---|------------------|
| MOT test number   | 816979001135     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #5  | 2009-12-21 11:35 |
| MOT test number   | 523575159394     |
| Result  | ✓ Passed         |
|   |                  |
| МОТ #4  | 2008-03-14 14:34 |
| MOT test number   | 301844778002     |
| Result  | ✓ Passed         |
|   |                  |
| МОТ #3  | 2008-03-13 10:39 |
| MOT test number   | 624543878094     |
| Result  | 🗙 Failed         |
| <b>Fail</b> Brakes imbalanced across an axle (3.7.B.5b) |                  |

FailNearside front brake binding (3.7.B.1)

| MOT #2          | 2006-11-22 12:59 |
|-----------------|------------------|
| MOT test number | 154896726349     |
| Result          | ✓ Passed         |

| MOT #1   | 2006-11-16 14:23        |  |
|--|-------------------------|--|
| MOT test number  | 472620426339            |  |
| Result   | 🗙 Failed                |  |
| <b>Fail</b> Offside Outer Rear Body or chassis has excessive corrosion, seriously affect<br>30cm of the body mountings (6.1.B.2)             | ing its strength within |  |
| Fail       Rear registration plate character(s) incorrectly spaced (6.3.4a)  |                         |  |
| FailNearside Outer Rear Body or chassis has excessive corrosion, seriously affecting its strength within30cm of the body mountings (6.1.B.2) |                         |  |
| <b>Fail</b> Front registration plate character(s) incorrectly spaced (6.3.4a)  |                         |  |



**G612SMV** report date: 2024-03-28

Tax & MOT check







### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |         |
|----------|---------|
| Date     | FETO    |
| Category | Lamp    |
| Туре     |         |
| Damage 2 | AMPL    |
|          | F Store |
| Date     | 1. E    |
| Category | amit    |
| Туре     |         |

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******  |             |
|---|-------------|
| **********  |             |
| *******   |             |
| ******  |             |
| ***********   |             |
| ********  |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this TOYOTA had different number plates. |             |
| Number of plates  |             |
| Current registration  |             |
| Plate since   |             |
| Current registration  |             |
| Plate since   |             |
|   | More info > |





### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info  $\rightarrow$ 





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 23         |
| First mileage registration | 1990-05-15 |
| Last registration          | 2023-05-24 |
| Complete history           | See info   |



| Registration #1                      | 1990-05-15 | 19 mi                                  |
|--------------------------------------|------------|--|
| Registration #2                      | 2006-11-16 | 101.437 mi                             |
| Registration #3                      | 2006-11-22 | 101.440 mi                             |
| Registration #4                      | 2008-03-13 | 102.294 mi                             |
| Registration #5                      | 2008-03-14 | 102.295 mi                             |
| Registration #6                      | 2009-12-21 | 102.343 mi                             |
| Registration #7                      | 2011-04-19 | 103.344 mi                             |
| Registration #8                      | 2012-05-10 | 105.714 mi                             |
| Registration #9                      | 2012-05-11 | 105.714 mi                             |
| Registration #10                     | 2014-04-07 | 108.452 mi                             |
| Registration #11                     | 2014-06-19 | 108.470 mi                             |
| Registration #12                     | 2015-06-16 | 110.949 mi                             |
| Registration #13                     |            | 11.777 mi                              |
| Registration #14                     |            | 11.777 esi                             |
| Registration #15                     |            | 11.777 mi                              |
| Registration #16                     |            | 11.777 esi                             |
| Registration #17                     |            | 11.777 mi                              |
| Registration #18                     |            | 11.777 esi                             |
| Registration #19                     |            | 11.777 mi                              |
| Registration #20                     |            | 11.777 mi                              |
|                                      |            |  |
| Registration #21                     |            | 11.777 mi                              |
| Registration #21<br>Registration #22 |            | 10.000 est                             |
| -                                    |            | 01.000 est<br>01.000 est<br>01.000 est |

More info >





## Car features

| S0225  | Air conditioning |
|--------|------------------|
| S0295  |                  |
| 50482  |                  |
| \$0501 |                  |
| S0566  |                  |
| \$0567 |                  |
| S0569  |                  |

| Dimensions & weight    |           |
|------------------------|-----------|
| Width                  | 1705 mm   |
| Height                 | 1300 mm   |
| Length                 | 4420 mm   |
| Additional information |           |
| Number of axles        | 2         |
| Engine number          | 359112419 |