



report date: 2024-03-29

General information

Make	NISSAN
Model	NAVARA DCI TEKNA 4X4 DCB
Colour	Black
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	450 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	39.2 mpg
Consumption combined	33.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-03
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-03-30
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	55
Total items failed	23

**MOT #12**

2023-03-31 09:45

MOT test number

373054441465

Result

✓ Passed

Next expiry date

2024-03-30

- Advice** Power steering pipe/hose slightly corroded Pump to rack (2.1.5 (g) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Rear Brake pipe clips or supports missing, pipe adequately supported Axle (1.1.11 (d) (i))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Brake pipe clips or supports missing, pipe adequately supported Axle (1.1.11 (d) (i))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Power steering pipe/hose slightly corroded Rack to oil cooler (2.1.5 (g) (i))

**MOT #11**

2023-03-15 13:08

MOT test number

179306196396

Result**✗ Failed**

- Fail** Exhaust system insecure all mountings failed (6.1.2 (a))
- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Offside Rear Inner Tyre has ply or cords damaged Sidewall (5.2.3 (d) (ii))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Leaf spring mounting (5.3.6 (a) (i))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Rear Brake pipe clips or supports missing, pipe adequately supported Axle (1.1.11 (d) (i))
- Fail** Offside Rear Inner Tyre has ply or cords exposed Sidewall (5.2.3 (d) (ii))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Oil leaking excessively from engine Sump leaking (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Power steering pipe/hose leaking to the rack (2.1.5 (a))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Brake pipe clips or supports missing, pipe adequately supported Axle (1.1.11 (d) (i))
- Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Leaf spring mounting (5.3.6 (a) (i))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #10**

2022-10-24 11:32

MOT test number

426984060375

Result

✗ Failed

Advice Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Fail** Front Power steering pipe/hose leaking pipes to the rack (2.1.5 (a))**Fail** Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced near front leaf spring mounting (6.1.1 (c) (i))**Fail** Rear Brake hose ferrule excessively corroded both (1.1.12 (f) (i))**Fail** Offside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))**Fail** Offside Rear Tyre fouling a part of the vehicle (5.2.3 (f))**Fail** Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced near front leaf spring mounting (6.1.1 (c) (i))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Front Brake hose ferrule excessively corroded both (1.1.12 (f) (i))**Fail** Offside Rear Leaf spring fractured (5.3.1 (b) (i))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Exhaust system insecure all mounts let go (6.1.2 (a))**MOT #9**

2021-11-18 11:13

MOT test number

287214754642

Result

✓ Passed

MOT #8

2020-11-20 10:16

MOT test number

818883509189

Result

✓ Passed

Minor Offside Windscreen damaged but not adversely affecting driver's view Cracked (3.2 (a) (i))**Advice** Suspension spring mounting prescribed area is corroded but not considered excessive Chassis (5.3.6 (a) (i))**Advice** Underbody re undersealed,

**MOT #7** 2020-11-19 10:23**MOT test number** 706632608413**Result** ✗ Failed**Fail** Fuel tank insecure Broken retaining strap (6.1.3 (a) (i))**Advice** Underbody re undersealed,**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Minor** Offside Windscreen damaged but not adversely affecting driver's view Cracked (3.2 (a) (i))**Advice** Suspension spring mounting prescribed area is corroded but not considered excessive Chassis (5.3.6 (a) (i))**Advice** Rear Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**MOT #6** 2019-07-04 15:25**MOT test number** 753495385946**Result** ✓ Passed**MOT #5** 2018-05-12 10:16**MOT test number** 991129683967**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Engine covers undertrays fitted

**MOT #4** 2018-05-12 10:16**MOT test number** 461674169167**Result** ✗ Failed

- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Engine covers undertrays fitted
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Pass with rectification** Nearside Headlamp aim too high (1.8)

MOT #3 2017-04-26 13:26**MOT test number** 409474791959**Result** ✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Brake pipe slightly corroded at end (3.6.B.2c)
- Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Brake pipe slightly corroded at end (3.6.B.2c)
- Advice** Engine covers and undertrays fitted

MOT #2 2016-03-28 11:54**MOT test number** 518925000237**Result** ✓ Passed

- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Outer Suspension arm has slight play in a ball joint (2.4.G.2)



MOT #1	2015-03-10 15:49
MOT test number	449029265027
Result	✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-30
Last registration	2023-03-31
Complete history	See info



Registration #1	2012-03-30	13 mi
Registration #2	2015-03-10	51.630 mi
Registration #3	2016-03-28	67.565 mi
Registration #4	2017-04-26	84.189 mi
Registration #5	2018-05-12	97.667 mi
Registration #6	2018-05-12	97.667 mi
Registration #7	2019-07-04	114.427 mi
Registration #8	2019-05-20	114.427 mi
Registration #9	2019-05-20	114.427 mi
Registration #10	2019-05-20	114.427 mi
Registration #11	2019-05-20	114.427 mi
Registration #12	2019-05-20	114.427 mi
Registration #13	2019-05-20	114.427 mi
Registration #14	2019-05-20	114.427 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	27862B