





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I30 COMFORT
Colour	Red
Year of manufacture	2010
Top speed	119 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	124 BHP	
Max. torque	157 Nm at 4.200 rpm	
Engine capacity	1.591 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	35.3 mpg	
Consumption extra urban	54.3 mpg	
Consumption combined	45.6 mpg	
CO2 emission	152 g/km	
CO2 label	G	



CarCheck.co.uk page 1/15




Internet history

Entry 2


Date 2021-08-07

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-01-31
Pictures	10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2025-01-23
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	59
Total items failed	12

MOT #17		2024-01-24 13:01
MOT test	number	940584109794
Result		✓ Passed
Next expi	ry date	2025-01-23
Minor (4.7.1 (b)	Offside Rear Registration plate lamp inoperative in the case of multiple lam_{\parallel}	ps or light sources
Advice	Rear Coil spring corroded both rear (5.3.1 (b) (i))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front Brake pipe corroded, covered in grease or other material both front (1.1.11 (c))
Advice	Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Overall underside body and components corroded	
Advice	Rear Brake pipe corroded, covered in grease or other material Both rear (1	.1.11 (c))
Advice	Front Suspension arm corroded but not seriously weakened Both front (5.3	.3 (b) (i))

CarCheck.co.uk page 3/15



MOT #16 2024-01-24 12:28

MOT test number 760634321871

Result X Failed

Advice Rear Coil spring corroded Both Sides (5.3.1 (b) (i))

Advice Overall underside body and components corrosion

Fail Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

Advice Rear Brake pipe corroded, covered in grease or other material Both Sides (1.1.11 (c))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front Front Lower both sides front lower suspension arms corroded

Advice Front Brake pipe corroded, covered in grease or other material Both Sides (1.1.11 (c))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15 2024-01-22 12:46

MOT test number 389520251119

Result × Failed

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Front Brake pipe corroded, covered in grease or other material Both Sides (1.1.11 (c))

Advice Front Front Lower both sides front lower suspension arms corroded

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Rear Coil spring corroded Both Sides (5.3.1 (b) (i))

Fail Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

Advice Rear Brake pipe corroded, covered in grease or other material Both Sides (1.1.11 (c))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Overall underside body and components corrosion

CarCheck.co.uk page 4/15



MOT #14 2022-12-29 13:13

MOT test number 756173426526

Result ✓ Passed

Advice Front Brake pipe corroded, covered in grease or other material both sides pipes (1.1.11 (c))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Rear Coil spring corroded both sides (5.3.1 (b) (i))

Advice Fuel tank corroded

Advice Rear Brake pipe corroded, covered in grease or other material both sides pipes (1.1.11 (c))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Front Lower both sides front lower suspension arms corroded

Advice Overall underside body and components corrosion

MOT #13 2021-12-30 17:58

MOT test number 845030123565

Result

Passed

Advice Rear both rear brake pipes corroded

Advice Fuel tank has corrosion

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Front both front brake pipes corroded

Advice Rear Coil spring corroded both sides (5.3.1 (b) (i))

Advice Front both front suspension arms corroded

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #12 2020-12-31 13:20

MOT test number 910381363451

Result / Passed

CarCheck.co.uk page 5/15



MOT #11 2020-12-22 11:57

MOT test number 233602233602

Result X Failed

Fail Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #10 2019-12-10 13:59

MOT test number 717374632112

Advice Front Service brake fluctuating, but not excessively both front (1.2.1 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))

Advice Rear Service brake binding but not excessively both rear (1.2.1 (f))

Advice Parking brake lever has little reserve travel

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Rear Service brake fluctuating, but not excessively both rear (1.2.1 (e))

CarCheck.co.uk page 6/15



MOT #9 2019-12-10 09:23

MOT test number 579149683899

Result X Failed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Rear Service brake fluctuating, but not excessively both rear (1.2.1 (e))

Advice Parking brake lever has little reserve travel

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Front Service brake fluctuating, but not excessively both front (1.2.1 (e))

Advice Rear Service brake binding but not excessively both rear (1.2.1 (f))

MOT #8 2018-12-20 11:22

MOT test number 622516756451

Result

Passed

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #7 2018-12-17 09:52

MOT test number 119764697893

Result X Failed

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Offside Front Lower Steering linkage ball joint ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

MOT #6 2017-11-28 15:05

MOT test number 568441238816

CarCheck.co.uk page 7/15



MOT #5 2017-11-28 10:25

MOT test number 797905209150

Result X Failed

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Nearside Front Upper anti roll bar linkage dust cover has sealer on it

Fail Offside Stop lamp not working (1.2.1b)

Fail Driver's door cannot be opened from inside the vehicle (6.2.B.1b)

MOT #4 2016-12-12 10:29

MOT test number 675556075910

Result ✓ Passed

MOT #3 2015-11-19 09:30

MOT test number 100241608260

Result
✓ Passed

MOT #2 2014-11-28 10:24

MOT test number 987782434327

Notice Nearside rear brake disc corroded on inner surface

Notice Nail in offside front tyre

MOT #1 2013-11-13 10:18

MOT test number 596757513301

Result

Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Both front tyres worn on inner edges

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-


CarCheck.co.uk page 9/15



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner	biotom,
UWNEI	nisioiv

e which misterly	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-11-30
Last registration	2024-01-24
Complete history	See info



Registration #1	2010-11-30	24 mi
Registration #2	2013-11-13	40.437 mi
Registration #3	2014-11-28	54.768 mi
Registration #4	2015-11-19	67.957 mi
Registration #5	2016-12-12	82.174 mi
Registration #6	2017-11-28	89.801 mi
Registration #7	2017-11-28	89.801 mi
Registration #8	2018-12-17	95.728 mi
Registration #9	2018-12-20	95.728 mi
Registration #10	2019-12-10	99.374 mi
Registration #11		11.177 es
Registration #12		71.777 es
Registration #13		11.177 es
Registration #14		77.777 46
Registration #15		11.177 es
Registration #16		77.777 46
Registration #17		11.177 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		11.777 es

More info >

CarCheck.co.uk page 14/15



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1775 mm
Height	1480 mm
Length	4245 mm
Wheel base	2650 mm
Kerb weight	1293 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	53
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles 2

Engine number G4FCAZ147266