





General information

| Make | HYUNDAI |
|---------------------|----------------------------|
| Model | TERRACAN CRTD STANDARD LTD |
| Colour | Silver |
| Year of manufacture | 2007 |
| Top speed | 103 mph |
| 0 - 60 mph | 13.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 148 BHP |
|-------------------------|---------------------|
| Max. torque | 333 Nm at 2.000 rpm |
| Engine capacity | 2.902 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 26.9 mpg |
| Consumption extra urban | 37.7 mpg |
| Consumption combined | 32.8 mpg |
| CO2 emission | 222 g/km |
| CO2 label | К |







Internet history

Entry 1

Date Pictures 2022-04-02

12

Listing price

View report









source: cargurus.co.uk



MOT history

| MOT expiry date | 2022-11-09 |
|--------------------|------------|
| MOT pass rate | 60 % |
| MOT passed | 12 |
| Failed MOT tests | 8 |
| Total advice items | 61 |
| Total items failed | 17 |

| MOT #20 | 2021-11-10 15:26 |
|------------------|------------------|
| MOT test number | 918220531854 |
| Result | ✓ Passed |
| Next expiry date | 2022-11-09 |

| MOT #19 | 2021-08-09 17:06 |
|---|----------------------|
| MOT test number | 760619188596 |
| Result | 🗙 Failed |
| Advice Suspension component corroded but not seriously weakened rear axle and spri (b) (i)) | ing holders (5.3.3 |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) | |
| Advice Vehicle structure is corroded but structural rigidity is not significantly reduced a (6.1.1 (c) (i)) | all chassis carroded |
| Advice Nearside Rear rear bumper bar excessivly carroded | |
| Advice Suspension arm corroded but not seriously weakened all suspension arms (5.3. | .3 (b) (i)) |
| Advice Exhaust has a minor leak of exhaust gases at join at rear (6.1.2 (a)) | |
| Advice Fuel Pipe/s corroded filler hoses | |
| Advice Integral body structure is corroded but structural rigidity is not significantly red sills and underside (6.1.1 (c) (i)) | luced both inner |
| Fail Nearside Rear Suspension component mounting prescribed area excessively corror reducing structural strength chassis at shock absorber top mount (5.3.6 (a) (i)) | ded significantly |





| MOT #18 | 2020-08-13 14:04 | |
|--|------------------|--|
| MOT test number | 324742630850 | |
| Result | ✓ Passed | |
| | | |
| MOT #17 | 2020-08-13 07:07 | |
| MOT test number | 823268982558 | |
| Result | × Failed | |
| Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b)) | | |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) | | |
| Fail Offside Rear Service brake excessively binding (1.2.1 (f)) | | |

| MOT #16 | 2019-08-20 07:50 |
|-----------------|------------------|
| MOT test number | 832534431227 |
| Result | ✓ Passed |

| MOT #15 | 2018-08-20 11:02 |
|--|----------------------------|
| MOT test number | 990706980721 |
| Result | ✓ Passed |
| Advice Central Front Upper Suspension component mounting prescribed considered excessive bumper panel (5.3.6 (a) (i)) | d area is corroded but not |
| MOT #14 | 2018-08-20 11.02 |

| MOT #14 | 2018-08-20 11:02 |
|--|--|
| MOT test number | 627666960093 |
| Result | × Failed |
| Pass with rectification | Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b)) |
| Advice Central Front Upper Suspension component mounting prescribed area is corroded but not considered excessive bumper panel (5.3.6 (a) (i)) | |



| HV57UCR |
|-------------------------|
| report date: 2024-03-28 |

| MOT #13 | 2017-08-18 11:57 | |
|---|------------------|--|
| MOT test number | 254997324144 | |
| Result | ✓ Passed | |
| Advice Slight brake bind o/s/r and n/s/f | | |
| Advice Exhaust system starting to get in poor condition | | |
| | | |
| MOT #12 | 2017-08-18 09:04 | |
| MOT test number | 678967056389 | |
| Result | 🗙 Failed | |
| Fail Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a) | | |
| Advice Slight brake bind o/s/r and n/s/f | | |
| Advice Exhaust system starting to get in poor condition | | |
| MOT #11 | 2016-07-26 08:55 | |
| | 2010-07-20-08.55 | |

| MOT test number | 610514260977 |
|-----------------|------------------|
| Result | ✓ Passed |
| | |
| MOT #10 | 2015-08-21 14:46 |

| MOT test number | 339133035442 |
|-----------------|--------------|
| Result | ✓ Passed |

| МОТ #9 | 2015-08-20 09:51 |
|--|------------------|
| MOT test number | 769512035204 |
| Result | 🗙 Failed |
| Fail Front Brake pipe excessively corroded (3.6.B.2c) | |



| MOT #8 | | 2014-10-02 16:30 |
|----------|--|------------------|
| MOT test | number | 116235974222 |
| Result | | ✓ Passed |
| Advice | Offside Front Brake pipe slightly corroded (3.6.B.2c) | |
| Advice | Nearside Front Brake pipe slightly corroded (3.6.B.2c) | |
| Notice | Slight oil leak at front diff | |
| MOT #7 | | 2014-10-02 15:45 |
| MOT #7 | number | 718645974285 |
| | | |
| Result | | 🗙 Failed |

| Nesult | × Falleu |
|---|----------|
| Advice Offside Front Brake pipe slightly corroded (3.6.B.2c) | |
| Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c) | |
| Notice Slight oil leak at front diff | |
| Fail Parking brake: efficiency below requirements (3.7.C.1b) | |

HV57UCR

report date: 2024-03-28



| MOT #6 | | 2014-03-05 16:53 |
|----------------------|---|------------------|
| MOT test | number | 379474764018 |
| Result | | ✓ Passed |
| Notice | Child seat fitted not allowing full inspection of adult belt | |
| Advice | Offside Front Brake pipe slightly corroded (3.6.B.2c) | |
| Notice | Front pads wearing thin | |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice ingress of | Nearside Front Upper Suspension arm ball joint dust cover deteriorated, but pre dirt (2.4.G.2) | eventing the |
| Advice | Nearside Front Brake pipe slightly corroded (3.6.B.2c) | |
| Notice | Exhaust rear joint deteriorated | |
| Advice | Front Brake pipe slightly corroded (3.6.B.2c) | |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |

HV57UCR

report date: 2024-03-28





| МОТ #5 | 2014-03-04 15:04 |
|--|------------------|
| MOT test number | 207633964084 |
| Result | 🗙 Failed |
| Fail Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3) | |
| Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) | |
| Advice Nearside Front Upper Suspension arm ball joint dust cover deteriorated, but pre- ingress of dirt (2.4.G.2) | venting the |
| Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c) | |
| Notice Brake fluid low | |
| Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c) | |
| Advice Front Brake pipe slightly corroded (3.6.B.2c) | |
| Fail Offside Front Windscreen washer provides insufficient washer liquid (8.2.3) | |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c) | |
| Notice Child seat fitted not allowing full inspection of adult belt | |
| Advice Front Brake pad(s) wearing thin (3.5.1g) | |
| Notice Exhaust rear joint deteriorated | |
| Advice Offside Front Brake pipe slightly corroded (3.6.B.2c) | |





| MOT #4 | | 2012-09-28 11:13 |
|--------------------------|---|-----------------------|
| MOT test | number | 566822172210 |
| Result | | ✓ Passed |
| Notice | Rear No.plate begining to delaminate. | |
| Notice | NSF, upper suspension ball joint gaiter leaking grease. | |
| Advice | Offside Rear Brake pipe slightly corroded (3.6.B.2c) | |
| Advice (2.5.C.1a) | Nearside Front Front constant velocity joint gaiter damaged, but preventing | g the ingress of dirt |
| Notice | OSF wiper rubber torn. | |
| Notice | Nail in nearside rear tyre | |
| Advice | Front Brake pad(s) wearing thin (3.5.1g) | |
| Advice | Offside Front Brake pipe slightly corroded (3.6.B.2c) | |





| MOT #3 | 2012-09-25 14:55 |
|---|------------------|
| MOT test number | 509299762281 |
| Result | 🗙 Failed |
| Fail Windscreen has a sticker or other obstruction encroaching into the swept area by moutside zone 'A' (8.3.1e) | ore than 40mm |
| Fail Nearside Headlamp aim too high (1.8) | |
| Notice Rear No.plate begining to delaminate. | |
| Advice Front Brake pad(s) wearing thin (3.5.1g) | |
| Notice NSF,upper suspension ball joint gaiter leaking grease. | |
| Advice Offside Front Brake pipe slightly corroded (3.6.B.2c) | |
| Fail Windscreen washer provides insufficient washer liquid (8.2.3) | |
| Notice OSF wiper rubber torn. | |
| Fail Intermediate drop arm damaged and unserviceable (2.2.C.1d) | |
| Notice Nail in nearside rear tyre | |
| Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c) | |
| Advice Nearside Front Front constant velocity joint gaiter damaged, but preventing the (2.5.C.1a) | ingress of dirt |

| MOT #2 | 2011-10-07 10:49 |
|---|------------------|
| MOT test number | 907800081218 |
| Result | ✓ Passed |
| Advice Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)Advice Nearside Headlamp damaged but light output not reduced (1.7.5a) | |





| MOT #1 | | 2010-09-24 17:01 |
|----------|--|------------------|
| MOT test | number | 323097560447 |
| Result | | ✓ Passed |
| Notice | Nsf headlamp mounting broken | |
| Notice | Osf and nsf tyres nearing leagal limit | |
| Notice | Child seat fitted not allowing full inspection of adult belt | |



Tax & MOT check

| X Untaxed | Х МОТ |
|-----------------------------|------------------------------------|
| Tax expired: 9 July 2022 | Expired: 9 November 2022 |
| Tax status | Expired at 9 July 2022 |
| Days left | 660 days too late |
| MOT expiry date | 9 November 2022 |
| Full MOT history | <u>See MOT history</u> |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | К |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| | |
| Date | \$ |
| Category | amp |
| Туре | |

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and the second | |
|---|-------------|
| ********** | |
| ******** | |
| ******* | |
| ******** | |
| ******** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| | |
| Number of plates | , |
| Current registration | |
| Plate since | 100.01.0 |
| Carrent registration | |
| Plate since | |

More info >





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 22 |
| First mileage registration | 2007-09-28 |
| Last registration | 2021-11-10 |
| Complete history | See info |



| Registration #1 | 2007-09-28 | 14 mi |
|------------------|------------|------------|
| Registration #2 | 2010-09-24 | 40.420 mi |
| Registration #3 | 2011-10-07 | 54.658 mi |
| Registration #4 | 2012-09-25 | 65.600 mi |
| Registration #5 | 2012-09-28 | 65.680 mi |
| Registration #6 | 2014-03-04 | 71.630 mi |
| Registration #7 | 2014-03-05 | 71.632 mi |
| Registration #8 | 2014-10-02 | 74.974 mi |
| Registration #9 | 2014-10-02 | 74.974 mi |
| Registration #10 | 2015-08-20 | 77.019 mi |
| Registration #11 | 2015-08-21 | 77.022 mi |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.707 esi |
| Registration #14 | | 11.777 est |
| Registration #15 | | 11.777 mi |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.777 mi |
| Registration #18 | | 11.777 est |
| Registration #19 | | 11.777 mi |
| Registration #20 | | 11.117 esi |
| Registration #21 | | 11.777 mi |
| Registration #22 | | 11.777 est |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| 50501 | |
| 60566 | |
| 60567 | |
| 50569 | |

Dimensions & weight

| Width | 1860 mm |
|---------------------|---------|
| Height | 1840 mm |
| Length | 4710 mm |
| Wheel base | 2750 mm |
| Kerb weight | 2265 kg |
| Max. allowed weight | 2620 kg |
| | |

Additional information

| Fuel tank capacity | 75 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | J3 924474 |