



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Grey
Year of manufacture	2007
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-01-10
Pictures	26
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2022-12-08
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	65
Total items failed	14

MOT #20	2021-12-09 15:09
MOT test number	829931997047
Result	✓ Passed
Next expiry date	2022-12-08

**MOT #19**

2021-11-30 17:26

**MOT test number**

367488405223

**Result****✗ Failed****Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Rear Sub-frame corroded and seriously weakened (5.3.3 (b) (i))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Suspension component mounting prescribed area is corroded but not considered excessive rear chassis (5.3.6 (a) (i))**MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Coil spring corroded (5.3.1 (b) (i))**Advice** Suspension component mounting prescribed area is corroded but not considered excessive front chassis (5.3.6 (a) (i))**MAJOR** Power steering malfunctioning (2.1.5 (a))**MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))**Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))

**MOT #18**

2020-10-16 15:26

**MOT test number**

747313327184

**Result**

✓ Passed

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material main brake pipe (1.1.11 (c))

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material main (1.1.11 (c))

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #17**

2020-10-06 09:00

**MOT test number**

146717008954

**Result**

✗ Failed

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MAJOR** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

**MAJOR** Nearside Front Suspension arm pin or bush excessively worn bush (5.3.4 (a) (i))

**MAJOR** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #16**

2019-09-25 07:49

**MOT test number**

243686749416

**Result**

✓ Passed

**MOT #15**

2018-09-24 08:44

**MOT test number**

459095734987

**Result**

✓ Passed

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14**

2017-10-12 11:06

**MOT test number**

978083314276

**Result**

✓ Passed

**MOT #13**

2016-10-18 11:29

**MOT test number**

376524673841

**Result**

✓ Passed

**Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Power steering component(s) has slight seepage from a component rack on (2.3.3b)**Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)**Advice** Unable to fully check outer sills due to plastic covers**Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Oil leak**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #12**

2016-10-17 11:15

**MOT test number**

977930921722

**Result****✗ Failed**

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Front Exhaust has a major leak of exhaust gases flexi section on (7.1.2)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Power steering component(s) has slight seepage from a component rack on (2.3.3b)
- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Rear Exhaust has a major leak of exhaust gases section of (7.1.2)
- Fail** Nearside rear brake binding (3.7.B.1)
- Advice** Oil leak
- Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Unable to fully check outer sills due to plastic covers
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

**MOT #11**

2015-10-02 15:51

**MOT test number**

723648797858

**Result****✓ Passed**

- Advice** Front Exhaust has a minor leak of exhaust gases flexy section (7.1.2)

**MOT #10** 2015-10-02 10:13**MOT test number** 495801186558**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Rear brake application uneven (3.7.B.2)**Advice** Front Exhaust has a minor leak of exhaust gases flexy section (7.1.2)**MOT #9** 2014-08-01 15:29**MOT test number** 945363414227**Result** ✓ Passed**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Offside front wiper blade split**MOT #8** 2014-07-19 10:08**MOT test number** 266220404262**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Offside front wiper blade split**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Offside rear handbrake low reading



**MOT #7** 2013-07-15 15:24**MOT test number** 639716793175**Result** ✓ Passed**Notice** Offside rear brake disc corroded**Notice** Front tyres right on limit with very worn outer edges**MOT #6** 2013-07-15 11:11**MOT test number** 168206693115**Result** ✗ Failed**Notice** Offside rear brake disc corroded**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Front brake pads very low**Fail** Nearside Front Body has a sharp edge caused by damage (6.1.C.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Notice** Front tyres right on limit with very worn outer edges**MOT #5** 2012-07-19 11:56**MOT test number** 338581202457**Result** ✓ Passed**MOT #4** 2011-07-22 08:57**MOT test number** 607073201244**Result** ✓ Passed**Notice** Both rear tyres worn low outer edges



MOT #3

2010-07-23 12:20

MOT test number

600054000263

Result

✓ Passed

Notice

N.s.r tyre outer side wall damaged but not through to ply cords

MOT #2

2010-07-22 13:40

MOT test number

370513900491

Result

✗ Failed

Notice

N.s.f tyre outer side wall damaged but not through to ply cords

Fail

Parking brake: efficiency below requirements (3.7.B.7)

Notice

Rear discs pitted

MOT #1

2010-05-10 10:07

MOT test number

292650430476

Result

✓ Passed

Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-06-04
Last registration	2021-12-09
Complete history	<a href="#">See info</a>



Registration #1	2007-06-04	27 mi
Registration #2	2010-05-10	32.343 mi
Registration #3	2010-07-22	33.369 mi
Registration #4	2010-07-23	33.370 mi
Registration #5	2011-07-22	44.704 mi
Registration #6	2012-07-19	55.732 mi
Registration #7	2013-07-15	66.684 mi
Registration #8	2013-07-15	66.688 mi
Registration #9	2014-07-19	77.346 mi
Registration #10	2014-08-01	77.876 mi
Registration #11	2015-10-02	89.106 mi
Registration #12	2016-05-20	95.277 mi
Registration #13	2016-05-20	95.277 mi
Registration #14	2016-05-20	95.277 mi
Registration #15	2016-05-20	95.277 mi
Registration #16	2016-05-20	95.277 mi
Registration #17	2016-05-20	95.277 mi
Registration #18	2016-05-20	95.277 mi
Registration #19	2016-05-20	95.277 mi
Registration #20	2016-05-20	95.277 mi
Registration #21	2016-05-20	95.277 mi
Registration #22	2016-05-20	95.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1312 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC6749744