

Ford



General information

Make	FORD
Model	RANGER DCB 4X4
Colour	Silver
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	330 Nm at 1.800 rpm
Engine capacity	2.500 cc
Cylinders	4
Fuel type	Diesel








Internet history

Entry 4		
Date	2021-10-30	
Pictures	14	
Listing price	View report	




source: autotrader.co.uk

Entry 3	
Date	2021-10-05
Pictures	12
Listing price	View report



source: autotrader.co.uk

Entry 2	
Date	2021-09-13
Pictures	12
Listing price	View report



source: autotrader.co.uk

Pictures

Listing price


12

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-22
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	62
Total items failed	14

MOT #18	2023-06-23 14:38
MOT test number	515387262744
Result	✓ Passed
Next expiry date	2024-06-22
Advice Central Upper Vehicle structure or chassis corroded within 30cm of a mounti- affecting overall security front to rear of vehicle (6.2.2 (d) (i))	ng, but not seriously
Advice Central Rear Leaf spring shackle bracket corroded but not seriously weakener springs corroded (5.3.1 (b) (i))	ed both rear leaf
Advice Offside Front Lower Suspension arm corroded but not seriously weakened (5	.3.3 (b) (i))
Advice Central Inner Vehicle structure or chassis corroded within 30cm of a mountin affecting overall security both sides of vehicles inner lower sills front to rear of vehicle (6	



MOT #17	2023-06-02 10:03
MOT test r	number 558398928128
Result	× Failed
MAJOR	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Advice	Both rea r leaf springs corroded
MAJOR (4.1.4 (b))	Nearside Front Headlamp has a product on the lens so that the light output is severely reduced
MAJOR	Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
MAJOR	Nearside Front Brake pipe excessively corroded (1.1.11 (c))
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
MAJOR	Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Nearside Rear Shock absorbers has negligible damping effect (5.3.2 (d))
MAJOR	Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
MAJOR	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
MAJOR	Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))
MAJOR	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
MAJOR (4.1.4 (b))	Offside Front Headlamp has a product on the lens so that the light output is severely reduced
MAJOR	Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Offside Front Brake pipe excessively corroded (1.1.11 (c))
MAJOR	Brake performance unable to be tested brake pipes corroded (1.2.1 (g))
MAJOR	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
MAJOR	Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d))
MAJOR	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))



MOT #16		2021-07-15 08:41
MOT test i	number	155370429899
Result		✓ Passed
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Oil leak, but not excessive rear diff (8.4.1 (a) (i))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Oil leak, but not excessive front diff (8.4.1 (a) (i))	

MOT #15		2021-07-13 15:25
MOT test	number	787287974405
Result		🗙 Failed
Advice	Oil leak, but not excessive rear diff (8.4.1 (a) (i))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
MAJOR	Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))	
Advice	Oil leak, but not excessive front diff (8.4.1 (a) (i))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11	. (c))
DANGEROUS Tyre tread depth below requirements of 1.6mm due to bulge in tyre (5.2.3 (e))		
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	



MOT #14		2021-06-25 16:38
MOT test	number	320693174966
Result		🗙 Failed
MAJOR	Rear fog lamp missing (4.5.1 (a) (ii))	
DANGER	OUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
MAJOR	Brake load sensing valve linkage defective and function impaired (1.1.17 (a))	
Advice	Offside front and nearside front brake pipes from flex hose at callipers slightly co	rroded
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR 30cm of a	Integral body structure or chassis has excessive corrosion, seriously affecting its body mounting NEARSIDE FRONT TO NEARSIDE REAR OUTER SILL AREA (6.2.2 (d)	2
MAJOR	Exhaust emissions exceed level of metered smoke for a turbo charged engine (8	.2.2.2 (b))

MOT #13	2020-10-01 15:59
MOT test number	369532854317
Result	✓ Passed

MOT #12	2019-01-15 15:52
MOT test number	719899292631
Result	✓ Passed

MOT #11		2019-01-15 13:03
MOT test	number	731341253300
Result		🗙 Failed
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	
MAJOR	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
MAJOR	Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))	
MAJOR	Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))	





MOT #10	2018-01-19 12:01
MOT test number	157814200398
Result	✓ Passed
МОТ #9	2016-11-10 14:26
MOT test number	654980806266
Result	✓ Passed
Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice Front Propshaft universal joint worn	
Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)	



MOT #8	3	2016-11-03 17:55
MOT te	st number	415432483570
Result		🗙 Failed
Fail	Horn not working (1.6.2a)	
Fail	Nearside Headlamp not working on main beam (1.7.5a)	
Fail	Offside Rear Brake pipe excessively corroded (3.6.B.2c)	
Fail	Nearside Rear Body has a sharp edge caused by damage (6.1.C.1)	
Advic	e Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Fail	Nearside Front Shock absorber has an excessively worn bush (2.7.4)	
Advic	e Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Fail	Nearside Headlamp not working on dipped beam (1.7.5a)	
Fail	Nearside Rear Brake pipe excessively corroded (3.6.B.2c)	
Fail	Offside Registration plate lamp not illuminating the registration plate (1.1.C.1e)	
Fail	Offside Rear Brake pipe excessively corroded front to rear (3.6.B.2c)	
Advic	e Front Propshaft universal joint worn	
Advic	e Offside Front Brake pipe slightly corroded (3.6.B.2c)	
L		

MOT #7	2015-10-07 08:38
MOT test number	647210731865
Result	✓ Passed





MOT #6		2014-10-06 12:29
MOT test	number	777739374288
Result		✓ Passed
Notice	Prop-shaft universal joint worn	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2013-09-19 08:47
MOT test number	305152463287
Result	✓ Passed

MOT #4		2013-09-19 08:47
MOT test number		855362163296
Result		🗙 Failed
Pass with rectification	Offside Headlamp not working on main beam (1.7.5a)	
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	

MOT #3	2012-09-12 15:22
MOT test number	816816052269
Result	✓ Passed



MOT #2		2012-09-12 12:18
MOT test I	number	978176652296
Result		🗙 Failed
Fail Of	ffside rear brake application uneven (3.7.B.2)	
Fail Ne	earside rear brake application uneven (3.7.B.2)	
Fail Ne	earside Front position lamp(s) not working (1.1.A.3b)	

MOT #1	2011-09-14 10:46
MOT test number	547657651200
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	



Tax & MOT check







Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	9
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-09-19
Last registration	2023-06-23
Complete history	See info



Registration #1	2008-09-19	14 mi
Registration #2	2011-09-14	71.799 mi
Registration #3	2012-09-12	95.269 mi
Registration #4	2012-09-12	95.269 mi
Registration #5	2013-09-19	111.308 mi
Registration #6	2014-10-06	117.716 mi
Registration #7	2015-10-07	123.503 mi
Registration #8	2016-11-03	137.359 mi
Registration #9	2016-11-10	137.359 mi
Registration #10	2018-01-19	143.059 mi
Registration #11	2019-01-15	150.722 mi
Registration #12		11.777 est
Registration #13		11.777 est
Registration #14		11.777 esi
Registration #15		11.117 esi
Registration #16		11.777 est
Registration #16 Registration #17		11.777 est 11.777 est
-		0.000 est 0.000 est 0.000 est
Registration #17		0.777 es 0.777 es 0.777 es 0.777 es
Registration #17 Registration #18		0.777 es 0.777 es 0.777 es 0.777 es
Registration #17 Registration #18 Registration #19		0.777 es 0.777 es 0.777 es 0.777 es 0.777 es





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
S0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Additional informationFuel tank capacity70 lFuel deliveryDirect InjectionNumber of doors4Number of seats5Engine number877850