



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 XC AWD D5 SE LUX
Colour	Blue
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	33.2 mpg



LABEL UNKNOWN



## Internet history

### Entry 3

Date 2022-03-05

Pictures 9

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 2

Date 2021-10-26

Pictures 16

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date 2021-06-27

Pictures 16

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #25</b>	2024-01-05 17:04
<b>MOT test number</b>	900561579310
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-01-11
<b>Advice</b>	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
<b>Advice</b>	Offside Front brake,pads, close to limit
<b>Advice</b>	Offside Front Service brake binding but not excessively (1.2.1 (f))
<b>Advice</b>	Offside Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. lazy (1.2.1 (b) (i))

<b>MOT #24</b>	2024-01-03 12:49
<b>MOT test number</b>	869784509370
<b>Result</b>	✗ Failed
<b>Fail</b>	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
<b>Fail</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))
<b>Advice</b>	Offside Front Service brake binding but not excessively (1.2.1 (f))
<b>Advice</b>	Nearside Front fog light out
<b>Fail</b>	Stop lamp(s) all not working (4.3.1 (a) (iii))
<b>Advice</b>	Offside Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. lazy (1.2.1 (b) (i))
<b>Fail</b>	Offside Front Position lamp not working (4.2.1 (a) (ii))
<b>Advice</b>	Offside Front brake,pads, close to limit
<b>Advice</b>	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
<b>Advice</b>	Nearside Rear revers light out

**MOT #23** 2023-01-12 15:17**MOT test number** 916725319494**Result** ✓ Passed

- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Surface rust under body
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**MOT #22** 2021-11-03 11:16**MOT test number** 445335261696**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21** 2021-10-26 07:22**MOT test number** 613948056006**Result** ✗ Failed

- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))

**MOT #20** 2020-10-21 13:04**MOT test number** 715887034153**Result** ✓ Passed**MOT #19** 2019-04-26 12:39**MOT test number** 573894339261**Result** ✓ Passed**MOT #18** 2019-04-25 11:03**MOT test number** 821061522216**Result** ✗ Failed**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #17** 2018-04-19 09:29**MOT test number** 709334739906**Result** ✓ Passed**MOT #16** 2017-04-21 15:33**MOT test number** 980135051202**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #15** 2016-04-04 16:08**MOT test number** 907051382489**Result** ✓ Passed

**MOT #14**

2014-03-27 09:40

**MOT test number**

638426784006

**Result**

✗ Failed

**Advice**

Front Tyre worn close to the legal limit (4.1.E.1)

**Fail**

Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**Pass with rectification**

Nearside Headlamp aim too high (1.8)

**Fail**

Nearside Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

**Fail**

Parking brake: efficiency below requirements (3.7.B.7)

**Fail**

Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**Fail**

Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

**Fail**

Rear Trailer electrical socket (13 pin) not operating the trailer lamps as intended (1.9.4)

**Fail**

Offside rear parking brake recording little or no effort (3.7.B.6a)

**MOT #13**

2013-04-02 11:40

**MOT test number**

359392193028

**Result**

✓ Passed

**Notice**

Advise offside rear upper tail light not working; lower pair work ok

**Notice**

Engine covers fitted obscuring some components in the engine bay

**Advice**

Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

**Notice**

Under-trays fitted obscuring some underside components

**MOT #12**

2013-04-02 10:09

**MOT test number**

407772493063

**Result****✗ Failed****Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Under-trays fitted obscuring some underside components**Advice** Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**Fail** Rear Registration plate lamp not working (1.1.C.1d)**Notice** Advise offside rear upper tail light not working; lower pair work ok**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #11**

2012-04-03 17:22

**MOT test number**

546334392065

**Result****✓ Passed****Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Off side front tyre wearing outer edge**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #10** 2012-04-03 17:22**MOT test number** 198754092096**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Notice** Under-trays fitted obscuring some underside components**Notice** Off side front tyre wearing outer edge**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #9** 2011-03-28 12:08**MOT test number** 678147581081**Result** ✓ Passed**MOT #8** 2011-03-28 10:24**MOT test number** 217547181000**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #7** 2010-04-14 16:28**MOT test number** 952464000107**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)



**MOT #6** 2010-04-13 14:56**MOT test number** 891553200195**Result** ✗ Failed**Fail** Rear Registration plate lamp not working (1.1.5c)**Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Offside Rear Anti-roll bar has excessive play in a pin/bush (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #5** 2009-04-15 16:00**MOT test number** 844435509150**Result** ✓ Passed**MOT #4** 2009-04-15 16:00**MOT test number** 884515809141**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2008-04-11 14:25**MOT test number** 894402508178**Result** ✓ Passed**MOT #2** 2008-04-10 10:32**MOT test number** 344461208190**Result** ✗ Failed**Fail** Offside Headlamp aim too low and too far to the right. (1.8)



MOT #1	2007-04-20 17:01
MOT test number	550340717125
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2004-04-13
Last registration	2024-01-05
Complete history	<a href="#">See info</a>



Registration #1	2004-04-13	18 mi
Registration #2	2007-04-20	64.487 mi
Registration #3	2008-04-10	75.619 mi
Registration #4	2008-04-11	75.656 mi
Registration #5	2009-04-15	84.222 mi
Registration #6	2010-04-13	91.865 mi
Registration #7	2010-04-14	91.884 mi
Registration #8	2011-03-28	99.517 mi
Registration #9	2011-03-28	99.517 mi
Registration #10	2012-04-03	106.273 mi
Registration #11	2013-04-02	115.383 mi
Registration #12	2013-04-02	115.383 mi
Registration #13	2014-03-27	123.577 mi
Registration #14	2016-04-04	124.290 mi
Registration #15	2016-04-04	124.290 mi
Registration #16	2016-04-04	124.290 mi
Registration #17	2016-04-04	124.290 mi
Registration #18	2016-04-04	124.290 mi
Registration #19	2016-04-04	124.290 mi
Registration #20	2016-04-04	124.290 mi
Registration #21	2016-04-04	124.290 mi
Registration #22	2016-04-04	124.290 mi
Registration #23	2016-04-04	124.290 mi
Registration #24	2016-04-04	124.290 mi
Registration #25	2016-04-04	124.290 mi
Registration #26	2016-04-04	124.290 mi

[More info >](#)





Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1860 mm
Height	1562 mm
Length	4733 mm
Wheel base	2763 mm
Kerb weight	1715 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	195069