





General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Silver
Year of manufacture	-
Top speed	137 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	152 BHP
Max. torque	366 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.1 mpg



MOT history

MOT #18		2020-10-26 11:08
MOT test	number	505554032740
Result		✓ Passed
Next expi	ry date	2021-10-25
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

MOT #17		2020-10-22 10:08
MOT test	number	444654683312
Result		🗙 Failed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weak	kened (1.1.14 (a) (ii))
MAJOR (a) (i))	Nearside Seat belt anchorage prescribed area strength or continuity sig	nificantly reduced (7.1.1
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weake	ened (1.1.14 (a) (ii))

MOT #16	2019-05-28 12:47
MOT test number	139801541622
Result	✓ Passed
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a)))
Advice Front Oil leak, but not excessive from bottom of eng	gine (8.4.1 (a) (i))
Advice Nearside Front Service brake fluctuating, but not ex	cessively (1.2.1 (e))
Advice Front Sub-frame corroded but not seriously weaken	ed (5.3.3 (b) (i))



MOT #15		2019-05-17 12:43
MOT test	number	323573551282
Result		🗙 Failed
MAJOR the ingress	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, n s of dirt (6.1.7 (g) (ii))	o longer prevents
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Front Oil leak, but not excessive from bottom of engine (8.4.1 (a) (i))	
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	

MOT #14		2018-03-12 16:01
MOT test	number	576131981360
Result		✓ Passed
Advice	Fuel Pipe/s corroded	
Advice	Power steering component(s) has slight seepage from a joint (2.3.3b)	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.	1i)
Advice	Offside Rear coil spring corroded (2.4.C.1b)	
Advice	Offside Rear Brake hose slightly deteriorated (3.6.B.4d)	
Advice	Offside Rear Brake pipe slightly corroded to front (3.6.B.2c)	
Advice	Engine covers and under trays fitted	
Advice	Oil leak	
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.	5.1i)
Advice	Nearside Rear coil spring corroded (2.4.C.1b)	
Advice	Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)	
Advice	Nearside Rear Brake pipe slightly corroded to front (3.6.B.2c)	



MOT #13 2018-03-12 10:07
MOT test number 363935060289
Result × Failed
Fail Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt drop link (2.4.G.2)
Advice Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)
Advice Offside Rear coil spring corroded (2.4.C.1b)
Advice Nearside Rear Brake pipe slightly corroded to front (3.6.B.2c)
Advice Fuel Pipe/s corroded
FailOffside Rear Outer Body or chassis has excessive corrosion, seriously affecting its strength within30cm of the body mountings sill (6.1.B.2)
Advice Power steering component(s) has slight seepage from a joint (2.3.3b)
Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice Nearside Rear coil spring corroded (2.4.C.1b)
Advice Offside Rear Brake hose slightly deteriorated (3.6.B.4d)
Advice Offside Rear Brake pipe slightly corroded to front (3.6.B.2c)
FailNearside Rear Outer Body or chassis has excessive corrosion, seriously affecting its strength within30cm of the body mountings sill (6.1.B.2)
Advice Oil leak
Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice Engine covers and under trays fitted



MOT #12		2017-03-23 12:00
MOT test	number	293094533417
Result		✓ Passed
Advice	Power steering component(s) has slight seepage from a component (2.3.3b)	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Engine covers and under trays fitted	
Advice	Oil leak	
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1	Li)

MOT #11	2017-03-22 09:48
MOT test number	334397011573
Result	🗙 Failed
Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the (4.1.D.1a)	ply or cords
Fail Nearside Front Lower Front suspension ball joint dust cover excessively damaged so prevents the ingress of dirt (2.4.G.2)	that it no longer
Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c)	
Fail Offside Rear brake caliper leaking (3.6.A.1)	
Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1	i)
Advice Power steering component(s) has slight seepage from a component (2.3.3b)	
Fail Nearside Front Anti-roll bar linkage has excessive play in a pin/bush and dust cover t	torn (2.4.G.2)
Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c)	
Advice Engine covers and under trays fitted	
Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5	.1i)
Advice Oil leak	



BK06	ULU
report date:	2024-03-28

MOT #10		2016-03-02 15:02
MOT test	number	522496761462
Result		✓ Passed
Advice	Rear coil springs coroded	
Advice	Offside Brake pipe slightly corroded front to rear (3.6.B.2c)	
Advice	Fuel pipes coroded	
Advice	Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)	
MOT #9		2016-02-27 09:45
MOT test	number	484949168803
Result		🗙 Failed
Fail	Nearside Rear Braking system leaking caliper (3.6.A.1)	

Fail	Nearside Rear Braking system leaking caliper (3.6.A.1)
Fail	Rear Exhaust system not adequately supported (7.1.1)
Advi	Rear coil springs coroded
Advi	Offside Brake pipe slightly corroded front to rear (3.6.B.2c)
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail preve	Nearside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer nts the ingress of dirt (2.4.G.2)
Advi	Fuel pipes coroded
Advi	Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)

MOT #8		2015-03-05 11:58
MOT test	number	869974665006
Result		🗸 Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Engine covers fitted obscuring some components in the engine bay	



MOT #7	2015-03-04 09:29
MOT test number	366783365018
Result	🗙 Failed
Fail Nearside Front coil spring broken (2.4.C.1a)	
Fail Offside Rear Shock absorber has an excessively worn bush (2.7.4)	
Notice Under-trays fitted obscuring some underside components	
Advice Rear Service brake: service brake efficiency only just met. It would appear that system requires adjustment or repair. (3.7.B.7)	t the braking
Fail Nearside Rear Shock absorber has an excessively worn bush (2.7.4)	
Fail Offside Inner Front constant velocity joint gaiter insecure to the extent that it no lo ingress of dirt etc (2.5.C.1a)	onger prevents the
Notice Engine covers fitted obscuring some components in the engine bay	

MOT #6		2014-03-27 09:25
MOT test r	number	479476484012
Result		✓ Passed
Advice (2.5.C.1a)	Offside Inner Front constant velocity joint gaiter deteriorated, but preventin	ng the ingress of dirt

MOT #5	2013-02-19 08:58
MOT test number	557640153077
Result	✓ Passed

MOT #4	2012-02-17 10:10
MOT test number	185668342038
Result	✓ Passed

BK06ULU

report date: 2024-03-28



BK06ULU report date: 2024-03-28

MOT #3	2011-03-16 12:36
MOT test number	168555671031
Result	✓ Passed
Notice Front wipers starting to smear the screen slightly	
Notice Offside rear tyre wearing on edges	
Notice Nearside rear tyre has 2mm of tread left and wearing on edges	
Notice Both rear springs corroded	
MOT #2	2010-03-18 17:07
MOT test number	794477070010
Result	✓ Passed
MOT #1	2009-03-18 13:39
MOT test number	192067379015
Result	✓ Passed





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lawer
Туре	(*******	
Damage 2		AMPLE
Damage 2		E CONTRACTOR
Date		
Category		AMP
Туре		

Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plat	tes.
Number of plates	7
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



BK06ULU report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-03-31
Last registration	2020-10-26
Complete history	See info



Registration #1	2006-03-31	17 mi
Registration #2	2009-03-18	28.355 mi
Registration #3	2010-03-18	35.418 mi
Registration #4	2011-03-16	42.463 mi
Registration #5	2012-02-17	48.095 mi
Registration #6	2013-02-19	57.979 mi
Registration #7	2014-03-27	69.979 mi
Registration #8	2015-03-04	78.775 mi
Registration #9	2015-03-05	78.775 mi
Registration #10	2016-02-27	90.920 mi
Registration #10 Registration #11	2016-02-27	90.920 mi
-		90.920 mi
Registration #11		90.920 mi
Registration #11 Registration #12		90.920 mi
Registration #11 Registration #12 Registration #13		90.920 mi
Registration #11 Registration #12 Registration #13 Registration #14		90.920 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15		90.920 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16		90.920 mi

More info \rightarrow



BK06ULU report date: 2024-03-28

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2035 kg
Additional information	
Additional information Fuel tank capacity	61 l
	61 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 4