



report date: 2024-03-28

General information

Make	MAZDA
Model	5 TS2
Colour	Silver
Year of manufacture	2007
Top speed	113 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg
CO2 emission	190 g/km
CO2 label	J



Internet history

Entry 1

Date	2022-07-07
Pictures	49
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-07
MOT pass rate	58 %
MOT passed	14
Failed MOT tests	10
Total advice items	101
Total items failed	20

MOT #242023-06-06 14:40

MOT test number303076884517

Result✓ Passed

Next expiry date2024-06-07

- AdviceSupplementary restraint system warning lamp does not illuminate (7.1.6 (a))
- AdviceNearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceOffside Rear Lower Coil spring corroded (5.3.1 (b) (i))
- MinorOffside Front Lower Sub-frame ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- AdviceFront and rear suspension components corroded
- AdviceOffside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- AdviceOffside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceNearside Rear Lower Coil spring corroded (5.3.1 (b) (i))
- AdviceOffside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceOffside Rear fuel filler pipe corroded
- AdviceNearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- AdviceNearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #23**

2023-06-06 14:40

MOT test number

282533451144

Result**✗ Failed**

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))

Advice Front and rear suspension components corroded

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Lower Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Front Lower Sub-frame ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Lower Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear fuel filler pipe corroded

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #22

2022-06-08 17:05

MOT test number

227499824470

Result**✓ Passed**

Advice Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Nearside Rear Lower Suspension arm corroded but not seriously weakened plus knuckle (5.3.3 (b) (i))

Advice Front Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Integral body structure is corroded but structural rigidity is not significantly reduced underfloor (6.1.1 (c) (i))

Advice Offside Rear Lower Suspension arm corroded but not seriously weakened plus kuckle (5.3.3 (b) (i))

**MOT #21**

2021-09-21 15:15

MOT test number

430950775198

Result

✓ Passed

- Advice** Underside vehicle heavy corrosion
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** All suspension components heavy corrosion

MOT #20

2021-09-10 13:48

MOT test number

644160803938

Result

✗ Failed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- DANGEROUS** Offside Front Wheel bearing so rough it is likely to overheat or break up (5.1.3 (b) (ii))
- MAJOR** Exhaust has a major leak of exhaust gases secondary kat (6.1.2 (a))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** All suspension components heavy corrosion
- MAJOR** Emissions not tested exhaust detached (8.2.1.2 (d))
- MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Underside vehicle heavy corrosion

**MOT #19**

2020-08-28 13:37

MOT test number

346301582705

Result

✓ Passed

- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear subframe and arms showing corrosion
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear disc brakes showing corrosion
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #18

2020-08-27 14:07

MOT test number

484437071556

Result

✗ Failed

- Advice** Rear disc brakes showing corrosion
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- MAJOR** Front Brakes imbalanced across an axle (1.2.1 (b) (i))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear subframe and arms showing corrosion
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))

**MOT #17** 2019-09-12 13:10**MOT test number** 452918502945**Result** ✓ Passed**Advice** Underside vehicle showing corrosion**Advice** All suspension components corrosion**MOT #16** 2019-09-12 13:10**MOT test number** 948821288064**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Underside vehicle showing corrosion**Advice** All suspension components corrosion**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #15** 2019-09-11 13:09**MOT test number** 263414917146**Result** ✗ Failed**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Underside vehicle showing corrosion**MAJOR** Nearside Headlamp aim not tested (4.1.2 (b))**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn drop link (5.3.4 (a) (i))**Minor** Tyre obviously under inflated both front (5.2.3 (l))**Advice** All suspension components corrosion**MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))**MAJOR** Offside Headlamp aim too low (4.1.2 (a))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #14** 2018-09-05 13:01**MOT test number** 242810658585**Result** ✓ Passed**Advice** Under side of vehicle corroded**Advice** Front bumper damaged**MOT #13** 2017-09-04 13:47**MOT test number** 404613943125**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear tyre on wear bars 205/55/16**Advice** Nearside Rear tyre showing perishing**MOT #12** 2017-09-04 10:02**MOT test number** 131720605537**Result** ✗ Failed**Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Rear tyre on wear bars 205/55/16**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear tyre showing perishing**MOT #11** 2016-08-31 15:24**MOT test number** 695528619768**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 205/55/16 inner edge (4.1.E.1)

**MOT #10**

2016-08-31 09:47

MOT test number

184638632247

Result**✗ Failed****Fail**

Nearside Front Shock absorber has a serious fluid leak (2.7.3)

Fail

Nearside Front Anti-roll bar has excessive play in a ball joint drop link (2.4.G.2)

Advice

Offside Rear Tyre worn close to the legal limit 205/55/16 inner edge (4.1.E.1)

Fail

Nearside Headlamp not working on dipped beam not tested (1.7.5a)

Fail

Offside Rear Shock absorber has a serious fluid leak (2.7.3)

Fail

Centre Exhaust has a major leak of exhaust gases section (7.1.2)

MOT #9

2015-09-03 15:43

MOT test number

428231893103

Result**✓ Passed****Advice**

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Rear exhaust heat shield insecure and in very poor condition

Advice

Centre exhaust section corroded and slight leaks



MOT #8	2015-09-03 09:53
MOT test number	570965804365
Result	✗ Failed
Fail	Nearside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement lower rear (2.4.G.2)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit 205/55 R16 (4.1.E.1)
Advice	Rear exhaust heat shield insecure and in very poor condition
Advice	Centre exhaust section corroded and slight leaks
Fail	Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement lower rear (2.4.G.2)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #7	2014-09-12 13:38
MOT test number	135655254297
Result	✓ Passed

**MOT #6** 2014-09-09 13:19**MOT test number** 607892654254**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Power steering fluid level close to minimum**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #5** 2013-09-10 11:04**MOT test number** 466353753286**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2012-08-02 12:37**MOT test number** 336145912477**Result** ✓ Passed**Notice** Both front lower rear suspension arm bushes splitting

**MOT #3** 2012-08-02 09:55**MOT test number** 939415612266**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Both front lower rear suspension arm bushes splitting**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Offside rear tyre soft**MOT #2** 2011-08-04 13:52**MOT test number** 798216311222**Result** ✓ Passed**MOT #1** 2010-08-17 15:14**MOT test number** 521609420298**Result** ✓ Passed**Notice** Both rear tyres wearing inside edge**Notice** Both rear trailing arm front bushes starting to split



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
7 June 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	7 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-09-01
Last registration	2023-06-06
Complete history	See info



Registration #1	2007-09-01	12 mi
Registration #2	2010-08-17	26.132 mi
Registration #3	2011-08-04	31.897 mi
Registration #4	2012-08-02	39.457 mi
Registration #5	2012-08-02	39.457 mi
Registration #6	2013-09-10	48.096 mi
Registration #7	2014-09-09	56.879 mi
Registration #8	2014-09-12	56.880 mi
Registration #9	2015-09-03	64.522 mi
Registration #10	2015-09-03	64.524 mi
Registration #11	2016-08-31	72.874 mi
Registration #12	2016-08-31	72.877 mi
Registration #13	2017-09-04	78.153 mi
Registration #14	2019-05-20	95.377 mi
Registration #15	2019-05-20	95.377 mi
Registration #16	2019-05-20	95.377 mi
Registration #17	2019-05-20	95.377 mi
Registration #18	2019-05-20	95.377 mi
Registration #19	2019-05-20	95.377 mi
Registration #20	2019-05-20	95.377 mi
Registration #21	2019-05-20	95.377 mi
Registration #22	2019-05-20	95.377 mi
Registration #23	2019-05-20	95.377 mi
Registration #24	2019-05-20	95.377 mi
Registration #25	2019-05-20	95.377 mi
Registration #26	2019-05-20	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1655 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1512 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	L8 20217257