



report date: 2024-03-29

General information

Make	MAZDA
Model	6 TAMURA
Colour	Blue
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	184 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-08
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history



MOT #22

2023-12-15 11:06

MOT test number

798621566734

Result

✗ Failed

- MAJOR** Nearside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Inner wing (6.1.1 (c) (i))
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn Top wish bone (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Vehicles internal headlight adjuster altered to recheck lights
- MAJOR** Nearside Front Vehicle structure inadequately repaired such that structural rigidity is significantly reduced Not fully seam welded. (6.1.1 (d) (i))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords several cuts (5.2.3 (d) (i))
- MAJOR** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- MAJOR** Nearside Rear Suspension arm pin or bush excessively worn Trailing arm (5.3.4 (a) (i))
- DANGEROUS** Offside Rear Suspension arm attachment bracket/mounting likely to become detached (5.3.3 (a) (ii))
- MAJOR** Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Inner sill & wheel arch. (6.1.1 (c) (i))
- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))
- MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Nearside Rear Suspension arm attachment bracket/mounting corroded and seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Smooth inner & outer edges. (5.2.3 (e))
- MAJOR** Central Inner Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Inner sill (6.1.1 (c) (i))
- MAJOR** Offside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Inner wing (6.1.1 (c) (i))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- MAJOR** Offside Front Vehicle structure inadequately repaired such that structural rigidity is significantly reduced

reduced Not fully seam welded. (6.1.1 (d) (i))

MAJOR Offside Front Suspension arm pin or bush excessively worn Top wish bone (5.3.4 (a) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Offside Rear Suspension arm pin or bush excessively worn Trailing arm (5.3.4 (a) (i))

Advice Central Front Items removed from driver's view prior to test

MAJOR Offside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced inner sill (6.1.1 (c) (i))

MAJOR Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MAJOR Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))

MAJOR Offside Rear Suspension arm attachment bracket/mounting corroded and seriously weakened (5.3.3 (b) (i))

DANGEROUS Nearside Rear Suspension arm attachment bracket/mounting likely to become detached (5.3.3 (a) (ii))

MAJOR Nearside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Inner sill (6.1.1 (c) (i))

MAJOR Nearside Rear Service brake excessively binding (1.2.1 (f))

MAJOR Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Inner sill (6.1.1 (c) (i))



MOT #212022-08-24 09:10

MOT test number447606515222

Result

✓ Passed

- Advice

Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice

UNDER BODY FULL CORRODED ALL HOLES WELDED
- Advice

Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice

Brake disc worn, pitted or scored, but not seriously weakened ALL ROUND (1.1.14 (a) (ii))

**MOT #20**

2022-01-17 08:29

MOT test number

708050172899

Result**✗ Failed**

- Advice** Outer and inner sills heavily corroded
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Underside heavily corroded
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Offside Front Brakes imbalanced across an axle (1.2.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

**MOT #19** 2021-01-16 09:36**MOT test number** 772432616912**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge of tyre worn (5.2.3 (e))**Advice** Nearside Front Small hole caused by corrosion underneath of vehicle not within 30cm**MOT #18** 2020-01-18 08:54**MOT test number** 503671672315**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Underside of vehicle slightly corroded**MOT #17** 2019-01-05 11:50**MOT test number** 880630751356**Result** ✓ Passed**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #16** 2019-01-05 10:14**MOT test number** 822107280314**Result** ✗ Failed

- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15 2018-01-18 11:03**MOT test number** 548178404023**Result** ✓ Passed**MOT #14** 2018-01-16 12:08**MOT test number** 679148435652**Result** ✗ Failed

- Fail** Nearside Front front brake binding (3.7.B.1)

**MOT #13** 2016-11-26 08:47**MOT test number** 596129495224**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Engine covers fitted**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #12** 2016-11-24 14:49**MOT test number** 582155300443**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Engine covers fitted**Fail** Nearside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #11** 2015-11-26 16:27**MOT test number** 197087618588**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt front (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10**

2015-11-26 09:16

MOT test number

907275484848

Result**✗ Failed**

Advice Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt rear (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt Rear (2.4.G.2)

Advice Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt front (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9

2014-12-05 16:27

MOT test number

429689634317

Result**✓ Passed**

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

Notice Both front and rear subframe and suspension components badly corroded but still structurally sound

MOT #8

2014-12-05 11:26

MOT test number

968309534324

Result**✗ Failed**

Fail Nearside Front wheel bearing rough when rotated (2.5.A.2)

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

Notice Both front and rear subframe and suspension components badly corroded but still structurally sound

**MOT #7** 2013-12-06 11:40**MOT test number** 129810143388**Result** ✓ Passed**Notice** Front brakes slightly binding**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Both rear tyres starting to crack**MOT #6** 2012-11-30 15:54**MOT test number** 649275132386**Result** ✓ Passed**MOT #5** 2012-11-30 14:48**MOT test number** 475785232311**Result** ✗ Failed**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** NEAR SIDE FRONT TYRE CRACKING**MOT #4** 2011-11-30 09:04**MOT test number** 328694231329**Result** ✓ Passed**MOT #3** 2010-12-07 12:27**MOT test number** 591731840385**Result** ✓ Passed**MOT #2** 2010-12-07 12:24**MOT test number** 674741940334**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)



MOT #1	2010-03-01 14:01
MOT test number	583010060061
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	YF56CLX
Plate since	2019-03-29
Current registration	YF56CLX
Plate since	2019-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-02-27
Last registration	2023-12-15
Complete history	See info



Registration #1	2007-02-27	18 mi
Registration #2	2010-03-01	28.422 mi
Registration #3	2010-12-07	33.987 mi
Registration #4	2010-12-07	33.987 mi
Registration #5	2011-11-30	43.110 mi
Registration #6	2012-11-30	54.157 mi
Registration #7	2012-11-30	54.157 mi
Registration #8	2013-12-06	64.110 mi
Registration #9	2014-12-05	78.013 mi
Registration #10	2014-12-05	78.013 mi
Registration #11	2015-11-26	82.267 mi
Registration #12	2015-11-26	82.267 mi
Registration #13	2016-11-26	82.267 mi
Registration #14	2017-11-26	82.267 mi
Registration #15	2018-11-26	82.267 mi
Registration #16	2019-11-26	82.267 mi
Registration #17	2020-11-26	82.267 mi
Registration #18	2021-11-26	82.267 mi
Registration #19	2022-11-26	82.267 mi
Registration #20	2023-11-26	82.267 mi
Registration #21	2024-11-26	82.267 mi
Registration #22	2025-11-26	82.267 mi
Registration #23	2026-11-26	82.267 mi
Registration #24	2027-11-26	82.267 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1435 mm
Length	4690 mm
Wheel base	2675 mm
Kerb weight	1375 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 10316922