





## General information

Make	HYUNDAI
Model	SANTA FE CRDI STYLE
Colour	Black
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 1.800 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.2 mpg
CO2 emission	197 g/km
CO2 label	J





# MOT history

MOT expiry date	2025-01-29
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	43
Total items failed	0

MOT #12	2024-01-15 12:49
MOT test number	974057010285
Result	✓ Passed
Next expiry date	2025-01-29
Advice Rear Suspension arm corroded but not seriously weakened Both r worn (5.3.3 (b) (i))	ear arms, bushes also slightly
<b>Minor</b> Offside Front Track rod end ball joint dust cover damaged or detering ingress of dirt Will require changing before next MoT (2.1.3 (g) (i))	orated, but preventing the
Advice Rear Coil spring corroded Both rear coils corroded (5.3.1 (b) (i))	
Advice Engine coolant and brake fluid low	
<b>Minor</b> Nearside Front Track rod end ball joint dust cover damaged or deterningress of dirt Will require changing before next MoT (2.1.3 (g) (i))	eriorated, but preventing the
Advice Front Headlamp has a product on the lens but not seriously reduct (4.1.4 (b))	ing light output Both front lenses
Advice Central Prop shaft bearing has slight play (6.1.7 (b) (i))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2	2 (a) (i))





MOT #11	L 202	24-01-15 11:36
MOT test	t number 2	234545170674
Result		🗙 Failed
<b>MAJOR</b> (b) (ii))	Nearside Front Suspension rod ball joint dust cover no longer prevents the ingress of	dirt (5.3.4
Advice	Rear Coil spring corroded Both rear coils corroded (5.3.1 (b) (i))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
<b>Advice</b> (4.1.4 (b))		h front lenses
Minor ingress of	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but prevent f dirt Will require changing before next MoT (2.1.3 (g) (i))	ing the
Advice	Central Prop shaft bearing has slight play (6.1.7 (b) (i))	
MAJOR (ii))	Offside Front Suspension rod ball joint dust cover no longer prevents the ingress of d	irt (5.3.4 (b)
Advice worn (5.3		lso slightly
Minor ingress of	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preve f dirt Will require changing before next MoT (2.1.3 (g) (i))	nting the
Advice	Engine coolant and brake fluid low	
	_	

MOT #10	2023-01-05 09:47
MOT test number	763702020739
Result	✓ Passed
Advice Rear Oil leak, but not excessive Diff leak (8.4.1 (a) (i))	
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Rear Coil spring corroded Both rear (5.3.1 (b) (i))	

MOT #9	2022-01-27 18:12
MOT test number	603681344922
Result	✓ Passed





MOT #8		2021-01-30 09:55
MOT test	number	964363282784
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MOT #7		2021-01-28 10:18
MOT test	number	758552502720
Result		× Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
MAJOR	Electronic stability control warning lamp indicates a fault (7.12 (e))	

MOT #6		2019-06-12 13:53
MOT test	number	278379078942
Result		✓ Passed
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
<b>Advice</b> (5.3.4 (a) (	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in exce (i))	essive movement
Advice	Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2	2 (b))
Advice	Advice Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
<b>Advice</b> (a) (i))	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in exces	sive movement (5.3.4





MOT #5	2019-06-06 13:	50
MOT test	number 3946366362	91
Result	× Fail	ed
Advice	Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	
<b>Minor</b> (4.7.1 (b)	Nearside Front Registration plate lamp inoperative in the case of multiple lamps or light sources (i))	
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
MAJOR	Parking brake lever missing parking brake broken (1.1.6 (d))	
MAJOR	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
<b>Advice</b> (a) (i))	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.	4
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Minor ingress of	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the dirt (2.1.3 (g) (i))	
MAJOR	Brake performance not tested parking brake cable broken (1.2.1 (g))	
MAJOR	Nearside Front Headlamp aim too high (4.1.2 (a))	
<b>Advice</b> (5.3.4 (a)	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (i))	

МОТ #4	2018-03-24 17:55
MOT test number	500646231689
Result	✓ Passed
Advice Rear Child Seat fitted not allowing full inspection of adult belt	

МОТ #3	2016-05-11 16:16
MOT test number	172344982592
Result	✓ Passed
MOT #2	2015-05-11 16:15
MOT test number	185751835111
Result	✓ Passed





MOT #1	2014-05-16 15:26
MOT test number	195216834124
Result	✓ Passed



Tax & MOT check

Taxed Tax due: 1 October 2024	✓ MOT Expires: 29 January 2025
Tax status	Valid until 1 October
Days left	156
MOT expiry date	29 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	S.
Category	ame
Туре	

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
*********	
And a second sec	
*******	
*********	
********	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-05-18
Last registration	2024-01-15
Complete history	See info



Registration #1	2011-05-18	8 mi
Registration #2	2014-05-16	49.602 mi
Registration #3	2015-05-11	66.035 mi
Registration #4	2016-05-11	83.293 mi
Registration #5	2018-03-24	97.948 mi
Registration #6	2019-06-06	102.502 mi
Registration #7	2019-06-12	102.502 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.117 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.117 esi

More info >





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1946 kg
Max. allowed weight	2570 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13