





report date: 2024-03-29

General information

Make	ТОУОТА
Model	LAND CRUISER D-4D LC3 5 SEATS
Colour	Grey
Year of manufacture	2003
Top speed	103 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	343 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	24.1 mpg
Consumption combined	30.1 mpg
CO2 emission	253 g/km
CO2 label	L



CarCheck.co.uk page 1/15



report date: 2024-03-29

MOT history

MOT expiry date	2022-04-21
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	24
Total items failed	32

MOT #23	2021-04-22 12:31
MOT test number	469978026061
Result	✓ Passed
Next expiry date	2022-04-21
Advice Front Sub-frame corroded but not seriously weakened and rear (5.3.3 (b) (i)) Advice Lower Vehicle structure is corroded but structural rigidity is not significantly reduced both sides sill and chassis (6.1.1 (c) (i))	

MOT #22	2019-05-24 18:27
MOT test number	874720169127
Result	✓ Passed

CarCheck.co.uk page 2/15



report date: 2024-03-29

MOT #21 2019-05-11 10:22

MOT test number 342511949293

Result X Failed

Advice Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Fail Nearside Front Body mounting fixings insecure (6.2.2 (c) (i))

Fail Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Fail Offside Front Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting (6.2.2 (d) (i))

Fail Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #20 2018-05-01 16:28

MOT test number 698100549091

Result \(\sqrt{Passed} \)

Advice Underside very dirty and slight corrosion

MOT #19 2018-05-01 16:28

MOT test number 564510787177

Result × Failed

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Underside very dirty and slight corrosion

MOT #18 2017-03-24 17:39

MOT test number 260017062611

Result \(\sqrt{Passed} \)

Advice Nearside Front Lower Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #17 2017-03-21 10:31

MOT test number 178313283053

Result

× Failed

Fail Nearside Front Inner Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Nearside Front Upper Suspension arm has excessive play in a ball joint (2.4.G.2)

Fail Offside Front Lower Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Nearside Front Lower Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Fail Offside Front Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Fail Offside Front Upper Suspension arm has excessive play in a ball joint (2.4.G.2)

Fail Offside Front Upper Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

Fail Nearside Front Front position lamp(s) not working (1.1.A.3b)

Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

MOT #16 2016-03-15 13:08

MOT test number 961922887130

Result

Passed

Advice Ns and os inner seals slightly corroded

MOT #15 2016-03-11 12:31

MOT test number 892741133958

Result

× Failed

Fail Offside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

Advice Ns and os inner seals slightly corroded

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #14

MOT test number

Result

Notice Vehicle underside very corroded

Notice Rear fuel lines damp

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #13 2015-03-13 10:10 **MOT** test number 715052575021 X Failed Result Fail Offside Front Upper Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2) Fail Nearside Front Brake pipe excessively corroded (3.6.B.2c) Fail Offside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2) Fail Rear fog lamp not working (1.3.2b) Notice Vehicle underside very corroded Fail Nearside Front Upper Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2) Fail Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a) Fail Nearside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2) **Notice** Rear fuel lines damp **Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a) Fail Front registration plate deteriorated (6.3.1d)

 MOT #12
 2014-03-17 15:14

 MOT test number
 265996174021

 Result
 ✓ Passed

CarCheck.co.uk page 5/15



Fail

NG53HZN

report date: 2024-03-29

MOT #	÷11	2014-03-13 15:29
MOT t	est number	106702474434
Result		X Failed
Fail	Nearside Registration plate lamp not working (1.1.C.1d)	
Fail	Offside Rear fog lamp not working (1.3.2b)	
Fail	Rear Fuel hose leaking (7.2.3)	

MOT #10	2013-03-27 11:54
MOT test number	926396683082
Result	✓ Passed
MOT #9	2013-03-22 12:12
MOT test number	125761083485
Result	🗙 Failed
Fail Nearside Registration plate lamp not working (1.1.C.1d)	
Advice Nearside Front Track rod end ball joint has slight play (2.2.B.1f)	

MOT #8	2012-03-26 08:39
MOT test number	347606482057
w tr	- D I

Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

Result		✓ Passed
MOT #7		2011-03-23 11:04
MOT test numb	er	276672681061
Result		✓ Passed
	te pipe slightly corroded (3.6.B.2c) worn close to the legal limit (4.1.E.1)	
Advice	worn close to the legal little (4.1.E.1)	

CarCheck.co.uk page 6/15



MOT #4

NG53HZN

report date: 2024-03-29

2008-12-02 11:53

MOT #6 2011-03-22 14:28 228651281005 **MOT** test number Result × Failed **Advice** Tyre worn close to the legal limit (4.1.E.1) **Advice** Front Brake pad(s) wearing thin (3.5.1g) Fail Brake pedal creeps down when held under pressure (3.3.B.1a) Advice Brake pipe slightly corroded (3.6.B.2c) Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

 MOT #5
 2009-11-30 16:17

 MOT test number
 494554739482

 Result
 ✓ Passed

MOT test number 592557838321

Result Passed

MOT #3

MOT test number

Result

Notice 2X FRONT TYRES WEARING UNEVENLY

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2 2007-12-07 15:31 MOT test number 121071647337

Notice 2X FRONT TYRES WEARING UNEVENLY

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #1 2006-12-01 13:03

MOT test number 292515236377

Result ✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-29

Tax & MOT check



Tax expired: 1 February 2021

X MOT

Expired: 21 April 2022

Tax status	Expired at 1 February 2021
Days left	1182 days too late
MOT expiry date	21 April 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Correct registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-12-17
Last registration	2021-04-22
Complete history	See info



Registration #1	2003-12-17	18 mi
Registration #2	2006-12-01	32.729 mi
Registration #3	2007-12-07	42.093 mi
Registration #4	2008-12-02	50.333 mi
Registration #5	2009-11-30	61.049 mi
Registration #6	2011-03-22	70.637 mi
Registration #7	2011-03-23	70.637 mi
Registration #8	2012-03-26	76.597 mi
Registration #9	2013-03-22	84.126 mi
Registration #10	2013-03-27	84.137 mi
Registration #11	2014-03-13	93.266 mi
Registration #12	2014-03-17	93.373 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 esi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	1980 kg

Additional information

Fuel tank capacity	87 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	1KD1001042

CarCheck.co.uk page 15/15