





report date: 2024-03-28

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Blue
Year of manufacture	2006
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/16



report date: 2024-03-28


Internet history

Entry 1

Date 2021-10-08

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



SK56HWZ report date: 2024-03-28

MOT history

MOT expiry date	2024-11-26
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	38
Total items failed	22

MOT #23	2023-11-25 11:21
MOT test number	645641722869
Result	✓ Passed
Next expiry date	2024-11-26
Advice Nearside Rear Wheel bearing slightly noisy (5.1.3 (b)	(i))
Advice Nearside Front Seat belt webbing slightly damaged or	frayed (7.1.2 (b) (ii))
Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice Rear Suspension component mounting prescribed area is corroded but not considered excessive nearside and offside (5.3.6 (a) (i))	
Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b)	(i))
Advice Nearside Rear Tyre slightly damaged/cracking or peris	shing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/16



report date: 2024-03-28

MOT #22 2023-11-24 18:11

MOT test number 381408147808

Result X Failed

Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Fail Central Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Rear Suspension component mounting prescribed area is corroded but not considered excessive nearside and offside (5.3.6 (a) (i))

Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #21 2022-11-18 17:45

MOT test number 152602136279

Result \(\sqrt{Passed} \)

Advice Rear Suspension component pin or bush slightly worn axle bushes nearside and offside (5.3.4 (a) (i))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Rear Suspension component mounting prescribed area is corroded but not considered excessive nearside and offside (5.3.6 (a) (i))

Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Front Inner Steering linkage ball joint has slight play (2.1.3 (b) (i))

CarCheck.co.uk page 4/16



report date: 2024-03-28

MOT #20 2021-11-27 21:10

MOT test number 535989789085

Result ✓ Passed

Minor

Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

MOT #19 2020-10-08 16:03

MOT test number 728859790964

Advice Fuel Pipe/s corroded

MOT #18 2019-09-19 14:22

MOT test number 352805329533

Result ✓ Passed

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened very slightly

(1.1.14 (a) (ii))

Advice Oil level low

Advice Oil leak at oil filter

CarCheck.co.uk page 5/16



Advice

Oil leak at oil filter

SK56HWZ

report date: 2024-03-28

MOT #17 2019-09-18 15:17 **MOT** test number 209638924818 Result × Failed Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Brake pipe excessively corroded centre section of n/s front to rear (1.1.11 (c)) Advice Oil level low Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened very slightly (1.1.14 (a) (ii)) Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii)) Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) Fail

MOT #16 2018-09-21 13:19
MOT test number 832922359340
Result ✓ Passed

MOT #15 2018-09-19 15:53
MOT test number 537057834682

Result X Failed

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Nearside Front Brake pipe excessively corroded (1.1.11 (c))

MOT #14 2017-09-21 13:35

MOT test number 184726882031

Result ✓ Passed

CarCheck.co.uk page 6/16



report date: 2024-03-28

MOT test number

Result

Advice Exhaust has a minor leak of exhaust gases slight blow (7.1.2)

Advice Eml on

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #12 2016-09-22 13:50 **MOT** test number 157102955225 Result × Failed Advice Exhaust has a minor leak of exhaust gases slight blow (7.1.2) Eml on **Advice** Fail Nearside Stop lamp adversely affected by the operation of another lamp on constant with sidelamp (1.2.1f)Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c) **Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c) Fail Offside Front Front position lamp(s) not working (1.1.A.3b) Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

 MOT #11
 2015-09-18 13:51

 MOT test number
 689536980190

 Result
 ✓ Passed

MOT test number

Result

Pass with rectification

Windscreen wiper does not clear the windscreen effectively both (8.2.2)

Pass with rectification

Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f)

CarCheck.co.uk page 7/16



MOT #6

SK56HWZ

report date: 2024-03-28

2012-09-27 15:05

MOT #9

MOT test number

417217994129

Result

Notice N/s mirror broken

MOT test number

Result

Fail Nearside Track rod end ball joint has excessive play (2.2.B.1f)

Fail Nearside Front Macpherson strut worn and seriously weakened (2.4.G.1)

Notice N/s mirror broken

 MOT #7
 2013-07-17 10:54

 MOT test number
 765098193130

 Result
 ✓ Passed

MOT test number 205911172268

Result

Result ✓ Passed

MOT #5 2012-09-27 13:06
MOT test number 185321972204

Result X Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Fail Rear registration plate has a feature which changes the appearance or legibility of the characters (6.3.4c)

Fail Front registration plate has a feature which changes the appearance or legibility of the characters (6.3.4c)

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT #4 2011-09-20 11:26 **MOT test number** 565703661247 Result ✓ Passed 2010-09-28 16:54 MOT #3 733001570257 **MOT** test number Result ✓ Passed MOT #2 2009-09-25 15:29 **MOT test number** 732538769231 Result ✓ Passed MOT #1 2009-09-24 14:31 772537969265 **MOT test number** Result **X** Failed Fail Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Notice Oil leak at filter

CarCheck.co.uk page 9/16



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	26 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 10/16



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



SK56HWZ report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK Nie
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 13/16



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 14/16



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2006-09-28
Last registration	2023-11-25
Complete history	See info



Registration #1	2006-09-28	21 mi
Registration #2	2009-09-24	22.471 mi
Registration #3	2009-09-25	22.471 mi
Registration #4	2010-09-28	27.145 mi
Registration #5	2011-09-20	32.904 mi
Registration #6	2012-09-27	40.540 mi
Registration #7	2012-09-27	40.540 mi
Registration #8	2013-07-17	44.667 mi
Registration #9	2014-07-16	51.060 mi
Registration #10	2014-07-16	51.060 mi
Registration #11	2015-09-18	58.614 mi
Registration #12	2015-09-18	58.614 mi
Registration #13	2016-09-22	63.965 mi
Registration #14		11.777 46
Registration #15		D.777 es
Registration #16		11.777 46
Registration #17		D.777 es
Registration #18		11.777 es
Registration #19		D.777 es
Registration #20		11.777 es
Registration #21		D.777 est
Registration #22		50 500 au
registration // 22		
Registration #23		11,177 es
		11.777 eac
Registration #23		11,777 ea 11,777 ea 11,777 ea



SK56HWZ report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 16

Number of axles2Engine number6L33722