





## General information

Make	JAGUAR
Model	X-TYPE V6 SPORT
Colour	Blue
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	157 BHP
Max. torque	200 Nm at 4.100 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	22.2 mpg
Consumption extra urban	39.8 mpg
Consumption combined	30.7 mpg





# Internet history

Entry	1
Date	

Pictures

2021-06-15

11

Listing price

View report



source: autotrader.co.uk



NG03DSZ report date: 2024-03-28

## MOT history

MOT #28	2023-12-28 14:41
MOT test	<b>number</b> 434886134438
Result	× Failed
<b>MAJOR</b> (5.2.3 (d)	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (i))
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
MAJOR	Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Rear Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
Minor	Brake master cylinder below minimum mark (1.1.10 (d) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Windscreen washer not working (3.5 (a))
MAJOR (b))	Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
MAJOR	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
MAJOR	Offside Parking brake inoperative on one side (1.4.1 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Driver's door cannot be opened from outside the vehicle (6.2.3 (a))
MAJOR	Nearside Windscreen washer not working (3.5 (a))

MOT #27	2022-12-20 16:19
MOT test number	528569297029
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))	
<b>Advice</b> Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))	



NG03DSZ
report date: 2024-03-28

МОТ #26	2022-12-19 15:50
MOT test number	578754938653
Result	🗙 Failed
<b>MAJOR</b> Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
<b>DANGEROUS</b> Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Offside Rear Suspension component mounting prescribed area is corrode excessive (5.3.6 (a) (i))	ed but not considered
<b>MAJOR</b> Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Nearside Rear Suspension component mounting prescribed area is corror excessive (5.3.6 (a) (i))	ded but not considered
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>MAJOR</b> Driver's door cannot be opened from outside the vehicle (6.2.3 (a))	

MOT #25		2021-12-21 13:31
MOT test	number	611292952016
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Inner edge. (5.2.3 (e))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	



NG03DSZ report date: 2024-03-28

MOT #24	2021-12-16 14:41
MOT test number	426607593202
Result	🗙 Failed
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
<b>MAJOR</b> Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
<b>DANGEROUS</b> Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
<b>DANGEROUS</b> Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	)
Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
<b>MAJOR</b> Offside Parking brake inoperative on one side (1.4.1 (a))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge Inner edge. (5.2.3 (e))	
<b>MAJOR</b> Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))	

MOT #23	2020-11-23 16:16
MOT test number	224167549488
Result	✓ Passed
Advice N/s/r wheel bearing slightly no	isy
MOT #22	2020-11-20 13:48

MOT test i	number 99	7421301396
Result		🗙 Failed
Advice	N/s/r wheel bearing slightly noisy	
MAJOR	Offside Rear Lower Suspension arm pin or bush excessively worn inner bush (5.3.4 (a)	(i))



MOT #21		2019-12-05 18:03
MOT test	number	926620541212
Result		✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	

# MOT #20

мот	test	number	

1	Result		🗙 Failed
	Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
	Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
	MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	
	MAJOR	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))	

МОТ #19	2018-11-21 14:07
MOT test number	196962001765
Result	✓ Passed

MOT #18	2017-12-14 11:07
MOT test number	887611327519
Result	✓ Passed

MOI #1/	2016-10-24 11:00
MOT test number	185568082858
Result	✓ Passed

MOT #16	2015-11-16 14:36
MOT test number	882028065061
Result	✓ Passed

NG03DSZ

report date: 2024-03-28

2019-12-05 13:44

558086955717



NG03DSZ	
report date: 2024-03-28	

MOT #15	2015-10-27 11:24
MOT test number	647356923892
Result	✓ Passed
MOT #14	2015-10-27 11:24
MOT test number	249707694804
Result	× Failed
<b>Pass with rectification</b> within zone 'A' (8.3.1b)	Windscreen has a sticker or other obstruction encroaching by more than 10mm
MOT #13	2014-11-24 14:55
MOT test number	845968724399
Result	✓ Passed
MOT #12	2014-11-24 11:52
MOT test number	969978324304
Result	× Failed
Fail Offside Rear Trailing	g arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
MOT #11	2013-11-22 15:06
MOT test number	909936323301
Result	✓ Passed
Advice Offside Rear Tra	iling arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)



MOT #10		2013-11-21 16:06
MOT test	: number	749735523311
Result		🗙 Failed
<b>Fail</b>	Brake pipe excessively corroded (3.6.B.2c)	
<b>Fail</b>	Brake pipe excessively corroded (3.6.B.2c)	
Fail	Brake pipe excessively corroded (3.6.B.2c)	
<b>Advice</b> (2.4.G.2)	5	novement

MOT #9		2012-11-22 11:46
MOT test	number	135997722348
Result		✓ Passed
Advice	Nearside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)	
Advice	Nearside Front Vehicle structure has slight corrosion (6.1.B.2)	
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Front Vehicle structure has slight corrosion (6.1.B.2)	
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Brake pipe slightly corroded (3.6.B.2c)	

MOT #8	2011-11-22 13:11
MOT test number	426536221454
Result	✓ Passed
Advice Offside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)	

NG03DSZ

report date: 2024-03-28





MOT #7	2010	-12-14 12:07
MOT test number	10	4698840307
Result		🗸 Passed
MOT #6	2010	0-12-14 12:07
MOT test number	64	3868340361
Result		🗙 Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (8.2.3)	
MOT #5	2009	-12-08 11:02
MOT test number	34	1302549346
Result		✓ Passed
Advice Front brake disc	slightly pitted (3.5.1h)	
МОТ #4	2008	3-12-08 11:25
MOT test number	19	00333048379
Result		✓ Passed
MOT #3	2007	/-12-03 11:52
MOT test number	58	32037337347
Result		✓ Passed
MOT #2	2006	5-12-21 16:05
MOT test number	17	3535656375
Result		🗸 Passed
MOT #1	2006	5-04-28 11:11
MOT test number	85	3108716104
Result		🗸 Passed





### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CATED ON
Date	*
Category	AMP
Туре	

#### Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	
************	
********	
******	
************	
********	
	More info >
Plate changes See in this check if this JAGUAR had different number pla	tes.
Number of plates	*
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



NG03DSZ report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2003-04-30
Last registration	2023-12-28
Complete history	See info



Registration #1	2003-04-30	29 mi
Registration #2	2006-04-28	17.004 mi
Registration #3	2006-12-21	19.702 mi
Registration #4	2007-12-03	22.711 mi
Registration #5	2008-12-08	25.360 mi
Registration #6	2009-12-08	27.118 mi
Registration #7	2010-12-14	29.702 mi
Registration #8	2011-11-22	31.250 mi
Registration #9	2012-11-22	34.022 mi
Registration #10	2013-11-21	36.047 mi
Registration #11	2013-11-22	36.047 mi
Registration #12	2014-11-24	37.464 mi
Registration #13	2014-11-24	37.464 mi
Registration #14	2015-10-27	38.827 mi
Registration #15	2015-10-27	38.827 mi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.777 est
Registration #21		11.777 est
Registration #22		11.777 est
Registration #23		11.777 est
Registration #24		11.777 est
Registration #25		11.777 esi
Registration #26		11.777 mi
CarCheck.co.uk		page 14/15

Registration #27	10.317 esi
Registration #28	11.777 est
Registration #29	11.117 esi





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1450 kg
Additional information	
Fuel tank capacity	61 I
Fuel delivery	
	Multi-Point Injection
Number of doors	4
Number of doors Number of axles	·