



T820UEW

report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA SRI 16V
Colour	Red
Year of manufacture	1999
Top speed	112 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	38.7 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-31
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-11
MOT pass rate	86 %
MOT passed	18
Failed MOT tests	3
Total advice items	46
Total items failed	3

MOT #21 2023-07-06 07:38

MOT test number 262466038531

Result ✓ Passed

Next expiry date 2024-07-11

Advice Offside Rear Tyre slightly damaged/cracking or perishing inner sidewall (5.2.3 (d) (ii))**Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

MOT #20 2022-07-02 10:17

MOT test number 600246468109

Result ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner arch (5.3.6 (a) (i))

MOT #19 2021-06-29 10:12

MOT test number 689092476317

Result ✓ Passed

MOT #18 2020-06-16 12:05

MOT test number 361172742285

Result ✓ Passed

**MOT #17** 2020-06-16 08:27**MOT test number** 890353883423**Result** ✗ Failed

MAJOR Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #16 2019-06-27 14:00**MOT test number** 169948781047**Result** ✓ Passed**MOT #15** 2018-07-02 11:35**MOT test number** 938108859481**Result** ✓ Passed**MOT #14** 2017-06-29 10:43**MOT test number** 209207108922**Result** ✓ Passed

Advice Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)

MOT #13 2016-07-04 10:04**MOT test number** 501931891492**Result** ✓ Passed

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #12 2015-06-17 13:17**MOT test number** 786468965180**Result** ✓ Passed

**MOT #11**

2014-06-19 16:09

MOT test number

266230674422

Result

✓ Passed

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Offside rear (outer skin holed-inner skin intact)**Notice** Nearside rear (outer skin holed-inner skin intact)**MOT #10**

2013-07-03 16:08

MOT test number

119984083175

Result

✓ Passed

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Notice** N/s/f strut dust cover split**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Notice** O/s/f strut dust cover split**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #9**

2013-07-03 16:08

MOT test number

757354683149

Result

✗ Failed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Notice** O/s/f strut dust cover split**Pass with rectification** Centre Stop lamp not working (1.2.1b)**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Notice** N/s/f strut dust cover split

**MOT #8** 2012-06-25 13:06**MOT test number** 209217272169**Result** ✓ Passed

- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

MOT #7 2011-06-15 10:38**MOT test number** 476796761157**Result** ✓ Passed

- Notice** O/s and n/s rear strut dust covers split
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Notice** O/s and n/s front strut dust covers split
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2010-07-12 09:58**MOT test number** 792983490126**Result** ✓ Passed

- Notice** Corroded hole on n/s/r outer seal

MOT #5 2009-06-30 12:36**MOT test number** 690901289107**Result** ✓ Passed

- Notice** N/S/R outer sill holed inner ok
- Advice** Offside Front constant velocity joint gaiter deteriorated (2.5.C.1a)
- Advice** Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)

**MOT #4** 2008-07-01 12:33**MOT test number** 380783688102**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Notice** Front numberplate cracked, backing starting to lift & contaminate, but plate easily read.**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Outer Front constant velocity joint gaiter deteriorated (2.5.C.1a)**MOT #3** 2008-07-01 12:33**MOT test number** 994683488113**Result** ✓ Passed**Advice** Offside Outer Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Notice** Front numberplate cracked, backing starting to lift & contaminate, but plate easily read.**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated (2.5.C.1a)**MOT #2** 2007-07-04 10:06**MOT test number** 664935987131**Result** ✓ Passed**Advice** Offside Rear brake disc slightly pitted (3.5.1h)**Notice** Surface corrosion on ferrule ends of rear brake hoses.**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear brake disc slightly pitted (3.5.1h)**Notice** Surface corrosion on metal brake pipes under vehicle.**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Front numberplate cracked, but secure.



MOT #1	2006-07-12 08:45
MOT test number	483123296147
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
11 July 2024

Tax status	Valid until 1 July
------------	--------------------

Days left	62
-----------	----

MOT expiry date	11 July 2024
-----------------	--------------

Full MOT history	See MOT history
------------------	---------------------------------



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	1999-06-18
Last registration	2023-07-06
Complete history	See info



Registration #1	1999-06-18	17 mi
Registration #2	2006-07-12	27.924 mi
Registration #3	2007-07-04	29.388 mi
Registration #4	2008-07-01	31.106 mi
Registration #5	2009-06-30	32.769 mi
Registration #6	2010-07-12	34.097 mi
Registration #7	2011-06-15	35.224 mi
Registration #8	2012-06-25	36.176 mi
Registration #9	2013-07-03	37.071 mi
Registration #10	2014-06-19	37.924 mi
Registration #11	2015-06-17	38.641 mi
Registration #12	2016-06-17	39.358 mi
Registration #13	2017-06-17	40.075 mi
Registration #14	2018-06-17	40.792 mi
Registration #15	2019-06-17	41.509 mi
Registration #16	2020-06-17	42.226 mi
Registration #17	2021-06-17	42.943 mi
Registration #18	2022-06-17	43.660 mi
Registration #19	2023-06-17	44.377 mi
Registration #20	2024-06-17	45.094 mi
Registration #21	2025-06-17	45.811 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1690 mm
Height	1395 mm
Length	4120 mm

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	GA16570985