


Ford



General informationMakeFORDModelTRANSIT CONNECT T200 L SWB P/VColourSilverYear of manufacture-Gearbox5 speed Manual

Engine & fuel consumption

| Power | 89 BHP |
|-------------|---------------------|
| Max. torque | 220 Nm at 1.750 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |





MOT history

| MOT #22 | | 2021-11-22 08:14 |
|-----------|--|-------------------|
| MOT test | number | 784089177724 |
| Result | | ✓ Passed |
| Next expi | ry date | 2022-11-21 |
| Advice | Offside Rear Brake pipe corroded, covered in grease or other material to l | hose (1.1.11 (c)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #21 | 2021-11-16 08:53 |
|---|--------------------|
| MOT test number | 181021944536 |
| Result | 🗙 Failed |
| Advice Offside Rear Brake pipe corroded, covered in grease or other material to hose (| 1.1.11 (c)) |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Horn sound not in accordance with requirements (7.7 (c)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Rear Exhaust has a major leak of exhaust gases (6.1.2 (a)) | |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light (i)) | sources (4.7.1 (b) |

| MOT #20 | 2020-11-05 15:11 |
|-----------------|------------------|
| MOT test number | 320280788563 |
| Result | ✓ Passed |
| | |

| MOT #19 | 2020-11-02 10:20 |
|-----------------|------------------|
| MOT test number | 174697318965 |
| Result | × Failed |

Fail Nearside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill coroded (5.3.6 (a) (i))

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Rear Suspension component mounting prescribed area excessively damaged significantly reducing structural strength outer sill coroded (5.3.6 (a) (i))





| MOT #18 | 2019-07-04 10:05 |
|--|--------------------------|
| MOT test number | 209146542483 |
| Result | ✓ Passed |
| | |
| MOT #17 | 2019-07-03 07:46 |
| MOT test number | 936506349720 |
| Result | 🗙 Failed |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no ingress of dirt (6.1.7 (g) (ii)) | longer prevents the |
| Fail Exhaust emissions exceed level of metered smoke for a non-turbo charged | d engine (8.2.2.2 (b)) |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Fail Nearside Vehicle structure corroded to the extent that the rigidity of the as reduced sill (6.1.1 (c) (i)) | ssembly is significantly |
| Fail Front Fuel pipe leaking pump (6.1.3 (b) (i)) | |
| | |
| MOT #16 | 2018-08-09 13:37 |

MOT test number

Result

| MOT # | 15 | 2018-08-09 07:39 |
|------------------------|---|---------------------|
| MOT te | est number | 280277135021 |
| Result | | 🗙 Failed |
| Fail | Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i)) | |
| Fail ingress | Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no s of dirt (6.1.7 (g) (ii)) | longer prevents the |
| Fail | Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) | |

184155455774

✓ Passed



| MOT #3 | 14 | 2017-07-19 07:57 |
|-----------------------|--|------------------------|
| MOT te | st number | 446892319011 |
| Result | | ✓ Passed |
| Advid | e Injectors blowing | |
| Advid | Gearbox mounting defective | |
| | | |
| MOT # | 13 | 2016-07-22 06:49 |
| MOT te | st number | 276828127005 |
| Result | | Passed |
| | | |
| MOT #3 | 12 | 2016-07-21 08:05 |
| MOT te | st number | 452625866675 |
| Result | | 🗙 Failed |
| Fail | Offside Front Headlamp not working on dipped beam (1.7.5a) | |
| Fail | Nearside Front Anti-roll bar insecure (2.4.G.1) | |
| Fail 30cm c | Nearside Body or chassis has an unsatisfactory modification, seriously affecti of the body mountings sill (6.1.B.2) | ng its strength within |
| Fail | Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |
| Fail | Nearside Front Inner Drive shaft which forms part of the suspension coupling | gaiter damaged to the |

extent that it no longer prevents the ingress of dirt etc (2.4.G.4e)

| MOT #11 | | 2015-07-14 10:12 |
|--------------------------|---|---------------------|
| MOT test | number | 869705695153 |
| Result | | ✓ Passed |
| Advice | Offside Inner Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice (2.5.C.1a) | Nearside Inner Front constant velocity joint gaiter damaged, but preventing | the ingress of dirt |

KS07KVB

report date: 2024-03-29





| MOT #10 | 2014-06-30 10:47 |
|--|------------------|
| MOT test number | 575541184198 |
| Result | 🗸 Passed |
| | |
| MOT #9 | 2014-06-30 09:46 |
| MOT test number | 388201784157 |
| Result | 🗙 Failed |
| Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b) | |
| | |
| MOT #8 | 2013-06-26 13:57 |
| MOT test number | 229367773448 |
| Result | ✓ Passed |
| | |
| MOT #7 | 2013-06-26 09:42 |
| MOT test number | 567327073147 |
| Result | 🗙 Failed |
| Fail Nearside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2) | |
| Fail Brakes imbalanced across an axle (3.7.B.5b) | |

| MOT #6 | 2012-04-23 12:15 |
|-----------------|------------------|
| MOT test number | 375084412121 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2011-06-20 10:15 |
| MOT test number | 269941271414 |

🗸 Passed





| MOT #4 2011-06-18 09 MOT test number 439319161 Result X Fa Fail Parking brake: efficiency below requirements (3.7.B.7) |
|--|
| |
| Fail Parking brake: efficiency below requirements (3.7.B.7) |
| |
| MOT #3 2011-06-17 1 |
| MOT test number 209158061 |
| Result × Fa |
| Fail Parking brake: efficiency below requirements (3.7.B.7) |
| MOT #2 2010-06-17 08 |
| MOT test number 621448360 |
| Result VPas |
| MOT #1 2010-06-14 1 |
| MOT test number 734175360 |
| Result × Fa |
| Fail Nearside Front Front wheel bearing rough when rotated (2.5.A.2) |
| Fail Nearside Registration plate lamp not working (1.1.C.1d) |
| FailNearside Front Front wheel bearing has excessive play (2.5.A.3c) |
| Fail Nearside Stop lamp not working (1.2.1b) |
| Fail Offside Registration plate lamp not working (1.1.C.1d) |





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|--|-------|
| Date | | |
| Category | | ARMP |
| Туре | | |
| Damage 2 | | AMPLE |
| | E E | AT I |
| Date | | * |
| Category | AMA | |
| Туре | No. Contraction of the second se | |

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******* | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 23 |
| First mileage registration | 2007-07-04 |
| Last registration | 2021-11-22 |
| Complete history | See info |



| Registration #1 | 2007-07-04 | 28 mi |
|------------------|------------|------------|
| Registration #2 | 2010-06-14 | 70.351 mi |
| Registration #3 | 2010-06-17 | 70.460 mi |
| Registration #4 | 2011-06-17 | 100.834 mi |
| Registration #5 | 2011-06-18 | 100.834 mi |
| Registration #6 | 2011-06-20 | 100.834 mi |
| Registration #7 | 2012-04-23 | 109.111 mi |
| Registration #8 | 2013-06-26 | 116.842 mi |
| Registration #9 | 2013-06-26 | 116.842 mi |
| Registration #10 | 2014-06-30 | 121.708 mi |
| Registration #11 | 2014-06-30 | 121.708 mi |
| Registration #12 | 2015-07-14 | 126.932 mi |
| Registration #13 | | 11.777 esi |
| Registration #14 | | 11.777 esi |
| Registration #15 | | 11.777 mi |
| Registration #16 | | 11.777 esi |
| Registration #17 | | 11.117 es |
| Registration #18 | | 11.117 esi |
| Registration #19 | | 11.777 esi |
| Registration #20 | | 11.117 est |
| Registration #21 | | 11.777 est |
| Registration #22 | | 11.117 est |
| Registration #23 | | 11.777 esi |
| | | |

More info >





Car features

| S0225 | Air conditionin |
|--------|-----------------|
| \$0295 | |
| S0482 | |
| \$0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Dimensions & weight

| Width | 2044 mm |
|---------------------|---------|
| Height | 598 mm |
| Length | 4278 mm |
| Kerb weight | 1410 kg |
| Max. allowed weight | 2035 kg |

Additional information

| Fuel tank capacity | 60 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 2 |
| Engine number | 6M34983 |