



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRTD CDX
Colour	Black
Year of manufacture	-
Top speed	99 mph
0 - 60 mph	14.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	111 BHP
Max. torque	260 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	36.7 mpg
Consumption combined	30.7 mpg



LABEL UNKNOWN



MOT history

MOT #20	2020-06-17 10:41
MOT test number	355169635377
Result	✓ Passed
Next expiry date	2021-06-16
Advice	Brake disc worn, pitted or scored, but not seriously weakened Both rear (1.1.14 (a) (ii))
Advice	Rear exhaust corroded

MOT #19	2020-06-17 08:38
MOT test number	590731914296
Result	✗ Failed
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Offside Headlamp lens seriously defective (4.1.1 (b) (ii))
Advice	Both front brake flex pipes insecure
Fail	Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened Both rear (1.1.14 (a) (ii))
Advice	Rear exhaust corroded

MOT #18	2019-05-01 11:13
MOT test number	971605626327
Result	✓ Passed

MOT #17	2019-05-01 11:13
MOT test number	545742827888
Result	✗ Failed
Pass with rectification	Stop lamp(s) all not working (4.3.1 (a) (iii))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a))
Pass with rectification	Offside Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #16** 2018-05-02 15:39**MOT test number** 187719832327**Result** ✓ Passed**MOT #15** 2018-05-02 14:05**MOT test number** 629752340741**Result** ✗ Failed

Fail Central Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

Fail Brake pedal anti-slip provision incomplete (3.3.A.1b)

MOT #14 2017-04-05 09:19**MOT test number** 890671200322**Result** ✓ Passed

Advice Rear exhaust box in poor condition and blowing on inner tail pipe

Advice Front outer cv boots perishing

Advice Nearside Rear Outer Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Offside Front Upper coil spring corroded (2.4.C.1b)

Advice Near side front steering rack boot full of fluid suspect rack leaking by seals

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Front Upper coil spring corroded (2.4.C.1b)

**MOT #13** 2016-04-21 08:18**MOT test number** 949395282580**Result** ✓ Passed**Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Front abs drive shaft target rings broken**Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Rear exhaust box in poor condition**MOT #12** 2016-04-21 08:18**MOT test number** 476471735358**Result** ✗ Failed**Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Advice** Front abs drive shaft target rings broken**Pass with rectification** Offside Front Steering retaining device missing (2.2.C.1g)**Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Rear exhaust box in poor condition**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**MOT #11** 2015-04-27 16:12**MOT test number** 356427515187**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)

**MOT #10** 2015-04-25 14:19**MOT test number** 489885515148**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)**Fail** Nearside Front Steering rack gaiter split (2.2.D.2d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2014-04-27 12:14**MOT test number** 208627014473**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Items removed from driver's view prior to test**MOT #8** 2013-04-06 14:25**MOT test number** 526386693039**Result** ✓ Passed**MOT #7** 2013-04-06 13:09**MOT test number** 158266493093**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)**MOT #6** 2012-04-18 11:26**MOT test number** 237939502406**Result** ✓ Passed



MOT #5	2011-04-04 17:32
---------------	------------------

MOT test number	476214491086
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2010-03-29 15:42
---------------	------------------

MOT test number	580778780097
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2009-04-07 15:52
---------------	------------------

MOT test number	910507299037
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2008-04-03 11:12
---------------	------------------

MOT test number	204694298071
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2008-04-03 11:12
---------------	------------------

MOT test number	772644498029
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Front Headlamp aim too low (1.8)
--------------------------------	---

Pass with rectification	Offside Front Headlamp aim too low (1.8)
--------------------------------	--



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-04-11
Last registration	2020-06-17
Complete history	See info



Registration #1	2005-04-11	10 mi
Registration #2	2008-04-03	44.463 mi
Registration #3	2009-04-07	57.954 mi
Registration #4	2010-03-29	69.249 mi
Registration #5	2011-04-04	79.871 mi
Registration #6	2012-04-18	84.653 mi
Registration #7	2013-04-06	88.604 mi
Registration #8	2013-04-06	88.604 mi
Registration #9	2014-04-27	95.539 mi
Registration #10	2015-04-25	103.090 mi
Registration #11	2016-04-25	110.541 mi
Registration #12	2017-04-25	117.992 mi
Registration #13	2018-04-25	125.443 mi
Registration #14	2019-04-25	132.894 mi
Registration #15	2020-04-25	140.345 mi
Registration #16	2021-04-25	147.796 mi
Registration #17	2022-04-25	155.247 mi
Registration #18	2023-04-25	162.698 mi
Registration #19	2024-04-25	170.149 mi
Registration #20	2025-04-25	177.600 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1730 mm
Length	4500 mm
Wheel base	2620 mm
Kerb weight	1718 kg
Max. allowed weight	2520 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4EA4546055