



Mercedes-Benz

 **KS08VBM**

report date: 2024-03-29

General information

Make	MERCEDES
Model	SPRINTER 311 CDI LWB CC
Colour	Black
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.600 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-23
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-20
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	52
Total items failed	12

MOT #18 2023-12-21 10:21

MOT test number 756791637559

Result ✓ Passed

Next expiry date 2024-12-20

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive spring mount area (5.3.6 (a) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive spring mount area (5.3.6 (a) (i))

MOT #17 2023-12-14 16:22

MOT test number 882529960010

Result ✗ Failed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive spring mount area (5.3.6 (a) (i))

MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MAJOR Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive spring mount area (5.3.6 (a) (i))

MAJOR Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))

MAJOR Nearside Front Headlamp aim too low (4.1.2 (a))



MOT #16	2023-11-09 17:45
MOT test number	859408314943
Result	✗ Failed
MAJOR	Offside Front Brake pipe excessively corroded (1.1.11 (c))
MAJOR	Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive spring mounting area (5.3.6 (a) (i))
MAJOR	Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
MAJOR	Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
DANGEROUS	Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))
MAJOR	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
MAJOR	Nearside Front Brake pipe excessively corroded (1.1.11 (c))
MAJOR	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
MAJOR	Brake performance unable to be tested fractured/leaking brake pipe (1.2.1 (g))
MAJOR	Offside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive spring mounting area (5.3.6 (a) (i))
MAJOR	Offside Rear Inner Integral body structure inadequately repaired such that structural rigidity is significantly reduced sill (6.1.1 (d) (i))
MAJOR	Nearside Headlamp aim too high (4.1.2 (a))
MAJOR	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
DANGEROUS	Offside Rear Brake pipe at imminent risk of failure or fracture fractured/leaking (1.1.11 (a))
MAJOR	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #15**

2022-03-09 12:21

MOT test number

318486053316

Result

✓ Passed

Advice Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Suspension spring mounting repair covered in underseal (5.3.6 (a) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14

2022-03-09 12:21

MOT test number

225974474217

Result

✗ Failed

Advice Offside Rear Suspension spring mounting repair covered in underseal (5.3.6 (a) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13

2021-03-04 15:50

MOT test number

386667926191

Result

✓ Passed

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Suspension component mounting repair covered in underseal (5.3.6 (a) (i))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #12

2020-03-03 14:22

MOT test number

510605526200

Result

✓ Passed

**MOT #11** 2020-03-03 14:22**MOT test number** 286904158678**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #10** 2019-03-09 11:41**MOT test number** 374828396211**Result** ✓ Passed**Advice** Offside Rear seal is heavily under-sealed**MOT #9** 2018-02-27 13:19**MOT test number** 297821915611**Result** ✓ Passed**MOT #8** 2017-03-03 11:42**MOT test number** 167167352899**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Play in steering rack inner joint(s)**Advice** Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #7** 2015-07-24 11:57**MOT test number** 899935605255**Result** ✓ Passed**MOT #6** 2014-07-24 11:18**MOT test number** 577485104289**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)

**MOT #5** 2013-07-17 12:38**MOT test number** 839448493152**Result** ✓ Passed**Notice** Emissions to clean to take reading**Advice** Nearside Front Shock absorber has slight external damage to the casing (2.7.2a)**MOT #4** 2013-07-16 10:18**MOT test number** 425487293196**Result** ✗ Failed**Notice** Emissions to clean to take reading**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Fail** Nearside Rear reflector excessively damaged so that its function is impaired (1.5.1c)**Fail** Nearside Rear Leaf spring to axle securing bolt insecure (2.4.B.7b)**Fail** Offside Rear Anti-roll bar linkage worn and seriously weakened (2.4.G.1)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Front Shock absorber has slight external damage to the casing (2.7.2a)**Fail** Rear fog lamp not working (1.3.2b)**Fail** Offside Rear Leaf spring to axle securing bolt insecure (2.4.B.7b)**Fail** Offside Rear Anti-roll bar worn and seriously weakened (2.4.G.1)**MOT #3** 2012-07-24 12:46**MOT test number** 926306802262**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Play in steering rack inner joint(s)



MOT #2	2011-05-20 14:19
MOT test number	287810541141
Result	✓ Passed
Advice	Nearside Front Ball joint has slight play (2.2.B.1f)
Advice	Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #1	2011-05-20 09:25
MOT test number	875730041126
Result	✗ Failed
Fail	Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
Advice	Nearside Front Ball joint has slight play (2.2.B.1f)
Fail	Nearside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
Advice	Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
Fail	Front registration plate deteriorated (6.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
20 December 2024

Tax status		Valid until 1 June
Days left		32
MOT expiry date		20 December 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 KS08VBM
Plate since	2024-03-29
Current registration	 KS08VBM
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-06-01
Last registration	2023-12-21
Complete history	See info



Registration #1	2008-06-01	28 mi
Registration #2	2011-05-20	59.647 mi
Registration #3	2011-05-20	59.647 mi
Registration #4	2012-07-24	79.941 mi
Registration #5	2013-07-16	87.232 mi
Registration #6	2013-07-17	87.232 mi
Registration #7	2014-07-24	97.108 mi
Registration #8	2015-07-24	100.365 mi
Registration #9	2017-03-03	106.377 mi
Registration #10	2018-02-27	110.320 mi
Registration #11	2019-05-20	115.377 mi
Registration #12	2019-05-20	115.377 mi
Registration #13	2019-05-20	115.377 mi
Registration #14	2019-05-20	115.377 mi
Registration #15	2019-05-20	115.377 mi
Registration #16	2019-05-20	115.377 mi
Registration #17	2019-05-20	115.377 mi
Registration #18	2019-05-20	115.377 mi
Registration #19	2019-05-20	115.377 mi
Registration #20	2019-05-20	115.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2426 mm
Height	2420 mm
Length	6845 mm
Kerb weight	2005 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	64698551611803