





report date: 2024-03-28

# General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Blue
Year of manufacture	2009
Top speed	106 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 3.200 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	141 g/km
CO2 label	F



CarCheck.co.uk page 1/15



report date: 2024-03-28

# Internet history

Entry	1

Lifety 1	
Date	2021-09-27
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

## MOT history

MOT expiry date	2024-09-05
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	39
Total items failed	6

Total iten	ns failed 6	
MOT #18		2023-09-06 15:10
MOT test	number	231241535350
Result		<b>✓</b> Passed
Next exp	iry date	2024-09-05
Minor grease (6	Offside Front Outer Drive shaft joint constant velocity boot sev .1.7 (g) (i))	rerely deteriorated some discharge of
<b>Minor</b> of grease	Nearside Front Outer Drive shaft joint constant velocity boot set $(6.1.7 (g) (i))$	everely deteriorated some discharge
Advice	Offside Rear Brake pipe corroded, covered in grease or other	material at securing clip. (1.1.11 (c))

CarCheck.co.uk page 3/15



Result

GK09RW

report date: 2024-03-28

**MOT #17** 2023-09-02 11:58

**MOT** test number 335883501590

× Failed

**MAJOR** Offside Front Direction indicator incorrect colour bulb coating deteriorated. (4.4.3 (a))

**MAJOR** Brake fluid contaminated showing in reservoir. (1.8 (a))

Offside Rear Brake pipe corroded, covered in grease or other material at securing clip. (1.1.11 (c)) Advice

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated some discharge of grease (6.1.7 (g) (i))

**MAJOR** Stop lamp(s) not working high level lamp inop. (4.3.1 (a) (ii))

**MAJOR** Offside Headlamp aim too far to the right (4.1.2 (a))

**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MAJOR** Rear Service brake excessively fluctuating (1.2.1 (e))

Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) MAJOR

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated some discharge of grease (6.1.7 (g) (i))

**MAJOR** Nearside Headlamp aim too far to the right (4.1.2 (a))

**MOT #16** 2022-09-01 10:36

**MOT** test number 471634824733

Result Passed

Offside Rear Tyre worn close to legal limit/worn on edge 175/65/14 (5.2.3 (e)) Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 4/15



report date: 2024-03-28

**MOT #15** 2022-08-29 12:27

**MOT test number** 656943148426

Result X Failed

MAJOR Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 175/65/14 (5.2.3 (e))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MAJOR Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2021-09-03 10:00

**MOT test number** 428710031396

**Result** 
✓ Passed

**MOT #13** 2021-09-01 08:47

MOT test number 444959554025

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MAJOR** Registration plate lamp does not illuminate simultaneously with the position lamps both (4.7.2 (a))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

MAJOR Nearside Front Suspension arm pin or bush excessively worn bottom arm, rear bush (5.3.4 (a) (i))

**MOT #12** 2021-01-07 16:48

**MOT test number** 481068779060

**Result** 
✓ Passed

**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 5/15



assembly

**GK09RWY** 

report date: 2024-03-28

**MOT #11** 2020-01-28 12:08

**MOT test number** 857720662931

**MOT #10** 2020-01-07 06:51

**MOT test number** 210620309614

Result X Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MAJOR** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #9 2019-03-21 11:33

MOT test number 385773020304

Result 

Passed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Offside Front Macpherson strut has movement in the upper support bearing

MOT #8 2018-03-20 14:55

MOT test number 627001142739

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 6/15



report date: 2024-03-28

**MOT #7** 2018-03-20 10:19 893427328954 **MOT** test number Result × Failed Fail Front registration plate deteriorated (6.3.1d) Fail Nearside Front position lamp(s) not working (1.1.A.3b) Fail Nearside Front Macpherson strut has excessive movement in the upper support bearing assembly (2.5.B.1b)Fail Windscreen washer provides insufficient washer liquid (8.2.3) Fail Offside Windscreen wiper does not clear the windscreen effectively split (8.2.2) Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #6

MOT test number

Result

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Rear Tyre worn close to the legal limit both (4.1.E.1)

MOT #5

MOT test number

Front Exhaust has a minor leak of exhaust gases (7.1.2)

2016-03-15 11:34

596261364969

✓ Passed

MOT #4 2015-03-09 12:55

MOT test number 458918765036

Result ✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #3 2014-03-08 09:20

**MOT test number** 527157864021

**Result** ✓ Passed

**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #2 2013-03-15 10:28

**MOT test number** 628064173025

**Result** ✓ Passed

MOT #1 2012-03-08 09:47

**MOT test number** 588478462057

**Result** ✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	5 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

_	
Owner	hictory
OWILL	HISLOLV

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		NDAI
manage of the same		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		,
Current registration	NK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 12/15



report date: 2024-03-28

#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-21
Last registration	2023-09-06
Complete history	See info



Registration #1	2009-03-21	18 mi
Registration #2	2012-03-08	27.805 mi
Registration #3	2013-03-15	37.301 mi
Registration #4	2014-03-08	42.453 mi
Registration #5	2015-03-09	48.906 mi
Registration #6	2016-03-15	57.516 mi
Registration #7	2017-03-06	75.789 mi
Registration #8	2018-03-20	83.815 mi
Registration #9	2018-03-20	83.817 mi
Registration #10	2019-03-21	87.028 mi
Registration #11		9.79 es
Registration #12		11.777 es
Registration #13		9.79 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.79 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-28

Car features

S0225		Air conditioning

The HYUNDAI factory car options list is only available in the premium report.

S0225 Air conditioning

S0295

\$0482 \$0501

\$0566 \$0567

S0569

View the complete HYUNDAI factory list for this vehicle <a href="here">here</a>.

More info >

#### Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	1025 kg
Max. allowed weight	1510 kg

# Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles 2

**Engine number** G4EE8076119