





General information

Make	NISSAN
Model	TERRANO TD SVE
Colour	Black
Year of manufacture	2002
Top speed	102 mph
0 - 60 mph	14.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	154 BHP
Max. torque	304 Nm at 1.600 rpm
Engine capacity	2.953 сс
Cylinders	4
Fuel type	Diesel
Consumption city	22.1 mpg
Consumption extra urban	34.0 mpg
Consumption combined	28.5 mpg
CO2 emission	262 g/km
CO2 label	М



CarCheck.co.uk page 1/16



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-08

Pictures 28

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/16





MOT history

MOT expiry date	2024-09-25
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	36
Total items failed	29

MOT #24		2023-09-26 16:18
MOT test	number	333660008393
Result		✓ Passed
Next expi	ry date	2024-09-25
Advice	Brake pipe corroded, covered in grease or other material all pipes coated	in underseal (1.1.11 (c))

MOT #2	23	2023-09-19 16:36
MOT te	st number	557298539498
Result		× Failed
Fail	Front Exhaust has a major leak of exhaust gases (6.1.2 (a))	
Fail	Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))	
Fail	Fail Emissions unable to be completed due to excessive exhaust blow (8.2.2.2 (e))	
Fail	Fail Nearside Front Direction indicator incorrect colour (4.4.3 (a))	
Fail Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))		
Advice Brake pipe corroded, covered in grease or other material all pipes coated in underseal (1.1.11 (c))		

CarCheck.co.uk page 3/16



report date: 2024-03-29

MOT #22 2022-09-16 10:12

MOT test number 615143331667

Result ✓ Passed

Minor Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #21 2021-09-25 15:04

MOT test number 309464783796

Result ✓ Passed

MOT #20 2018-07-18 11:06

MOT test number 665896071071

Result \(\sqrt{Passed} \)

Advice Offside front indicator damaged

Advice Brake pipes corroded in places

MOT #19 2018-07-18 08:17

MOT test number 983078206388

Result X Failed

Fail Offside Front Direction indicator incorrect colour (4.4.3 (a))

Fail Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Brake pipes corroded in places

Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))


Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Offside front indicator damaged

CarCheck.co.uk page 4/16



report date: 2024-03-29



MOT #16		2016-07-14 10:36
MOT test	number	501630081323
Result		✓ Passed
Advice	Offside Front wheel bearing has slight play (2.5.A.3c)	
Advice	Nearside Front wheel bearing has slight play (2.5.A.3c)	
Advice	Offside Front Tyre worn close to the legal limit worn inner edge (4.1.E.1)	

CarCheck.co.uk page 5/16



report date: 2024-03-29

MOT #15 2016-07-12 15:15

MOT test number 296374796847

Result X Failed

Advice Offside Front Tyre worn close to the legal limit worn inner edge (4.1.E.1)

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Fail Offside Front Trailing arm synthetic bush deteriorated resulting in excessive movement as marked (2.4.G.2)

Advice Offside Front wheel bearing has slight play (2.5.A.3c)

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Fail Exhaust has a major leak of exhaust gases Flexy section (7.1.2)

Advice Nearside Front wheel bearing has slight play (2.5.A.3c)

MOT #14 2015-07-10 12:22

MOT test number 375801495198

Result \(\sqrt{Passed} \)

Advice Offside Front Direction indicator slightly discoloured (1.4.A.2f)

Notice Under-trays fitted obscuring some underside components

Advice Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Notice Fuel pipe/s corroded

Advice Offside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive

movement (2.4.G.2)

CarCheck.co.uk page 6/16



report date: 2024-03-29

MOT #13 2015-07-01 10:52

MOT test number 535862685116

Result X Failed

Fail Offside Windscreen wiper blade insecure (8.2.2)

Advice Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Under-trays fitted obscuring some underside components

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Fail Nearside Stop lamp not working (1.2.1b)

Fail Nearside Windscreen wiper blade insecure (8.2.2)

Fail Offside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Notice Fuel pipe/s corroded

Advice Offside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Offside Rear position lamp(s) not working (1.1.A.3b)

Advice Offside Front Direction indicator slightly discoloured (1.4.A.2f)

Fail Offside Stop lamp not working (1.2.1b)

MOT #12 2014-07-11 16:26

MOT test number 575412794185

Result ✓ Passed

MOT #11 2014-07-10 10:44

MOT test number 247141094130

Result X Failed

Fail Centre Rear Exhaust has a major leak of exhaust gases (7.1.2)

Fail Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

CarCheck.co.uk page 7/16



report date: 2024-03-29

MOT #10 2013-07-05 17:12

MOT test number 279336883456

Result ✓ Passed

MOT #9 2013-07-05 10:06

MOT test number 275066283102

Result X Failed

Fail Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #8 2012-06-29 15:46

MOT test number 109851382128

Result \rightarrow Passed

Advice Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #7 2012-06-29 11:10

MOT test number 635041982118

Result X Failed

Notice No smoke on bet test

Fail Front Exhaust has a major leak of exhaust gases (7.1.2)

Advice Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Fail Offside Stop lamp not working (1.2.1b)

Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)

MOT #6 2011-07-05 14:12

MOT test number 576616981140

Result
✓ Passed

CarCheck.co.uk page 8/16



report date: 2024-03-29

MOT #5 2010-06-11 11:44

MOT test number 321312060141

Result ✓ Passed

MOT #4 2009-06-24 11:42

MOT test number 531435779190

Advice Offside Front constant velocity joint gaiter deteriorated (2.5.C.1a)

MOT #3 2008-06-27 09:28

MOT test number 144709678109

Result \rightarrow Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2007-06-23 14:48

MOT test number 111834477158

Notice Child seat fitted not allowing full inspection of adult belt

MOT #1 2006-06-23 10:00

MOT test number 534684176167

Result
✓ Passed

CarCheck.co.uk page 9/16





Tax & MOT check





Expires: 25 September 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	25 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 10/16



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



Owner history

NC02FWA

report date: 2024-03-29

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN
have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

Plate since

See in this check if this NISSAN had different number plates.

More info >

CarCheck.co.uk page 13/16



report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 14/16





Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2002-06-26
Last registration	2023-09-26
Complete history	See info



Registration #1	2002-06-26	13 mi
Registration #2	2006-06-23	34.892 mi
Registration #3	2007-06-23	43.633 mi
Registration #4	2008-06-27	51.512 mi
Registration #5	2009-06-24	60.380 mi
Registration #6	2010-06-11	69.592 mi
Registration #7	2011-07-05	75.698 mi
Registration #8	2012-06-29	81.804 mi
Registration #9	2012-06-29	80.804 mi
Registration #10	2013-07-05	86.483 mi
Registration #11	2013-07-05	86.483 mi
Registration #12	2014-07-10	91.567 mi
Registration #13	2014-07-11	91.568 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		D.777 es
Registration #20		11.777 es
Registration #21		11.777 est
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		11.777 au

CarCheck.co.uk page 15/16



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1850 mm
Length	4697 mm
Wheel base	2650 mm
Kerb weight	1965 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	090439

CarCheck.co.uk page 16/16