





# General information

Make	VOLKSWAGEN	
Model	TOURAN S TDI DSG DPF	
Colour	Grey	
Year of manufacture	2008	
Top speed	128 mph	
0 - 60 mph	9.8 seconds	
Gearbox	6 speed Semi Auto	

# Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	172 g/km
CO2 label	Н





# MOT history

MOT expiry date	2025-03-05
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	29
Total items failed	6

MOT #16		2024-03-06 15:13
<b>MOT test number</b> 40556466662		405564666628
Result		✓ Passed
Next expi	ry date	2025-03-05
Advice	Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		ovement (5.3.4 (a)
Advice	Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Advice Offside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly reduc	ced (6.1.1 (c) (i))

**MOT #15** 2024-03-06 15:13 862171729472 **MOT test number** Result × Failed Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i)) Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Pass with rectification Nearside Front Headlamp aim too high (4.1.2 (a)) Advice Offside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))



MOT #14	2023-01-31 10:4
MOT test	<b>number</b> 53645952922
Result	✓ Passe
Minor (b) (i))	Nearside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13	2022-02-22 11:55
MOT test number	136186812554
Result	Passed
Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #12	2020-11-27 13:36
MOT test number	913201545110
Result	Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing Close to 1	6 limit (5.2.3 (d) (ii))

MOT #11	2020-11-27 13:36
MOT test number	873258236673
Result	× Failed
Pass with rectification (4.7.1 (b) (ii))	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps
Advice Offside Rear Tyr	e slightly damaged/cracking or perishing Close to 1.6 limit (5.2.3 (d) (ii))

MOT #10	2019-11-09 09:47
MOT test number	772052181131
Result	✓ Passed
Advice Front discs and pads rear pads worn slightly both front tyres worn close to 1.6mm	



GR08BHO
report date: 2024-03-29

MOT #9	2018-10-16 13:31
MOT test number	592631291646
Result	✓ Passed
MOT #8	2017-05-10 15:03
MOT test number	856067497312
Result	✓ Passed

Advice Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #7	2017-05-10 14:05
MOT test number	905336145303
Result	
<b>Fail</b> Nearside Front Anti-roll bar linkage ball joint dust cover excessively damage prevents the ingress of dirt (2.4.G.2)	
Advice Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)   Fail Nearside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer	
prevents the ingress of dirt etc (2.5.C.1a)	

МОТ #6		2016-05-06 16:57
MOT test number		483063948524
Result		✓ Passed
Advice Nearside Inner Front (2.5.C.1a)	constant velocity joint gaiter dete	eriorated, but preventing the ingress of dirt

MOT #5		2015-03-26 14:53
MOT test	number	806435185039
Result		✓ Passed
Advice	Front Windscreen has damage to an area less than a 10mm circle w	ithin zone 'A' (8.3.1a)



GR08BHO report date: 2024-03-29

МОТ #4	2014-03-07 12:39
MOT test number	329056164064
Result	✓ Passed
Advice Windscreen has damage to an area less than a 40mm circle outside zone	e 'A' (8.3.1d)
MOT #3	2014-03-06 11:26
MOT test number	698335364050
Result	🗙 Failed
Fail   Centre Stop lamp not working (1.2.1b)	
Fail   Nearside Stop lamp not working (1.2.1b)	
Advice Windscreen has damage to an area less than a 40mm circle outside zone	e 'A' (8.3.1d)

MOT #2		2013-03-21 14:23
MOT test	number	998560883088
Result		✓ Passed
<b>Advice</b> (8.3.1a)	Offside Front Lower Windscreen has damage to an area less than a 10mm circ	le within zone 'A'
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Offside rear tyre wearing uneven on inner edge	
<b>Advice</b> (2.5.C.1a)	Nearside Front Front constant velocity joint gaiter damaged, but preventing th	e ingress of dirt

MOT #1	2012-03-19 12:39
MOT test number	227529172094
Result	✓ Passed
<b>Notice</b> Child seat fitted not allowing full inspection of adult belt	



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	✓ MOT Expires: 5 March 2025
Tax status	Valid until 1 September
Days left	124
MOT expiry date	5 March 2025
Full MOT history	See MOT history
Tax calculation	

# Vehicle class49BandHSingle payment (12 months)£ 290,00,-Single six month payment£ 159,50,-Total payable by 12 monthly instalments£ 304,50,-





### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Demons 2	AMPLE
Damage 2	6 6 at - a
Date	
Category	AMPT
Туре	

### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700





# Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
********	
and a second sec	
***********	
*********	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



GR08BHO report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-08-15
Last registration	2024-03-06
Complete history	See info



Registration #1	2008-08-15	6 mi
Registration #2	2012-03-19	41.237 mi
Registration #3	2013-03-21	48.292 mi
Registration #4	2014-03-06	51.569 mi
Registration #5	2014-03-07	51.582 mi
Registration #6	2015-03-26	61.092 mi
Registration #7	2016-05-06	72.883 mi
Registration #8	2017-05-10	80.458 mi
Registration #9	2017-05-10	80.459 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.222 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.222 est





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



### Dimensions & weight Width 1820 mm Height 1472 mm Length 4765 mm Wheel base 2709 mm Kerb weight 1671 kg Max. allowed weight 2090 kg Additional information Fuel tank capacity 70 I **Fuel delivery Direct Injection** Number of doors 4

CarCheck.co.uk

Number of seats	5
Number of axles	2
Engine number	BKP 284781