





General information

| Make | ΤΟΥΟΤΑ |
|---------------------|-------------------------------|
| Model | HILUX INVINCIBLE 4X4 D-4D DCB |
| Colour | Silver |
| Year of manufacture | 2013 |
| Top speed | 106 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power 169 BHP |
|---------------------------------|
| Max. torque343 Nm at 3.400 rpm |
| Engine capacity 2.982 cc |
| Cylinders 4 |
| Fuel type Diesel |
| Consumption city 29.7 mpg |
| Consumption extra urban42.2 mpg |
| Consumption combined 36.7 mpg |
| CO2 emission 203 g/km |
| CO2 label K |





| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-07-11 |
| Pictures | 1 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| MOT expiry date | 2025-04-25 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 8 |
| Failed MOT tests | 3 |
| Total advice items | 24 |
| Total items failed | 8 |

| MOT #11 | 2024-04-24 14:54 | |
|--|------------------------------|--|
| MOT test number | 202826284259 | |
| Result | ✓ Passed | |
| Next expiry date | 2025-04-25 | |
| Minor Nearside Rear Registration plate lamp missing in the case of multiple lamp (b) (i)) | amps or light sources (4.7.1 | |
| Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Front spring hanger (5.3.6 (a) (i)) | | |
| Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive Front spring hanger (5.3.6 (a) (i)) | | |

| MOT #10 | | 2023-04-26 13:49 |
|----------|--|----------------------|
| MOT test | number | 112620254793 |
| Result | | ✓ Passed |
| Minor | Nearside Rear Registration plate lamp inoperative in the case of multiple la | mps or light sources |





| MOT #9 | 2023-04-19 13:42 | |
|--|------------------|--|
| MOT test number | 760045609410 | |
| Result | 🗙 Failed | |
| Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps of (4.7.1 (b) (i)) | or light sources | |
| Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) | | |
| Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) | | |
| Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a)) | | |
| Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) | | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 | 5 (c)) | |

| MOT #8 | | 2022-03-25 20:29 |
|----------|---|-----------------------|
| MOT test | number | 793048156182 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Coil spring corroded (5.3.1 (b) (i)) | |
| Minor | Registration plate lamp inoperative in the case of multiple lamps or light so | urces (4.7.1 (b) (i)) |
| Advice | Underbody sealed | |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.1 | 4 (a) (ii)) |
| Advice | Brake pipe corroded, covered in grease or other material (1.1.11 (c)) | |
| Advice | Offside Front Coil spring corroded (5.3.1 (b) (i)) | |
| Minor | Offside Front Suspension arm ball joint dust cover severely deteriorated (5. | 3.4 (b) (i)) |



| لۍين | CAR CHECK | report date: 2024-03-28 |
|----------|--|---------------------------|
| | | |
| MOT #7 | | 2022-03-25 14:53 |
| MOT test | number | 227400726563 |
| Result | | 🗙 Failed |
| Advice | Offside Front Coil spring corroded (5.3.1 (b) (i)) | |
| Fail | Rear Registration plate lamp inoperative in the case of a single lamp or al | ll lamps (4.7.1 (b) (ii)) |
| Minor | Offside Front Suspension arm ball joint dust cover severely deteriorated | d (5.3.4 (b) (i)) |
| Advice | Advice Nearside Front Coil spring corroded (5.3.1 (b) (i)) | |
| Advice | Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |
| Fail | Offside Rear Service brake excessively binding (1.2.1 (f)) | |
| Advice | Brake pipe corroded, covered in grease or other material (1.1.11 (c)) | |
| Advice | Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Underbody sealed | |

| МОТ #6 | 2021-03-25 09:55 |
|--|------------------|
| MOT test number | 207862479708 |
| Result | ✓ Passed |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| | |

| MOT #5 | 2020-03-21 09:33 |
|-----------------|------------------|
| MOT test number | 542264346451 |
| Result | ✓ Passed |

YF13UPY





| MOT #4 | | 2020-03-21 09:33 |
|-------------------------|--|------------------|
| MOT test number | | 715750746361 |
| Result | | 🗙 Failed |
| Pass with rectification | Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) | |
| | | |
| MOT #3 | | 2019-03-29 10:46 |
| MOT test number | | 147933463716 |
| Result | | ✓ Passed |
| | | |
| MOT #2 | | 2018-03-17 10:27 |
| MOT test number | | 822154124742 |
| Result | | ✓ Passed |
| | | |
| MOT #1 | | 2016-06-23 14:00 |
| MOT test number | | 702417303816 |
| Result | | ✓ Passed |



Tax & MOT check

| ✓ Taxed | мот |
|--|--|
| Tax due: 1 September 2024 Tax status | Expires: 25 April 2025 Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 25 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|------|
| Date | |
| Category | Lamp |
| Туре | K K |
| Damage 2 | AMPL |
| | |
| Date | NE |
| Category | AMP |
| Туре | |

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|---|-------------|
| *********** | |
| ******* | |
| ******* | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this TOYOTA had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | |





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 13 |
| First mileage registration | 2013-06-25 |
| Last registration | 2024-04-24 |
| Complete history | <u>See info</u> |



| Registration #1 | 2013-06-25 | 6 mi |
|------------------|------------|------------|
| Registration #2 | 2016-06-23 | 33.832 mi |
| Registration #3 | 2018-03-17 | 57.522 mi |
| Registration #4 | 2019-03-29 | 73.789 mi |
| Registration #5 | 2020-03-21 | 93.500 mi |
| Registration #6 | 2020-03-21 | 93.500 mi |
| Registration #7 | 2021-03-25 | 100.026 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.117 esi |
| Registration #11 | | 11.777 esi |
| Registration #12 | | 10.000 est |
| | | |

More info >





Car features

| S0225 | Air conditionin |
|--------|-----------------|
| \$0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Dimensions & weight

| Width | 1835 mm |
|---------------------|---------|
| Height | 1860 mm |
| Length | 5260 mm |
| Kerb weight | 1975 kg |
| Max. allowed weight | 3080 kg |

Additional information

| Fuel delivery | Direct Injection |
|-----------------|------------------|
| Number of doors | 4 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 1KDA220659 |