





report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI STYLE
Colour	Black
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 1.800 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.2 mpg
CO2 emission	197 g/km
CO2 label	1



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date	2021-05-26	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-06-07
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	33
Total items failed	0

MOT #14		2023-05-19 09:34
MOT test	number	416750133266
Result		✓ Passed
Next expi	ry date	2024-06-07
Advice (c))	Brake pipe corroded, covered in grease or other material bothside rea	ar corroded in places. (1.1.11
Advice componen	Rear Sub-frame is corroded but structural rigidity is not significantly rets. (6.1.1 (c) (i))	educed and suspension
Advice	Shock absorbers has a reduced damping effect bothside rear. (5.3.2 (d))
Advice (1.1.11 (c)	Brake pipe corroded, covered in grease or other material bothside fro	nt to hose corroded in place.
Advice lamp lights	Offside Front Headlamp has a product on the lens but not seriously resolution output reduced, marginal pass. $(4.1.4 (b))$	ducing light output head
Advice	Direction indicator slightly discoloured bothside rear , should replace.	(4.4.3 (a))
Advice	Bothside rear parking brake should be adjusted, poor efficiency, marg	jinal pass.
Advice grease, ma	Nearside Front Drive shaft flexible coupling slightly deteriorated outer arginal I pass ,should replace. (6.1.7 (d) (i))	cracking starting to seeping

CarCheck.co.uk page 3/13



HG11SLV

report date: 2024-03-28

MOT #13 2023-05-10 09:27

MOT test number 275005459496

Result

× Failed

Advice

Brake pipe corroded, covered in grease or other material bothside rear corroded in places. (1.1.11

(c))

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output head lamp lights output reduced, marginal pass. (4.1.4 (b))

Advice

Bothside rear parking brake should be adjusted, poor efficiency, marginal pass.

Advice

Rear Sub-frame is corroded but structural rigidity is not significantly reduced and suspension components. (6.1.1 (c) (i))

Advice Nearside Front Drive shaft flexible coupling slightly deteriorated outer cracking starting to seeping grease, marginal I pass ,should replace. (6.1.7 (d) (i))

Advice

Shock absorbers has a reduced damping effect bothside rear. (5.3.2 (d))

Advice Brake pipe corroded, covered in grease or other material bothside front to hose corroded in place. (1.1.11(c))

MAJOR Nearside Front Power steering component leaking inner rack seal leak badly new steering rack is required. (2.1.5 (a))

MAJOR Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Direction indicator slightly discoloured bothside rear, should replace. (4.4.3 (a))

MAJOR Offside Front Drive shaft flexible coupling excessively deteriorated inner c.v gaiter broken and leak grease. (6.1.7 (d) (i))

MOT #12 2022-05-19 11:41

MOT test number 187545837750

Result ✓ Passed

CarCheck.co.uk page 4/13

Advice Offside Rear Suspension arm damaged but not seriously weakened tracking arm, bend. (5.3.3 (b) (i)) Minor Offside Front Side repeater with a multiple light source up to 1/2 not functioning light output dim, should replace. (4.4.1 (a) (i)) **Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output head lamp light bulb should be replaced. (4.1.4 (b)) Bothside rear parking brake poor efficiency, should be adjusted. Advice Advice Brake pipe corroded, covered in grease or other material bothside rear corroding. (1.1.11 (c)) Advice Nearside Front Front passenger door hinge deteriorated but the door can still be readily opened and closed lower hinge . (6.2.3 (c) (i)) Nearside Front Tyre worn close to legal limit/worn on edge inner shoulder ,should replace. (5.2.3 **Advice**

(e))



HG11SLV

report date: 2024-03-28

MOT test number 725537315936

Result ✓ Passed

MOT #10 2020-08-04 15:11

MOT test number 541453318880

Result

Passed

MOT #9 2020-08-04 10:31

MOT test number 774042563778

Result X Failed

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #8 2019-07-31 09:13

MOT test number 317107101065

Result ✓ Passed

MOT #7 2018-07-30 14:56

MOT test number 297053693015

Result
✓ Passed

Advice Windscreen washers weak

MOT #6 2018-07-30 10:44

MOT test number 974553793693

Result X Failed

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))

DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Windscreen washers weak

CarCheck.co.uk page 5/13



MOT #5	2017-07-17 11:18
MOT test number	694954540446
Result	✓ Passed
Advice O/s and n/s rear brake pads wearing low	

Advice O/s and n/s rear brake pads wearing low	
MOT #4	2016-07-27 10:52
MOT test number	622839890108
Result	✓ Passed
MOT #3	2015-08-10 08:09
MOT test number	280872777383
Result	✓ Passed
MOT #2	2014-08-13 17:19
MOT test number	229285624211
Result	✓ Passed
MOT #1	2014-05-06 11:37
MOT test number	619886324179
Result	./ Passed

MOT #1	2014-05-06 11:37
MOT test number	619886324179
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	7 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when misterly	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-06-30
Last registration	2023-05-19
Complete history	See info



Registration #1	2011-06-30	25 mi
Registration #2	2014-05-06	13.032 mi
Registration #3	2014-08-13	13.949 mi
Registration #4	2015-08-10	24.408 mi
Registration #5	2016-07-27	33.028 mi
Registration #6	2017-07-17	43.450 mi
Registration #7	2018-07-30	55.730 mi
Registration #8	2018-07-30	55.732 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1946 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13