





report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Silver
Year of manufacture	2003
Top speed	102 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	116 Nm at 3.200 rpm
Engine capacity	1.341 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/15



report date: 2024-03-28


Internet history

Entry 1

Date 2021-10-19

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

MOT expiry date	2024-04-29
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	27
Total items failed	9

MOT #23		2023-04-28 13:52
MOT test	number	567808667050
Result		✓ Passed
Next expi	y date	2024-04-29
Advice	Car have age rust underneath allover	
Advice	Front Subframe mounting prescribed area is corroded but not considered	excessive (5.3.6 (a) (i))

MOT #22		2022-04-30 10:41
MOT test	number	294226873076
Result		✓ Passed
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #21		2022-04-30 10:41
MOT test number		444327315577
Result		× Failed
Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))		
Pass with rectification	Front Windscreen wiper does not clear the windscr	reen effectively (3.4 (b) (ii))
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))		

CarCheck.co.uk page 3/15



003FFW

report date: 2024-03-28

MOT #20 2021-04-30 14:40 **MOT** test number 526312722282 ✓ Passed Result **Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) **Advice** Rear Brake pipe corroded, covered in grease or other material n/s and o/s (1.1.11 (c))

MOT #19 2021-04-22 08:39 **MOT** test number 505080979302 Result **★** Failed **Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) Fail Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) **Advice** Rear Brake pipe corroded, covered in grease or other material n/s and o/s (1.1.11 (c)) Fail Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #18 2020-03-26 13:20 359163287895 **MOT** test number Result Passed

MOT #17 2019-03-27 15:41 863220615030 **MOT** test number Result ✓ Passed **Minor** Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Vehicles internal headlight adjuster altered to recheck lights **Advice** Minor Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #16	2018-03-28 13:48
MOT test number	109103190282
Result	✓ Passed
MOT #15	2017-03-30 08:03
MOT test number	999203365664
Result	✓ Passed
MOT #14	2017-03-29 11:09
MOT test number	778502010248
Result	× Failed
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Rear washer inop	
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Rear wiper split	

MOT #13		2016-03-30 08:58
MOT test	number	269787588882
Result		✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Rear washer inop	

CarCheck.co.uk page 5/15



Fail

MOT #10

VO03FFW

report date: 2024-03-28

MOT #12 2016-03-29 11:52 **MOT** test number 673241473449 Result × Failed **Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d) Fail Centre Stop lamp not working (1.2.1b) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Advice Front tyres slightly deteriorated Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) **Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d) Nearside Front Tyre worn close to the legal limit (4.1.E.1) Advice Advice Front Brake pad(s) wearing thin (3.5.1g) **Advice** Rear washer inop

MOT #11	2015-03-26 13:43
MOT test number	137815885468
Result	✓ Passed

Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

FIG1 # 10	2014 03 20 13.00
MOT test number	547515284067
Result	✓ Passed

MOT #9	2013-04-03 09:50
MOT test number	357633293069
Result	✓ Passed

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #8		2012-03-28 09:27
MOT test number		528228782057
Result		✓ Passed
MOT #7		2012-03-28 09:27
MOT test number		548048482096
Result		× Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	
MOT #6		2011-03-28 15:40
MOT test number		485597381028
Result		✓ Passed
1105411		V i abbed
MOT #5		2010-03-29 09:36
MOT test number		964618280048
Result		✓ Passed
MOT #4		2009-03-27 09:45
MOT test number		904686189083
Result		✓ Passed
MOT #3		2008-04-01 09:21
MOT test number		811812598098
Result		✓ Passed
MOT #2		2007-04-02 14:34
MOT test number		274402197042
Result		✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #1 2006-04-26 11:20


MOT test number 271119126402

CarCheck.co.uk page 8/15



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	29 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Flate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-06-03
Last registration	2023-04-28
Complete history	See info



Registration #1	2003-06-03	9 mi
Registration #2	2006-04-26	14.337 mi
Registration #3	2007-04-02	17.599 mi
Registration #4	2008-04-01	21.232 mi
Registration #5	2009-03-27	24.464 mi
Registration #6	2010-03-29	27.861 mi
Registration #7	2011-03-28	30.814 mi
Registration #8	2012-03-28	33.053 mi
Registration #9	2013-04-03	35.300 mi
Registration #10	2014-03-26	37.527 mi
Registration #11	2015-03-26	39.406 mi
Registration #12	2016-03-29	41.520 mi
Registration #13		11.77
Registration #13 Registration #14		1.77 m
		1.77 m
Registration #14		1.77 m
Registration #14 Registration #15		17.77 es 17.77 es 17.77 es 17.77 es
Registration #14 Registration #15 Registration #16		11.77 es 11.77 es 11.77 es 11.77 es
Registration #14 Registration #15 Registration #16 Registration #17		11,777 es 11,777 es 11,777 es 11,777 es 11,777 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		11,777 es 11,777 es 11,777 es 11,777 es 11,777 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		11,777 es 11,777 es 11,777 es 11,777 es 11,777 es 11,777 es 11,777 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11,777 es 11,777 es 11,777 es 11,777 es 11,777 es 11,777 es 11,777 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea

More info >



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	*Arkelek
Video	see crash video



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1072 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	G4EA3362542 page 15/15