



HONDA



report date: 2024-03-28

General information

| | |
|---------------------|------------------|
| Make | HONDA |
| Model | INSIGHT IMA ES-T |
| Colour | Silver |
| Year of manufacture | 2010 |
| Top speed | 113 mph |
| 0 - 60 mph | 12.5 seconds |
| Gearbox | 1 speed CVT |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 87 BHP |
| Max. torque | 120 Nm at 4.500 rpm |
| Engine capacity | 1.339 cc |
| Cylinders | 4 |
| Fuel type | Hybrid / Electric |
| Consumption city | 60.1 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 61.4 mpg |
| CO2 emission | 105 g/km |
| CO2 label | B |





Internet history

Entry 2



| | |
|---------------|-----------------------------|
| Date | 2023-10-04 |
| Pictures | 38 |
| Listing price | View report |



source: [cargurus.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-07-29 |
| Pictures | 12 |
| Listing price | View report |



source: [cargurus.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-02 |
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 64 |
| Total items failed | 3 |

| | |
|------------------|--|
| MOT #15 | 2023-10-03 13:30 |
| MOT test number | 748623128555 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-02 |
| Advice | Integral body structure is corroded but structural rigidity is not significantly reduced All under side. (6.1.1 (c) (i)) |
| Advice | Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | All under side suspension components corroded / covered in under seal. |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Front Macpherson strut corroded but not seriously weakened Both sides (5.3.3 (b) (i)) |
| Advice | Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

**MOT #14**

2023-07-24 13:33

MOT test number

808081860887

Result**✗ Failed****DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MAJOR** Offside Rear Inner Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))**DANGEROUS** Nearside Front Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected (5.3.6 (a) (ii))**Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MAJOR** Offside Front Macpherson strut corroded and seriously weakened (5.3.3 (b) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**MAJOR** Offside Headlamp light intensity severely reduced (4.1.4 (a))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MAJOR** Nearside Rear Inner Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))**Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MAJOR** Nearside Front Macpherson strut corroded and seriously weakened (5.3.3 (b) (i))**DANGEROUS** Offside Front Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected (5.3.6 (a) (ii))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**MAJOR** Nearside Headlamp light intensity severely reduced (4.1.4 (a))**MOT #13**

2022-07-28 15:46

MOT test number

856855373989

Result**✓ Passed**

**MOT #12**

2021-08-09 08:55

MOT test number

898896563741

Result

✓ Passed

Advice

Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Minor

Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

MOT #11

2021-08-02 09:48

MOT test number

811647780011

Result

✗ Failed

Minor

Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

Advice

Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

DANGEROUS

Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #10

2020-06-16 16:16

MOT test number

319101091469

Result

✓ Passed

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing Tyre cracking. (5.2.3 (d) (ii))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge Tyre at 2mm. (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge Worn on the inner edge.(Bald) (5.2.3 (e))



| | |
|-----------------|--|
| MOT #9 | 2019-05-30 09:44 |
| MOT test number | 422128756056 |
| Result | ✓ Passed |
| Advice | Fuel clips corroded |
| Advice | Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i)) |
| Advice | Fuel Pipe/s corroded |
| Advice | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|--|
| MOT #8 | 2018-06-05 08:11 |
| MOT test number | 557395190150 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) |

**MOT #7** 2018-06-04 15:17**MOT test number** 497086986999**Result** ✗ Failed

- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- MAJOR** Offside Rear Brake clevis joint has restricted free movement (1.1.15 (e))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- MAJOR** Nearside Rear Brake clevis joint has restricted free movement (1.1.15 (e))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))

MOT #6 2017-06-05 09:03**MOT test number** 668557641910**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2016-05-31 13:18**MOT test number** 296596079368**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2015-06-02 10:17**MOT test number** 889963655173**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2014-05-30 14:11**MOT test number** 289250654434**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Engine covers fitted obscuring some components in the engine bay



| | |
|-------------------------|--|
| MOT #2 | 2014-05-30 14:11 |
| MOT test number | 739330354117 |
| Result | ✗ Failed |
| Pass with rectification | Nearside Headlamp aim too low (1.8) |
| Pass with rectification | Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| Notice | Under-trays fitted obscuring some underside components |
| Pass with rectification | Offside Headlamp aim too low (1.8) |
| Notice | Engine covers fitted obscuring some components in the engine bay |

| | |
|-----------------|------------------|
| MOT #1 | 2013-06-07 14:08 |
| MOT test number | 217888353425 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
2 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 December |
| Days left | 217 |
| MOT expiry date | 2 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 59 |
| Band | B |
| Single payment (12 months) | £ 10,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 10,50,- |



Damage history


Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 10,000 |
| Auction value | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this HONDA had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2019-01-01 |
| Current registration | XXXXXX |
| Plate since | 2019-01-01 |

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.


| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2010-06-16 |
| Last registration | 2023-10-03 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-06-16 | 15 mi |
| Registration #2 | 2013-06-07 | 18.200 mi |
| Registration #3 | 2014-05-30 | 22.977 mi |
| Registration #4 | 2015-06-02 | 27.089 mi |
| Registration #5 | 2016-05-31 | 31.156 mi |
| Registration #6 | 2017-06-05 | 36.091 mi |
| Registration #7 | 2018-06-04 | 40.426 mi |
| Registration #8 | 2018-06-05 | 40.427 mi |
| Registration #9 | 2019-05-30 | 44.986 mi |
| Registration #10 | 2019-05-30 | 45.377 mi |
| Registration #11 | 2019-05-30 | 45.377 mi |
| Registration #12 | 2019-05-30 | 45.377 mi |
| Registration #13 | 2019-05-30 | 45.377 mi |
| Registration #14 | 2019-05-30 | 45.377 mi |
| Registration #15 | 2019-05-30 | 45.377 mi |
| Registration #16 | 2019-05-30 | 45.377 mi |
| Registration #17 | 2019-05-30 | 45.377 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 90% |
| Children | 74% |
| Pedestrian | 76% |
| Safety systems | 86% |
| Overall rating | 84% |
| Video | see crash video |



Dimensions & weight

| | |
|-------------|---------|
| Width | 1695 mm |
| Height | 1425 mm |
| Length | 4396 mm |
| Wheel base | 2550 mm |
| Kerb weight | 1240 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 40 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | LDA3 1072437 |