



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	LANDCRUISER D-4D LC5 8 SEATS
Colour	Silver
Year of manufacture	2004
Top speed	106 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	343 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	32.5 mpg
Consumption combined	27.2 mpg
CO2 emission	277 g/km
CO2 label	M





Internet history

Entry 2


Date	2021-12-19
Pictures	13
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-12-18
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-03
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	116
Total items failed	15

MOT #22	2023-11-04 13:48
MOT test number	500252036474
Result	✓ Passed
Next expiry date	2024-11-03
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Oil Leak
Advice	Rear Brake pad(s) wearing thin Change ASAP (1.1.13 (a) (ii))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Various Areas of Corrosion on Suspension & Chassis Repair ASAP
Advice	Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
Advice	Front Brake pad(s) wearing thin Change ASAP (1.1.13 (a) (ii))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Service brake binding but not excessively Repair ASAP (1.2.1 (f))



MOT #212022-08-01 16:44

MOT test number654762552789

Result

✓ Passed

Advice

Various areas of corrosion (suspension components & chassis)

Minor

Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice

Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #20**

2021-06-21 11:03

MOT test number

168153580946

Result

✓ Passed

- Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced whole underside corroded (6.1.1 (c) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases center silencer (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19**

2020-07-01 11:14

MOT test number

307796489759

Result

✓ Passed

- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
- Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))

**MOT #18**

2019-06-12 12:33

MOT test number

367343794705

Result

✓ Passed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Nearside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Nearside Front Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #17

2019-06-05 10:07

MOT test number

969175559530

Result

✗ Failed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Nearside Front Seat belt anchorage prescribed area is corroded but not considered excessive inner sill (7.1.1 (a) (i))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail Offside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))

Fail Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Advice Nearside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

Fail Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill (7.1.1 (a) (i))

Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

Fail Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting inner sill (6.2.2 (d) (i))

Fail Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Advice Nearside Front Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))



MOT #162018-06-27 11:19

MOT test number911327834198

Result

✓ Passed

- Advice

Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
- Advice

Cab step mounting brackets corroded
- Advice

Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice

Vehicle body corroded

**MOT #15**

2018-06-11 14:22

MOT test number

785518425544

Result**✗ Failed**

- Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
- Fail** Rear fog lamp not working (4.5.1 (a) (ii))
- Minor** Offside Cab steps insecure (6.2.8 (a) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Service brake grabbing slightly (1.2.1 (c))
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Vehicle body corroded
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Rear Bumper insecure (6.1.4 (a) (i))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Heatshield loose
- Advice** Nearside Rear Service brake grabbing slightly (1.2.1 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2017-06-05 13:36

MOT test number

198754130275

Result

✓ Passed

- Advice** Body has slight corrosion (6.1.B.2)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Rear seats not in use at time of test
- Advice** Fuel filler pipes corroded
- Advice** Vehicle structure has slight corrosion (6.1.A.1)
- Advice** Offside Front Outer Brake pad(s) wearing thin (3.5.1g)

MOT #13

2017-05-29 13:11

MOT test number

204283548309

Result

✗ Failed

- Advice** Offside front brake slightly binding
- Advice** Vehicle structure has slight corrosion (6.1.A.1)
- Advice** Rear seats not in use at time of test
- Advice** Body has slight corrosion (6.1.B.2)
- Fail** Offside Rear Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings sill (6.1.B.2)
- Advice** Fuel filler pipes corroded
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Fail** Nearside Rear Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings sill (6.1.B.2)

**MOT #12**

2016-06-17 12:25

MOT test number

817422659552

Result

✓ Passed

- Advice** Nearside Body has slight corrosion (6.1.B.2)
- Advice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside front brake slightly binding
- Advice** Power steering pipe(s) or hose(s) slightly corroded (2.3.2)
- Advice** Offside Body has slight corrosion (6.1.B.2)
- Advice** Under-trays fitted obscuring some underside components

MOT #11

2015-06-05 11:55

MOT test number

749006355188

Result

✓ Passed

- Advice** Offside Body has slight corrosion (6.1.B.2)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Body has slight corrosion (6.1.B.2)
- Notice** Under-trays fitted obscuring some underside components
- Notice** All tyres perished
- Advice** Nearside Front Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #10**

2014-06-23 13:24

MOT test number

808594674133

Result

✓ Passed

- Notice** Nearside and offside rear tyres perished
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Service brake juddering slightly (3.7.C.2)
- Notice** Offside front brake slightly binding
- Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #9

2013-05-30 09:42

MOT test number

248890353420

Result

✓ Passed

- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT #8

2012-06-22 16:17

MOT test number

907024172194

Result

✓ Passed

- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Front tyres slightly perished

**MOT #7** 2012-06-22 11:32**MOT test number** 296044872138**Result** ✗ Failed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Notice** Front tyres slightly perished**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**MOT #6** 2011-06-09 09:55**MOT test number** 155750661138**Result** ✓ Passed**MOT #5** 2010-06-21 17:03**MOT test number** 492512670123**Result** ✓ Passed**MOT #4** 2009-06-24 11:31**MOT test number** 201295079483**Result** ✓ Passed**MOT #3** 2007-09-17 14:26**MOT test number** 343260567406**Result** ✓ Passed**MOT #2** 2007-07-18 16:44**MOT test number** 104449597135**Result** ✓ Passed



MOT #1	2007-07-18 14:11
MOT test number	643829797111
Result	✗ Failed
Fail	Offside Registration plate lamp not working (1.1.5c)
Fail	Offside Rear fog lamp not working (1.3.2b)



Tax & MOT check

X

Untaxed

Tax expired:
14 January 2024

✓

MOT

Expires:
3 November 2024

Tax status	Expired at 14 January 2024
Days left	106 days too late
MOT expiry date	3 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-09-29
Current registration	 XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-07-24
Last registration	2023-11-04
Complete history	See info



Registration #1	2004-07-24	14 mi
Registration #2	2007-07-18	22.514 mi
Registration #3	2007-07-18	22.515 mi
Registration #4	2007-09-17	24.933 mi
Registration #5	2009-06-24	30.981 mi
Registration #6	2010-06-21	33.513 mi
Registration #7	2011-06-09	35.782 mi
Registration #8	2012-06-22	38.284 mi
Registration #9	2012-06-22	38.286 mi
Registration #10	2013-05-30	49.928 mi
Registration #11	2014-06-23	46.440 mi
Registration #12	2015-06-05	49.994 mi
Registration #13	2016-06-17	54.906 mi
Registration #14	2016-06-17	54.906 mi
Registration #15	2016-06-17	54.906 mi
Registration #16	2016-06-17	54.906 mi
Registration #17	2016-06-17	54.906 mi
Registration #18	2016-06-17	54.906 mi
Registration #19	2016-06-17	54.906 mi
Registration #20	2016-06-17	54.906 mi
Registration #21	2016-06-17	54.906 mi
Registration #22	2016-06-17	54.906 mi
Registration #23	2016-06-17	54.906 mi
Registration #24	2016-06-17	54.906 mi
Registration #25	2016-06-17	54.906 mi



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1875 mm
Height	1895 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	1990 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	1K01118161