





General information

Make	VAUXHALL
Model	AGILA CLUB
Colour	Black
Year of manufacture	2008
Top speed	106 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	79 BHP	
Max. torque	114 Nm at 4.400 rpm	
Engine capacity	1.242 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	36.2 mpg	
Consumption extra urban	57.6 mpg	
Consumption combined	47.9 mpg	
CO2 emission	142 g/km	
CO2 label	F	







Internet history

Entry 1

Date Pictures 2022-01-24

19

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-07
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	69
Total items failed	4

MOT #18	2024-01-17 14:29
MOT test number	103559736586
Result	✓ Passed
Next expiry date	2025-02-07

MOT #17		2024-01-17 14:29
MOT test number		929232026575
Result		🗙 Failed
Pass with rectification	Front Windscreen wiper missing (3.4 (a))	

MOT #16		2023-02-03 13:33
MOT test	number	453110738938
Result		✓ Passed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Front strut top mount noisy when turning steering	

MOT #15	2022-02-08 17:19
MOT test number	335214985853
Result	✓ Passed



F	V58ECW
	report date: 2024-03-28

МОТ #14	2021-11-30 07:50
MOT test number	159795388892
Result	✓ Passed
Advice High level brake light not working	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Front fog light inoperative	
Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.1	1 (c))

MOT #13		2021-11-11 16:35
MOT test	number	975006031054
Result		🗙 Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
MAJOR	Offside Front Windscreen washer not working (3.5 (a))	
Advice	Nearside Front fog light inoperative	
MAJOR	Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
MAJOR	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Minor	Stop lamp(s) with a multiple light source up to $1/2$ not functioning high level (4	.3.1 (a) (i))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.)	11 (c))
MAJOR	Nearside Front Windscreen washer not working (3.5 (a))	
MAJOR	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	





MOT #12	2020-12-01 14:12
MOT test	number 666578391278
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement
Advice	Windscreen damaged but not adversely affecting driver's view small chip to zone a

MOT #11	2019-11-15 11:24
MOT test	number 993365577729
Result	✓ Passed
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Advice	Coolant leak radiator
Minor	Windscreen damaged but not adversely affecting driver's view small chip to zone a (3.2 (a) (i))

MOT #10		2018-11-20 13:07
MOT test	number	520740544900
Result		✓ Passed
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effec	ct (5.3.2 (b))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Rear Subframe mounting prescribed area is corroded but not considered exce	essive (5.3.6 (a) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Brake hose has slight corrosion to ferrule both side rear $(1.1.12 (f) (i))$	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Exhaust system corroded	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	



FV58ECW report date: 2024-03-28

MOT #9	2018-11-19 10:28
MOT test number	520813895050
Result	🗙 Failed
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
DANGEROUS Front Exhaust shield missing where fitted as original equipment creating (e))	a risk of fire (6.1.3
Advice Brake hose has slight corrosion to ferrule both side rear (1.1.12 (f) (i))	
Advice Exhaust system corroded	
Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect ((5.3.2 (b))
MAJOR Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt b (5.3.4 (b) (ii))	ooth side front
Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Rear Subframe mounting prescribed area is corroded but not considered exces	sive (5.3.6 (a) (i))





MOT #8		2017-11-03 16:11	
MOT test	number	925301984975	
Result		✓ Passed	
Advice	Brake hose has slight corrosion to ferrules both side rear (3.6.B.4e)		
Advice	Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.	1b)	
Advice	Advice Suspension spring mounting prescribed area is corroded but not considered excessive both side		
rear (2.4.A	A.3)		
Advice	Nearside Rear coil spring corroded (2.4.C.1b)		
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice	Front and middle exhaust sections corroded		
Advice	Front Sub-frame corroded but not seriously weakened (2.4.G.1)		
Advice	Coil spring corroded both side front (2.4.C.1b)		



FV58ECW report date: 2024-03-28

MOT #7 2017-11-03 11	:30
MOT test number 5782068380)98
Result X Fai	led
Fail Exhaust has a major leak of exhaust gases back box (7.1.2)	
Advice Brake hose has slight corrosion to ferrules both side rear (3.6.B.4e)	
Advice Front and middle exhaust sections corroded	
Fail Offside Front Brake pipe excessively corroded (3.6.B.2c)	
Advice Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)	
Advice Suspension spring mounting prescribed area is corroded but not considered excessive both side rear (2.4.A.3)	
Advice Nearside Rear coil spring corroded (2.4.C.1b)	
Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2))
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Front Sub-frame corroded but not seriously weakened (2.4.G.1)	
Advice Coil spring corroded both side front (2.4.C.1b)	

MOT #6	2016-11-14 10:35
MOT test number	604278223996
Result	✓ Passed
Advice Suspension component mounting presinner sills (2.4.A.3)	cribed area is corroded but not considered excessive both
Advice Coil spring corroded both front (2.4.C.	1b)
Advice Nearside Front Suspension arm rubber (2.4.G.2)	bush deteriorated but not resulting in excessive movement
Advice Middle and back exhaust sections corr	oded
Advice Subframe mounting prescribed area is (2.4.A.3)	corroded but not considered excessive both side rear
Advice Nearside Rear coil spring corroded (2.4	4.C.1b)





MOT #5	2015-10-28 00:00
MOT test number	778179922314
Result	✓ Passed
MOT #4	2014-10-27 12:44
MOT test number	985600104319
Result	✓ Passed
Notice Both rear tyres perishing	

MOT #3		2013-10-22 15:06
MOT test	number	135215993213
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	All 4 tyres perishing	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2012-10-25 14:58
MOT test number	825739892229
Result	✓ Passed
MOT #1	2011-11-01 09:43
MOT test number	87858500131/

MOT test number	878585001314
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 7 February 2025
Tax status	Valid until 1 January
Days left	248
MOT expiry date	7 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET O
Category	LAMP
Туре	
Damage 2	VAMPLE
Date	
Category	AMPL
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Ends sizes	





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-11-21
Last registration	2024-01-17
Complete history	See info



Registration #1	2008-11-21	28 mi
Registration #2	2011-11-01	15.423 mi
Registration #3	2012-10-25	19.528 mi
Registration #4	2013-10-22	23.619 mi
Registration #5	2014-10-27	27.104 mi
Registration #6	2015-10-28	30.158 mi
Registration #7	2016-11-14	33.589 mi
Registration #8	2017-11-03	36.754 mi
Registration #9	2017-11-03	36.754 mi
Registration #10	2018-11-19	39.715 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		01.777 mi
Registration #19		11.777 mi
Registration #20		11.117 mi







Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1040 kg
Max. allowed weight	1485 kg
Additional information	
Additional information Fuel tank capacity	45 l
	45 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5